

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Hui Peng

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0386/2023/EQ
4-May-23
CHANG
1 of 1
SLQ 9368 Z
AUDI A4 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REPAIR LHS TAILLAMP PANEL.	\$ 700.00	250.
2	TO RESPRAY LHS TAILLAMP PANEL.	\$ 1,400.00	250.
GRAND TOTAL		\$ 2,100.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling

+ 1 additional day
sls

Car in 25/4/23

mp: 17101

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



A16 - Holman

- 6 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLO 9368 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Distorted</i>	1	\$ 2,763.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 496.00	+
3	REAR BUMPER SECURING STRIP <i>new</i>	1	\$ 264.00	✓
4	REAR BUMPER SPOILER <i>Distorted</i>	1	\$ 292.00	✓
5	REAR BUMPER REFLECTOR - LH <i>new</i>	1	\$ 49.00	✓
6	REAR OUTER TAIL LIGHT - LH <i>new</i>	1	\$ 1,200.00	✓
7	REAR OUTER TAIL LIGHT TRIM - LH <i>new</i>	1	\$ 36.00	+
8	REAR INNER TAIL LIGHT - LH <i>new</i>	1	\$ 1,200.00	✓
9	REAR INNER TAIL LIGHT TRIM - LH <i>new</i>	1	\$ 36.00	+
10	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,197.00	?
11	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 34.00	?
12	REAR BUMPER GUIDE SECTION - LH UPPER	1	\$ 52.00	?
13	REAR BUMPER GUIDE SECTION (LH) RH LOWER	2	\$ 54.00	27. <i>outer missing</i>
14	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	27/50
15	REAR PARKING AID SEAL RING	4	\$ 11.00	✓
16	REAR BUMPER WIRING SET	1	\$ 751.00	?
17	REAR BOOT LID OPENING CONTROL UNIT <i>new</i>	1	\$ 528.00	+
18	REAR TAILGATE OPENING SENSOR LINE <i>new</i>	1	\$ 230.00	+
19	REAR AERIAL KEY ACCESS	1	\$ 123.00	?
20	REAR AERIAL RETAINER - LH	1	\$ 30.00	?
SUB TOTAL SPARE PARTS			\$ 9,889.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.