

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0386/2023/EQ
DATE : 19-Apr-23
WIP : 17101

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/4/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WANG TUI HAI
ADDRESS : BLK 119B CANBERRA CRESCENT
#09-333
SINGAPORE 752119
TELEPHONE : HP +65 91168141
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700014153-05
VEHICLE NO : **SLQ 9368 Z**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 29/6/2017
ENGINE NO : CVN 039005
CHASSIS NO : WAUZZZF42HA165370
MILEAGE : 88,075
DATE IN : 18-Apr-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Apr-23
PLACE OF ACCIDENT : WOODLANDS AVENUE 12 TOWARDS CTE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLO 9368 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	✓
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	?
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	?
5	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE RENEWAL LHS REAR FENDER.	S/N \$	600.00	?
6	TO INSTALL SOLAR FILM FOR ALL AFFECTED GLASSES.	S/N \$	400.00	?
TOTAL LABOUR CHARGES		: \$	4,440.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLO 9368 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	?
8	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD LHS REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,700.00	1000
9	TO RESPRAY REAR BUMPER, REAR LID, LHS REAR FENDER, DRAIN CHANNEL, LHS SILL PANEL, DOOR ENTRANCE, ROOF CHANNEL, REAR END PANELLING AND SPARE WHEEL HOUSING.	\$	6,500.00	1100.
10	TO CARRY OUT JOINT SEALANT AND PRIMER WORK ON REAR END PANELLING AND SPARE WHEEL HOUSING.	S/N \$	780.00	?
11	TO RENEW LHS REAR EXHAUST SILENCER AND CENTER EXHAUST SILENCER. TO ALIGN TO POSITION.	S/N \$	480.00	✓
12	TO RENEW LHS REAR TYRE. TO CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	✓
13	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 20,572.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 9368 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Distorted</i>	1	\$ 2,763.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 496.00	+
3	REAR BUMPER SECURING STRIP <i>new</i>	1	\$ 264.00	✓
4	REAR BUMPER SPOILER <i>Distorted</i>	1	\$ 292.00	✓
5	REAR BUMPER REFLECTOR - LH <i>could</i>	1	\$ 49.00	✓
6	REAR OUTER TAIL LIGHT - LH <i>lit</i>	1	\$ 1,200.00	✓
7	REAR OUTER TAIL LIGHT TRIM - LH <i>new</i>	1	\$ 36.00	+
8	REAR INNER TAIL LIGHT - LH <i>could</i>	1	\$ 1,200.00	✓
9	REAR INNER TAIL LIGHT TRIM - LH <i>new</i>	1	\$ 36.00	+
10	REAR BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 1,197.00	?
11	REAR BUMPER IMPACT BAR GASKET - LH / RH <i>?</i>	2	\$ 34.00	?
12	REAR BUMPER GUIDE SECTION - LH UPPER <i>?</i>	1	\$ 52.00	?
13	REAR BUMPER GUIDE SECTION - LH / RH LOWER <i>?</i>	2	\$ 54.00	?
14	REAR PARKING AID SENSOR - INNER / OUTER <i>outer missing</i>	2	\$ 543.00	27/50
15	REAR PARKING AID SEAL RING <i>new</i>	4	\$ 11.00	✓
16	REAR BUMPER WIRING SET <i>?</i>	1	\$ 751.00	?
17	REAR BOOT LID OPENING CONTROL UNIT <i>new</i>	1	\$ 528.00	x
18	REAR TAILGATE OPENING SENSOR LINE <i>new</i>	1	\$ 230.00	+
19	REAR AERIAL KEY ACCESS <i>?</i>	1	\$ 123.00	?
20	REAR AERIAL RETAINER - LH <i>?</i>	1	\$ 30.00	?
SUB TOTAL SPARE PARTS			\$ 9,889.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 9368 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR TELEPHONE AERIAL ?	1	\$ 197.00	?
22	REAR LID <i>Deleted</i>	1	\$ 3,704.00	✓
23	REAR LID LOCK <i>new</i>	1	\$ 247.00	+
24	REAR LID LOCK COVER CAP <i>new</i>	1	\$ 9.00	+
25	REAR LID ATTACHMENT PARTS <i>new</i>	1	\$ 454.00	+
26	REAR LID FLAP GASKET <i>new</i>	1	\$ 242.00	+
27	PACKING ADHESIVE	1	\$ 22.00	✓
28	AUDI EMBLEM	1	\$ 152.00	✓
29	"A4" INSCRIPTION	1	\$ 110.00	✓
30	"TFSI" INSCRIPTION	1	\$ 110.00	✓
31	REAR SIDE PANEL - LH ?	1	\$ 4,612.00	?
32	REAR WINDOW ?	1	\$ 1,362.00	?
33	REAR QUARTER WINDOW - LH ?	1	\$ 726.00	?
34	WINDOW PRIMER ?	2	\$ 47.00	?
35	REAR WHEEL HOUSING LINER - LH <i>Deleted</i>	1	\$ 281.00	✓
36	REAR CROSS PANEL ?	1	\$ 290.00	?
37	REAR CROSS PANEL REINFORCEMENT ?	1	\$ 565.00	?
38	REAR SILENCER <i>Best</i>	1	\$ 1,619.00	✓
39	REAR SILENCER DUAL CLIP <i>new</i>	1	\$ 61.00	✓
40	EXHAUST SILENCER BRACKET <i>new</i>	1	\$ 48.00	✓
SUB TOTAL SPARE PARTS			\$ 14,858.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 9368 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	REAR CENTRE SILENCER ?	1	\$ 1,445.00	?
42	REAR CENTRE SILENCER DUAL CLIP ?	2	\$ 122.00	?
43	REAR SILENCER HEAT SHIELD - LH ?	1	\$ 179.00	?
44	REAR HEAT SHIELD - CENTER ?	1	\$ 83.00	?
45	ACRYLIC SEALANT ?	S/N	\$ 180.00	?
46	CAVITY WAX ?	S/N	\$ 140.00	?
47	STONE CHIP ?	S/N	\$ 180.00	?
48	METAL FILLER POWDER ?	S/N	\$ 280.00	?
49	1/4 GLASS SEALANT ?	S/N	\$ 100.00	?
50	REAR WINDSCREEN SEALANT ?	S/N	\$ 200.00	?
51	LHS REAR TYRE Not ?	S/N	TBC	✓
52	SUNDRIES ?		\$ 700.00	?
TOTAL SPARE PARTS		:	\$ 28,356.00	
TOTAL LABOUR CHARGES		:	\$ 20,572.00	
GRAND TOTAL		:	\$ 48,928.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lij*
SURVEYED DATE : *20/04/23.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 06 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT