

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2004136068-01	Date of Loss:	19/04/2023
Vehicle Reg. No.:	SJS9919Y	Driveable?	
Driver Age/Info:	25 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHEE YOKE PENG	Contact No:	+6597579618
Driver:	CHIANG ZHEN ANN		

Make/Model:	TOYOTA HARRIER, 2.0 ELEGANCE CVT (A)	Vehicle Reg. Date:	26/01/2017
Vehicle Colour:	WHITE		
Engine No:	3ZRB871559	Chassis No:	ZSU600088015
Odometer:	140102 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	14

Description of Accident/Loss COLLISION - HEAD TO REAR
Present Location: DING AUTO PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	9,388.50
Miscellaneous Items	250.00
Labour	3,360.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	12,998.50
+ GST 8.00% (\$\$)	1,039.88
Nett Amount (\$\$)	14,038.38

This claim is handled by: LYNN YAP WEI LINGenerated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 20 Apr 2023)**Parts:** M1-SUV TOYOTA HARRIER 2.0 ELEGANCE CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Ding Auto Pte Ltd/SJS9919Y/20/04/2023 16:01**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	*315.00 F
2	1		*LOWER GRILLE	0.00	0.00	*145.00 F
3	1		*LOWER LIP	0.00	0.00	*150.00 F
4	1		*FRONT BUMPER RETAINER LHS	0.00	0.00	*55.00 F
5	1		*FRONT BUMPER RETAINER RHS	0.00	0.00	*55.00 F
6	1		*FRONT GRILLE	0.00	0.00	*265.00 F
7	1		*FRONT FENDER LHS	0.00	0.00	*375.00 F
8	1		*FRONT FENDER RHS	0.00	0.00	*375.00 F
9	1		*FRONT FENDER INNERSHIELD COVER LHS	0.00	0.00	*220.00 F
10	1		*FRONT FENDER INNERSHIELD COVER RHS	0.00	0.00	*220.00 F
11	1		*FRONT HEADLAMP LHS	0.00	0.00	*1,180.00 F
12	1		*FRONT HEADLAMP RHS	0.00	0.00	*1,180.00 F
13	1		*HEADLAMP BRACKET LHS	0.00	0.00	*55.00 F
14	1		*HEADLAMP BRACKET RHS	0.00	0.00	*55.00 F
15	1		*FOG LAMP ASSY LHS	0.00	0.00	*135.00 F
16	1		*FOG LAMP ASSY RHS	0.00	0.00	*135.00 F
17	1		*FOG LAMP GARNISH LHS	0.00	0.00	*80.00 F
18	1		*FOG LAMP GARNISH RHS	0.00	0.00	*80.00 F
19	1		*BONNET	0.00	0.00	*560.00 F
20	1		*BONNET HINGE LHS	0.00	0.00	*38.00 F
21	1		*BONNET HINGE RHS	0.00	0.00	*38.00 F
22	1		*BONNET ABSORBER	0.00	0.00	*150.00 F
23	1		*BONNET WEATHER STRIP	0.00	0.00	*48.00 F
24	1		*BONNET LOCK	0.00	0.00	*95.00 F
25	1		*RADIATOR TOP GARNISH	0.00	0.00	*195.00 F
26	1		*FRONT REINFORCEMENT	0.00	0.00	*180.00 F
27	1		*FRONT SUPPORT PANEL	0.00	0.00	*400.00 F
28	1		*RADIATOR	0.00	0.00	*625.00 F
29	1		*CONDENSER	0.00	0.00	*625.00 F
30	1		*TOWING CAP LHS	0.00	0.00	*18.00 F
31	1		*TOWING CAP RHS	0.00	0.00	*18.00 F
32	1		*FRONT BUMPER LOWER COVER	0.00	0.00	*110.00 F
33	1		*FRONT BRACE PANEL	0.00	0.00	*120.00 F
34	1		*HIGH HORN	0.00	0.00	*65.00 F
35	1		*LOW HORN	0.00	0.00	*65.00 F
36	1		*FRONT REINFORCEMENT CENTRE SPONGE	0.00	0.00	*80.00 F
37	1		*FRONT REINFORCEMENT SIDE SPONGE	0.00	0.00	*30.00 F

F=Franchise part.

Sub Total (\$\$) **8,535.00**
+ Margin on L,N Items 10.00% (\$\$) **853.50**

Ding Auto Pte Ltd/SJS9919Y/20/04/2023 16:01. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						9,388.50

Ding Auto Pte Ltd/SJS9919Y/20/04/2023 16:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER, FRONT INNERSHIELD LHS, FRONT INNERSHIELD RHS & BONNET CLIPS	200.00
2	1	FRONT CARPLATE WITH FRAME	50.00
Sub Total (S\$)			250.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REPAIR, PANEL BEAT & STRAIGHTEN - ACCIDENT AREAS	New	1,600.00
2	SPRAY PAINT - FRONT BUMPER, FRONT FENDER LHS, FRONT FENDER RHS, FRONT BONNET	New	1,200.00
3	ALIGN HEADLAMP & TEST WIRING	New	120.00
4	REMOVE & INSTALL - CONDENSER & RADIATOR	New	200.00
5	REMOVE & REFIT - BONNET COMPONENTS	New	120.00
6	REFILL AIRCON GAS & COOLANT	New	120.00
Gross Labour Cost (S\$)			3,360.00

Ding Auto Pte Ltd/SJS9919Y/20/04/2023 16:01. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >