



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2303407

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 30/05/2023
Reference CS3/III23004129/Wqy3m4
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. FBT 1157X
Insured Veh. SLN 5915L
Claim No. MFL2023D0004214
Policy No. D23MFL0002582
Accident Date 17/04/2023
Inspection Date 21/04/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 21.04.2023 02.30pm	
- Dismantle Inspection 04.05.2023 03.51pm	
- After Repair Inspection 08.05.2023 06.33pm	
Merimen Fee	11.00
Subtotal	131.00
GST (8%)	10.48
Grand Total	141.48

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML