

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 65713
Date Estimated : 19/04/2023
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lee Kuew Lih Mrs Kuew Lih Schnepf-Pesch
106 Duchess Avenue
#01-09

Singapore 266311

- ACCOUNT -

137

Allianz Global Corporate & Specialty SE
Singapore Branch
12 Marina View
Singapore 018961
#14-01 Asia Square Tower 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDB7997U	WBATS720109B89668	28/08/2020	X3 sDrive20i	15022

DESCRIPTION

VALUE

Replace front bonnet, right front side fender, front bumper include remove
ayyachm, ent etc and carryout necessary repair on the accident damage area

2550 3,400.00

Painting front bumper, bonnet and right front side fender

3340 3,516.00

To check electrical wiring system at the front section for proper function including adjustment of headlights.

168 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 177.00

To carry out body cavity preservation.
(2 panel).

112 224 236.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).

m X 531.00

To replace tyre and wheel rim including balancing. (1x).
right front

m X 94.00

To replace right headlight.

457 456 481.00

Sundries.

150.00

Total Labour 1: 8,762.00

DESCRIPTION

QTY

PRIC

VALUE

ALLOY RIM right front	1	1,226.50	1,226.50
FRT RH SIDE PANEL	1	980.60	980.60
BONNET repair	1	1,987.85	1,987.85
FRT RH 1 SIDE PANEL BRACKET	1	43.70	43.70
RH BOTTOM SIDE PANEL BRACKET	1	43.70	43.70
FRT RH 2 SIDE PANEL BRACKET	1	43.70	43.70

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159941
Fax. 64747770



GST REG. NO : M2 - 0020081

ESTIMATE

**Insurance Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate No. : b1 65713
Date Estimated : 19/04/2023
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDB7997U	WBATS720109B89668	28/08/2020	X3 sDrive20i	15022

DESCRIPTION	QTY	PRIC	VALUE
EXPANDING RIVET <i>ne</i>	10	0.50	5.00
FRT BUMPER FLAP TOWING EYE <i>3x11</i>	1	44.00	44.00
FRT SHOCK ABSORBER <i>? can</i>	1	78.60	78.60
FRT BUMPER TOP CARRIER <i>? fan</i>	1	886.25	886.25
FRT BUMPER BOTTOM CARRIER <i>? fan</i>	1	487.45	487.45
RH FOG LAMP SUPPORT <i>? fan</i>	1	57.65	57.65
LH GUIDE BUMPER <i>fan</i>	1	54.55	54.55
RH GUIDE BUMPER <i>? can</i>	1	54.55	54.55
FRT BUMPER LH INSERT <i>? fan</i>	1	54.55	54.55
FRT BUMPER RH INSERT <i>? can</i>	1	54.55	54.55
RH AIR CURTAIN <i>? fan</i>	1	51.05	51.05
RH SIDE GRILLE OPEN WITH PDC (NEBEL) <i>? can</i>	1	97.00	97.00
RH SIDE PROTECTIVE STRIP <i>? can</i>	1	49.45	49.45
RH SIDE PROTECTIVE STRIP <i>? fan</i>	1	49.45	49.45
RH COVER FOR AIR INLET <i>? fan</i>	1	83.10	83.10
RH COVER FOR AIR INLET <i>? fan</i>	1	83.10	83.10
FRT BUMPER PANEL PRIMED (PMA) <i>de</i>	1	1,454.15	1,454.15
FRT BUMPER COVER (PDC) <i>fan</i>	1	746.35	746.35
SET MOUNTING PDC/PMA SENSOR FRT <i>? fan</i>	1	71.50	71.50
EMBLEM GROMMET <i>ne</i>	1	0.95	0.95
PLAQUE 82MM <i>ne</i>	1	72.85	72.85
RH LOCK <i>? fan</i>	1	128.40	128.40
LOCK TOP PART <i>? fan</i>	2	77.05	154.10
GAS FILLED STRUT ENGINE COMPARTMENT <i>3x11</i>	2	130.65	261.30
RH HEADLIGHT MOUNTING <i>? fan</i>	1	240.20	240.20
FRT RH WHEEL ARCH COVER RR SECTION <i>3x11</i>	1	151.20	151.20
RH BOTTOM COVER <i>3x11</i>	1	75.00	75.00
FRT RH WHEEL ARCH COVER FRT SECTION <i>3x11</i>	1	145.70	145.70
EXPANDING RIVET BLACK <i>ne</i>	13	1.40	18.20
FRT RH WHEEL ARCH TRIM <i>de</i>	1	213.05	213.05
RH HEADLIGHT LED AHL HIGH (ICON LIG) <i>bo</i>	1	4,475.70	4,475.70
RH FOG LIGHT LED <i>? fan</i>	1	505.65	505.65
ULTRASONIC SENSOR BLACK <i>? fan</i>	2	254.05	508.10
DECOUPING RING PDC TORQUE CONVERTER <i>? fan</i>	6	5.30	31.80

Total Parts : 15,770.55

Claims OD 3rd Party / Uninsured losses / Direct Settlement

Regn No. 02/05/23 01440 Claim No. 600
Date & Time 02/05/23 01440 Excess S\$ 600
Surveyor's Name Ravear Sign Ph
Surveyor's Tel 9606068 Authorised Yes/No Yes
Authorised Date 02/05/23 Time 14:00
RESURVEY PARTS PHOTO BY SURVEYOR Yes/No Yes PML Yes/No No
Surveyor's E-mail Ravear

Labour 1	:	8,762.00
Parts	:	15,770.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	1,962.60
Grand Total	:	26,495.15



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **