



**Section A - Accident Details**

Registration Number	SHB5126H
Case Reference Number	TAX/04/23/2042
Registration Date	30/Nov/2020
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	MOHAMMED DELWAR HOSSAIN
Type of Accident	Side Swipe
Accident Date and Time	20/Apr/2023 11:08 AM
Accident Reported Date and Time	20/Apr/2023 2:27 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118225
Special Instruction to ARC, if any	DAMAGE TO THE FRONT LHS TO THE REAR
Prepared Date and Time	20/Apr/2023 4:37 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$400.00
Total Spray Cost	\$4,304.00	\$920.00
Total Spare Part Cost	\$14,924.69	\$2,390.86
Total Other Cost	\$1,040.00	\$45.00
<b>TOTAL COST</b>	<b>\$21,620.69</b>	<b>\$3,755.86 (P/P)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	8.0	3.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>Kenneth Kong (LKK) / INCOME</b>
ARC / Surveyor Sign Off Date	<b>21/04/2023 5:26 PM</b>	<b>21/04/2023 4:27 PM</b>
Signature		
Remarks	PART BY PART REPAIR / BEFORE PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) / HP : 9691 0663 / Email : kennethkong@lkkauto.com	

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2305-0341	<b>Invoice Number</b>	
<b>Quotation Date</b>	30.05.2023	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

<b>Part 1 - Labour Works</b>		
<b>Job Scope</b>	<b>Quotation from AR</b>	<b>Adjusted by Surveyor, if applicable</b>
TO REPAIR REAR PORTION LH	\$338.00	\$0.00
TO REPAIR LH PORTION	\$1,014.00	\$400.00
<b>Total Labour</b>	<b>\$1,352.00</b>	<b>\$400.00</b>

<b>Part 2 - Spray Painting &amp; Panel Beating Related Works</b>		
<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO RESPRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING LH	\$220.00	\$0.00
To respray mirror cover LH	\$180.00	\$60.00
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$0.00
TO RESPRAY VIEW MIRROR	\$220.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	\$0.00
TO RESRAY REAR DOOR LH	\$378.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY RIM	\$378.00	\$60.00
TO RESPRAY DOOR HANDLE	\$220.00	\$0.00
TO RESPRAY FUEL LID COVER	\$220.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$4,304.00</b>	<b>\$920.00</b>

<b>Part 3 - Other Costs - Accident and Accident Repair Related Expense</b>		
<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$15.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$300.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
<b>Total Other Costs</b>	<b>\$1,040.00</b>	<b>\$45.00</b>

