

ASS. REC. BY:

REF:

INC / 23004131 / Kg43

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

PMRT

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

1. B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 512614

Yr Regn:

11, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

N. Brown

AC:

Insured / Std / NI / NA

Sp. Reading

202427

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU303091879

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

9

mm

R/Bal.

7

mm

L/Bal.

9

mm

L/Bal.

7

mm

D.O.A.

20/4/23

D.O.I.

21/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Frt &amp; N/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2016 @ 2205-05 3295.86 Cash Paid \$ 18963.12, 85%

26/06/23 Re-finalised with Poh Suan final fig \$3755.86, 3 days. (Red \$18503.12, 83%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

TP

Lump Sum / I.B.I: (\$

3755.86

## SMRT Accident Vehicle Repair Estimates

|                                                   |
|---------------------------------------------------|
| SMK Automotive Services Pte Ltd                   |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 21/04/2023

User ID : munsan

### Section A - Accident Details

|                                    |                                     |
|------------------------------------|-------------------------------------|
| Registration Number                | SHB5126H                            |
| Case Reference Number              | TAX/04/23/2042                      |
| Registration Date                  | 30/11/20                            |
| Company Type                       | Strides Taxi Pte Ltd                |
| Make                               | TOYOTA                              |
| Model                              | PRIUS4FL                            |
| Name of Driver                     | MOHAMMED DELWAR HOSSAIN             |
| Type of Accident                   | Side Swipe                          |
| Accident Date and Time             | 20/4/23 11:08 AM                    |
| Accident Reported Date and Time    | 20/4/23 2:27 PM                     |
| Surveyor Required?                 | No                                  |
| Surveyed by                        |                                     |
| Vehicle is Towed Back?             | No                                  |
| Towed Back Date and Time           |                                     |
| Replacement Vehicle issued?        | No                                  |
| Job Card Number                    | 24116225                            |
| Special Instruction to ARC, if any | DAMAGE TO THE FRONT LHS TO THE REAR |
| Prepared Date and Time             | 20/4/23 4:37 PM                     |
| Chassis Number                     |                                     |
| Allegae                            |                                     |
| Work Shop                          |                                     |
| Repair Completion Date and Time    |                                     |

### Section B - Summary of Repair Estimates

| Summary of Repair Estimates  |                                                                                     |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                 |
| Total Labour Cost            | \$1,014.00                                                                          | \$0.00                                                                              |
| Total Spray Cost             | \$3,148.00                                                                          | \$0.00                                                                              |
| Total Spare Part Cost        | \$13,615.73                                                                         | \$0.00                                                                              |
| Total Other Cost             | \$1,040.00                                                                          | \$0.00                                                                              |
| <b>TOTAL COST</b>            | <b>\$18,817.73</b>                                                                  | <b>\$0.00</b>                                                                       |
| ump Sum Total                | \$0.00                                                                              | \$0.00                                                                              |
| Number of Repair Days        | 8.0                                                                                 | 03days                                                                              |
| Prepared / Adjusted By       | Boon Chew Tay                                                                       |                                                                                     |
| ARC / Surveyor Sign Off Date | 20/04/2023 4:50 PM                                                                  |                                                                                     |
| Signature                    |  |  |
| Remarks                      |                                                                                     |                                                                                     |

### Section C - Quotation and Accident Invoice Details

|                  |  |                |  |
|------------------|--|----------------|--|
| Quotation Number |  | Invoice Number |  |
| Quotation Date   |  | Invoice Date   |  |
| Invoice Amount   |  | Prepared Date  |  |



**SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 21/04/2023

User ID : munsan

**Section D - Details of Repair Estimates**
**Part 1 - Labour Works**

| Job Scope           | Quotation from AR     | Adjusted by Surveyor, if applicable |
|---------------------|-----------------------|-------------------------------------|
| O REPAIR LH PORTION | \$1,014.00 <i>400</i> |                                     |
| <b>total Labour</b> | <b>\$1,014.00</b>     |                                     |

**Part 2 - Spray Painting & Panel Beating Related Works**

| Job Scope                                       | Quotation from ARC  | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|---------------------|-------------------------------------|
| O RESPRAY FRONT BUMPER                          | \$378.00 <i>200</i> |                                     |
| O RESPRAY FRONT FENDER LH                       | \$378.00 <i>200</i> |                                     |
| O RESPRAY FRONT DOOR LH                         | \$378.00 <i>200</i> |                                     |
| O RESPRAY VIEW MIRROR                           | \$220.00 <i>200</i> |                                     |
| O RESPRAY ROCKER PANEL MOULDING                 | \$220.00 <i>200</i> |                                     |
| O RESPRAY REAR DOOR LH                          | \$378.00 <i>200</i> |                                     |
| O RESPRAY REAR FENDER LH                        | \$378.00 <i>200</i> |                                     |
| O RESPRAY RIM                                   | \$378.00 <i>200</i> |                                     |
| O RESPRAY DOOR HANDLE                           | \$220.00 <i>200</i> |                                     |
| O RESPRAY FUEL LID COVER                        | \$220.00 <i>200</i> |                                     |
| <b>total Spray Painting &amp; Panel Beating</b> | <b>\$3,148.00</b>   |                                     |

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

| Job Scope                              | Quotation from ARC  | Adjusted by Surveyor, if applicable |
|----------------------------------------|---------------------|-------------------------------------|
| O WASH AND VACUUM                      | \$60.00 <i>200</i>  |                                     |
| O CHECK WIRING AND SYSTEM FUNCTION     | \$120.00 <i>150</i> |                                     |
| O APPLY RUST-PROOFING ON AFFECTED AREA | \$100.00 <i>300</i> |                                     |
| O DO WHEEL ALIGNMENT / TYRE BALANCING  | \$120.00 <i>200</i> |                                     |
| O REMOVE AND REFIT TYRE                | \$120.00 <i>200</i> |                                     |
| O TRANSFER DOOR MECHANISM              | \$120.00 <i>200</i> |                                     |
| O REMOVE AND REFIX UNDERCARRIAGE       | \$300.00 <i>200</i> |                                     |
| O REPLACE SUNDRY PARTS                 | \$100.00 <i>200</i> |                                     |
| <b>total Other Costs</b>               | <b>\$1,040.00</b>   |                                     |

**Part 4 - Spare Parts / Material Usage**

| Part Number | Portion | Stock Number   | Part Name                            | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|----------------|--------------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
|             |         | 52119-47980    | COVER, FR BUMPER                     | 1.00     | \$565.60        | 25.00        | \$424.20         | Replace            | <i>bu</i>         |
|             |         | 52116-47050    | SUPPORT, FR BUMPER LH                | 1.00     | \$86.20         | 25.00        | \$64.65          | Replace            | <i>SVC</i>        |
|             |         | 52161-16010    | CLIPS PIECE, FRT & RR BUMPER         | 10.00    | \$4.80          | 25.00        | \$36.00          | Replace            | <i>bu</i>         |
|             |         | 81185-47890    | UNIT, HEADLAMP, LH                   | 1.00     | \$2,852.40      | 10.00        | \$2,567.16       | Replace            | <i>SVC</i>        |
|             |         | 53802-47100    | FENDER SUB-ASSY, FR LH               | 1.00     | \$1,060.70      | 25.00        | \$795.53         | Replace            | <i>bu</i>         |
|             |         | 75374-47140    | EMBLEM, SIDE PANEL (HYBRID)          | 1.00     | \$59.10         | 25.00        | \$44.33          | Replace            | <i>bu</i>         |
|             |         | 53876-47060    | LINER, FR FENDER, LH                 | 1.00     | \$227.80        | 25.00        | \$170.85         | Replace            | <i>bu</i>         |
|             |         | 42611-47450    | WHEEL, DISC FRONT                    | 1.00     | \$2,036.30      | 25.00        | \$1,527.23       | Replace            | <i>bu</i>         |
|             |         |                | TYRE                                 | 1.00     | \$126.74        | 0.00         | \$126.74         | Replace            | <i>bu</i>         |
|             |         | 43550-47020    | HUB & BEARING ASSY, RH & LH          | 1.00     | \$722.10        | 25.00        | \$541.58         | Replace            | <i>bu</i>         |
|             |         | 87945-47060-A1 | COVER, OUTER MIRROR, LH              | 1.00     | \$117.80        | 25.00        | \$88.35          | Replace            | <i>bu</i>         |
|             |         | 87940-47440    | MIRROR ASSY, OUTER REAR VIEW, LH     | 1.00     | \$1,454.40      | 10.00        | \$1,308.96       | Replace            | <i>bu</i>         |
|             |         | 75860-47900    | MOULDING ASSY, BODY ROCKER PANEL, LH | 1.00     | \$649.10        | 25.00        | \$486.83         | Replace            | <i>bu</i>         |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705  
FAX Number : 63685592  
Estimator Telephone Number : 68662623  
Accident Reporting Number : 68662672

Date Generated : 21/04/2023

User ID : munsan

**Part 4 - Spare Parts / Material Usage**

| Part Number | Portion | Stock Number   | Part Name                                                | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|----------------|----------------------------------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
|             |         | 67002-47163    | PANEL SUB-ASSY, FRONT DOOR LH                            | 1.00     | \$1,407.80      | 25.00        | \$1,055.85       | Replace            | <i>R</i> X        |
|             |         |                | STICKER STRIDES TAXI ( DOOR )                            | 1.00     | \$60.00         | 0.00         | \$60.00          | Replace            | <i>nn</i> X       |
|             |         | 67004-47211    | PANEL SUB-ASSY, REAR DOOR, LH                            | 1.00     | \$1,401.70      | 25.00        | \$1,051.28       | Replace            | <i>R</i> X        |
|             |         | 61602-47180    | PANEL SUB-ASSY, FENDER REAR LH                           | 1.00     | \$943.10        | 25.00        | \$707.33         | Replace            | <i>R</i> X        |
|             |         | 4261147450     | WHEEL, DISC                                              | 1.00     | \$2,036.30      | 25.00        | \$1,527.23       | Replace            | <i>Rn</i> X       |
|             |         |                | TYRE                                                     | 1.00     | \$126.74        | 0.00         | \$126.74         | Replace            | <i>Rn</i> X       |
|             |         | 42450-76020    | HUB & BEARING ASSY WITH SPEED SENSOR, REAR AXLE, RH & LH | 1.00     | \$644.10        | 10.00        | \$579.69         | Replace            | <i>nn</i> X       |
|             |         | 69210-47051-A1 | DOOR OUTER HANDLE FRONT, LH                              | 1.00     | \$423.20        | 25.00        | \$317.40         | Replace            | <i>Rn</i> X       |
|             |         |                | STICKER PETROL ONLY                                      | 1.00     | \$7.80          | 0.00         | \$7.80           | Replace            | <i>Rn</i> X       |
| total       |         |                |                                                          |          | \$17,013.78     |              | \$13,615.73      |                    |                   |

**Added Spare Parts / Material Usage After Surveyor Signed off**

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| total       |         |              |           |          |               |              |                  |           |                |