

ASS. REC. BY:

REF:

INC / 23004131 / Kgy3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

PMRT

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

1. B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 512614

Yr Regn:

11, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

N. Brown

AC:

Insured / Std / NI / NA

Sp. Reading

202427

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU303091879

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

9

mm

R/Bal.

7

mm

L/Bal.

9

mm

L/Bal.

7

mm

D.O.A.

20/4/23

D.O.I.

21/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Frt & N/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/6/23 @ 2205-05 3295.86 Car had been & 18963.12, 85%

26/06/23 Re-finalised with Poh Suan final fig \$3755.86, 3 days. (Red \$18503.12, 83%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

3755.86

SMRT Accident Vehicle Repair Estimates

SMK Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 21/04/2023

User ID : munsan

Section A - Accident Details

Registration Number	SHB5126H
Case Reference Number	TAX/04/23/2042
Registration Date	30/11/20
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	MOHAMMED DELWAR HOSSAIN
Type of Accident	Side Swipe
Accident Date and Time	20/4/23 11:08 AM
Accident Reported Date and Time	20/4/23 2:27 PM
Surveyor Required?	No
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116225
Special Instruction to ARC, if any	DAMAGE TO THE FRONT LHS TO THE REAR
Prepared Date and Time	20/4/23 4:37 PM
Chassis Number	
Allegae	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$0.00
Total Spray Cost	\$3,148.00	\$0.00
Total Spare Part Cost	\$13,615.73	\$0.00
Total Other Cost	\$1,040.00	\$0.00
TOTAL COST	\$18,817.73	\$0.00
ump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	03 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	20/04/2023 4:50 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 21/04/2023

User ID : munsan

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR LH PORTION	\$1,014.00 <i>400</i>	
total Labour	\$1,014.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY FRONT BUMPER	\$378.00 <i>200</i>	
O RESPRAY FRONT FENDER LH	\$378.00 <i>200</i>	
O RESPRAY FRONT DOOR LH	\$378.00 <i>200</i>	
O RESPRAY VIEW MIRROR	\$220.00 <i>200</i>	
O RESPRAY ROCKER PANEL MOULDING	\$220.00 <i>200</i>	
O RESPRAY REAR DOOR LH	\$378.00 <i>200</i>	
O RESPRAY REAR FENDER LH	\$378.00 <i>200</i>	
O RESPRAY RIM	\$378.00 <i>200</i>	
O RESPRAY DOOR HANDLE	\$220.00 <i>200</i>	
O RESPRAY FUEL LID COVER	\$220.00 <i>200</i>	
total Spray Painting & Panel Beating	\$3,148.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00 <i>200</i>	
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00 <i>150</i>	
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00 <i>300</i>	
O DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00 <i>200</i>	
O REMOVE AND REFIT TYRE	\$120.00 <i>200</i>	
O TRANSFER DOOR MECHANISM	\$120.00 <i>200</i>	
O REMOVE AND REFIX UNDERCARRIAGE	\$300.00 <i>200</i>	
O REPLACE SUNDRY PARTS	\$100.00 <i>200</i>	
total Other Costs	\$1,040.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	25.00	\$424.20	Replace	<i>bu</i>
		52116-47050	SUPPORT, FR BUMPER LH	1.00	\$86.20	25.00	\$64.65	Replace	<i>X</i>
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	<i>bu</i>
		81185-47890	UNIT, HEADLAMP, LH	1.00	\$2,852.40	10.00	\$2,567.16	Replace	<i>X</i>
		53802-47100	FENDER SUB-ASSY, FR, LH	1.00	\$1,060.70	25.00	\$795.53	Replace	<i>bu</i>
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	<i>bu</i>
		53876-47060	LINER, FR FENDER, LH	1.00	\$227.80	25.00	\$170.85	Replace	<i>bu</i>
		42611-47450	WHEEL, DISC FRONT	1.00	\$2,036.30	25.00	\$1,527.23	Replace	<i>bu</i>
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	<i>bu</i>
		43550-47020	HUB & BEARING ASSY, RH & LH	1.00	\$722.10	25.00	\$541.58	Replace	<i>bu</i>
		87945-47060-A1	COVER, OUTER MIRROR, LH	1.00	\$117.80	25.00	\$88.35	Replace	<i>bu</i>
		87940-47440	MIRROR ASSY, OUTER REAR VIEW, LH	1.00	\$1,454.40	10.00	\$1,308.96	Replace	<i>bu</i>
		75860-47900	MOULDING ASSY, BODY ROCKER PANEL, LH	1.00	\$649.10	25.00	\$486.83	Replace	<i>bu</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/04/2023

User ID : munsan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67002-47163	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	25.00	\$1,055.85	Replace	<i>R</i> X
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	<i>nn</i> X
		67004-47211	PANEL SUB-ASSY, REAR DOOR, LH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	<i>R</i> X
		61602-47180	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$943.10	25.00	\$707.33	Replace	<i>R</i> X
		4261147450	WHEEL, DISC	1.00	\$2,036.30	25.00	\$1,527.23	Replace	<i>Rn</i> X
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	<i>Rn</i> X
		42450-76020	HUB & BEARING ASSY WITH SPEED SENSOR, REAR AXLE, RH & LH	1.00	\$644.10	10.00	\$579.69	Replace	<i>nn</i> X
		69210-47051-A1	DOOR OUTER HANDLE FRONT, LH	1.00	\$423.20	25.00	\$317.40	Replace	<i>Rn</i> X
			STICKER PETROL ONLY	1.00	\$7.80	0.00	\$7.80	Replace	<i>Rn</i> X
total					\$17,013.78		\$13,615.73		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									