

ASS. REC. BY:

REF:

072 / 23004135 / 1/19

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

0.5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

05/23

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

1

Est not ready

29/5

L1 Rm 826501 Cash (red, \$1106, 29%)

Veh No:

PA 7426P

Yr Regn: 05, 08

Type: M.Car / M.Cycle (Bus) / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Hiace

c.c 2982

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

314134

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KOH 201 - 0017882

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: N/A / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15 X P

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

19/4/23

D.O.I.

24/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - St

Photos

Others

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump-Sum / I.B.I. (\$

TOTAL

-> Back to OneMotoring

PA 7426P
7P/CHINA

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 810B

Vehicle Details

Vehicle No.: PA7426P
Vehicle to be Exported: No
Intended Deregistration Date: 20 Apr 2023
Vehicle Make: TOYOTA
Vehicle Model: HIACE 3.0DX M
Primary Colour: White
Manufacturing Year: 2008
Engine No.: 1KD1783913
Chassis No.: KDH2010017882
Maximum Power Output: -
Open Market Value: \$30,536.00
Original Registration Date: 08 May 2008
First Registration Date: 08 May 2008
Transfer Count: 3
Actual ARF Paid: \$1,527.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 07 May 2023
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$17,865.00
COE Rebate Amount: \$166.00
Total Rebate Amount: \$166.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 20 Apr 2023

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
PA7426P

Make / Model
TOYOTA / HIACE 3.0DX M

Vehicle Type :
Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus

Vehicle Scheme :
Public Service Vehicle (Others)

Propellant :
Diesel

Motor No. :
-

Power Rating :
-

Maximum Laden Weight :
3195 kg

Year Of Manufacture :
2008

Lifespan Expiry Date :
07 May 2028

PQP Paid :
\$17,865.00

Road Tax Expiry Date :
07 May 2023

Inspection Due Date :
07 May 2023

CO2 Emission :
-

CO Emission :
-

NOx Emission :
-

Vehicle Attachment 1 :
No Attachment

Chassis No. :
KDH2010017882

Engine No. :
1KD1783913

Engine Capacity :
2982 cc

Maximum Power Output :
-

Unladen Weight :
1800 kg

Original Registration Date :
08 May 2008

COE Category :
C - Goods Vehicle & Bus

COE Expiry Date :
07 May 2023

PARF Eligibility Expiry Date :
-

Intended Transfer Date :
21 Apr 2023

CEV/VES Rebate Utilised Amount :
-

HC Emission :
-

PM Emission :
-

Fees To Be Paid For Transfer

Enquire PQP Payable for Category C Early Turnover Scheme

Vehicle Details

The discounted Prevailing Quota Premium (PQP) paid for the replacement vehicle's COE depends on:

- The period of unused COE of the existing vehicle
- The remaining 20-year lifespan of the existing vehicle when it is deregistered

Vehicle No.
PA7426P

Intended Registration Date
02 May 2023

Vehicle Type:

Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus

Propellant:

Diesel

Emission Standard Code:

Euro IV

Original Registration Date:

08 May 2008

First Registration Date:

08 May 2008

Turnover Eligibility Expiry Date:

20 May 2023

Intended Deregistration Date:

21 Apr 2023

Existing Vehicle's COE and Lifespan Details

Last COE Renewal Date:

20 Apr 2018

Remaining Unused COE Period:

22 Apr 2023 - 07 May 2023

COE Rebate:

\$156.00

Remaining 20-year Lifespan:

22 Apr 2023 - 07 May 2028

PQP/COE Details for Replacement Vehicle

New COE Period:

02 May 2023 - 01 May 2033

Current Month PQP Rate:

\$83,589.00

If the replacement vehicle is a Light Goods Vehicle that is Euro VI-compliant (or equivalent) and Band A under CVES:

Estimated discounted PQP to be paid for COE*:

\$74,791.00 or \$8,359.00 (i.e. 10% of PQP); whichever is higher.

Estimated 10-year COE value**:

\$74,947.00

If the replacement vehicle is a Light Goods Vehicle that is Euro VI-compliant (or equivalent) and Band B under CVES:

Estimated discounted PQP to be paid for COE*:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 May 2023)
 Parts: 213 TOYOTA HIACE 3.0 D DX (M) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for PA7426P)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc tailgate	0.00	0.00	*780.00 F
2	1		*1 pc tailgate logo	0.00	0.00	*35.00 F
3	1		*1 pc tailgate inner lock	0.00	0.00	*105.00 F
4	1		*1 pc tailgate inner rubber	0.00	0.00	*120.00 F
5	1		*1 pc rear bumper	0.00	0.00	*155.00 F
6	1		*1 pc rear bumper centre step panel	0.00	0.00	*150.00 F
7	1		*1 pc rear bumper clips @ \$2/pc	0.00	0.00	*12.00 F
8	1		*1 pc rear end panel outer	0.00	0.00	*160.00 F
9	1		*1 pc rear end panel inner top garnish	0.00	0.00	*78.00 F
10	1		*1 pc RH taillamp	0.00	0.00	*115.00 F
Sub Total (\$\$)						1,710.00
+ Margin on L,N Items 10.00% (\$\$)						171.00
Total Parts (\$\$)						1,881.00

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 pc 70km/hr sticker	10.00
2	1	1 pc emergency sticker	25.00
3	1	1 pc rear windscreen glass sealant	40.00
Sub Total (\$\$)			75.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	Remove & refix rear windscreen glass	New	100.00
2	Remove & refix rear bumper assy,taillamps,tailgate & attachment,lock assy; to welding,renew rear end panel outer;knocking & repair rear floorboard panel & realign the same	New	1,000.00
3	Putty & respray on rear floorboard panel,rear end panel,tailgate	New	700.00
Gross Labour Cost (\$\$)			1,800.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Notified
 L/R @ 2650
 Resurvey After Pain
 4 days

Y. P. WANG