7/7/23, 2:08 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIS23004140/RPA3Q2

07/07/2023 Date:

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle

GBJ1201D

Insured Vehicle No: PC3151Y

No:

Date of Loss: 09/04/2023 Nature of Claim: TP Claim No: 2023 32007135FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ1201D**

ISUZU NHR87AUE4AA, 1.9 D (M) RZ4E10G243 Make & Model: Engine No:

Reg. Date: 03/01/2019 (Man. Year: 2018) Chassis No: JAANHR87EJ7100256

Colour: Odometer: Red 151627 km

Engine Capacity: 1898 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R13C (D) Maxmiler 5/5 mm Front Left Side: Maxmiler 7 mm Rear Left Side: Front Right Side: Maxmiler 7 mm Rear Right Side: Maxmiler 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,050.00	1,830.00	1,220.00	40.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,230.00	1,000.00	230.00	18.70
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,280.00	2,830.00	1,450.00	33.88
	Approved Total (Overridden) (S\$)		2,250.00		
	Nett Amount (S\$)	4,280.00	2,250.00	2,030.00	47.43
	Global Sum	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 20/04/2023

ETHOZ Protect Pte Ltd (Bukit Batok) Inspected At: Date Inspected: 20/04/2023

30 Bukit Batok Crescent

Singapore 658075

Estimated Period of Repair: 6.0 days

CHEW HSIAO TONG Adjuster: MOHD RASUL Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/7/23, 2:08 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Jul 2023)

Parts: N/A ISUZU NHR87AUE4AA 1.9 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBJ1201D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR ALUMINIUM CABIN BOX DOOR RH	Bent	500.00 FS	*350.00 FS
2	2		*REAR ALUMINIUM CABIN DOOR HINGES RH	Bent	220.00 FS	*150.00 FS
3	1		*REAR ALUMINIUM CABIN BOX DOOR LH	Bent	500.00 FS	*350.00 FS
4	1		*REAR CABIN BOX SIDE PILLAR RH	Bent	400.00 FS	*200.00 FS
5	1		*REAR CABIN BOX LOCK ARM LEVER	Repair	280.00 FS	*- FS
6	1		*REAR CABIN BOX LOCK LEVER HOLDER RH	Missing	80.00 FS	*40.00 FS
7	2		*REAR END PANEL RUBBER DAMPER LH/RH	Broken	200.00 FS	*120.00 FS
8	1		*REAR END PANEL	Bent	500.00 FS	*300.00 FS
9	1		*REAR ADVERTISEMENT PANEL	Necessary	350.00 FS	*300.00 FS
10	1		*70KM/HR	Necessary	10.00 FS	*10.00 FS
11	1		*13 PAX STICKER	Necessary	10.00 FS	*10.00 FS
F=Fra	anchise	part. S=SpcN	ett.	-		
				Total Parts (S\$)	3,050.00	1,830.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
<u>Lab</u>	our Items					
1	LABOUR TO FACILITATE REPAIR	New	600.00	500.00		
2	TO RESPRAY AFFECTED AREAS	New	600.00	500.00		
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	0.00		
	Gross Labour Cost (S\$)		1,230.00	1,000.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >