

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986 Fax: 6744 4165

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT	<i>7P Budget Direct Xin Yu.</i>
DATE:		
CLAIM TYPE:	T/P CLAIM	
TO:		
VEHICLE DETAILS		
VEHICLE NO:	SMM5934A	
MAKE & MODEL:	MITSUBISHI ATTRAGE 1.2 CVT	
CHASSIS NO:	MMBSTA13AK002203	
ACCIDENT DETAILS		
DATE:	20 April, 2023	
TIME:	09:00HRS	
THIRD PARTY REQUESTOR:	JACK LI	

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Deled</i>	1	\$ 1,080.50	\$ 1,080.50
2	BOOTLID LOGO <i>Ne</i>	1	\$ 62.20	\$ 62.20
3	BOOTLID EMBLEM "ATTRAGE"	1	\$ 63.00	\$ 63.00
4	BOOTLID EMBLEM "MIVEC TECHNOLOGY" <i>Ne</i>	1	\$ 63.00	\$ 63.00
5	BOOTLID EMBLEM "C&C"	1	\$ 63.00	\$ 63.00
6	BOOTLICK TOP LOCK <i>Deled</i>	1	\$ 228.40	\$ 228.40
7	BOOTLID CATCH <i>Ne</i>	1	\$ 103.00	\$ 103.00
8	BOOTLID HINGE <i>Ne</i>	2	\$ 123.20	\$ 246.40
9	BOOTLIT KEYLESS ANTENNA <i>Deled</i>	1	\$ 233.20	\$ 233.20
10	BOOTLID BUZZER	1	\$ 203.40	\$ 203.40
11	BOOTLID WEATHERSTRIP <i>Ne</i>	1	\$ 230.00	\$ 230.00
12	BOOTLID SENSOR LOCK <i>Ne</i>	1	\$ 203.40	\$ 203.40
13	BOOTLID OUTER GARNISH <i>Ne</i>	1	\$ 280.00	\$ 280.00
14	REAR BUMPER <i>Deled</i>	1	\$ 822.30	\$ 822.30
15	REAR BUMPER SIDE RETAINER <i>Ne</i>	2	\$ 72.50	\$ 145.00
16	REAR BUMPER AIR VENT <i>Deled</i>	1	\$ 89.00	\$ 89.00
17	REAR BUMPER AIR VENT COVER <i>Ne</i>	1	\$ 133.00	\$ 133.00
18	REAR BUMPER REFLECTOR <i>Ne</i>	2	\$ 90.00	\$ 180.00
19	REAR BUMPER INNER SIDE BRACKET <i>x nn</i>	2	\$ 130.00	\$ 260.00
20	REAR BUNUMBER PLATE LAMP (SET) <i>Ne</i>	1	\$ 133.80	\$ 133.80
21	TAILLAMP <i>Deled</i>	2	\$ 530.00	\$ 1,060.00

828

96

91

765

770

22	TAILLAMP PANEL <i>Buckled</i>	2	\$ 190.00	\$ 380.00	✓
23	REAR FENDER <i>LH Buckled</i>	2	\$ 890.00	\$ 1,780.00	890. ✓
24	REAR FENDER INNER TRIM <i>new</i>	2	\$ 420.00	\$ 840.00	+
25	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 155.00	\$ 155.00	-
26	REAR END PANEL <i>Distorted</i>	1	\$ 670.00	\$ 670.00	-
27	REAR END PANEL TOP GARNISH <i>Delud</i>	1	\$ 174.00	\$ 174.00	-
28	REAR FLOOR PANEL <i>Pyre</i>	1	\$ 960.80	\$ 960.80	+
29	REAR FLOOR PANEL TOP BAORD <i>torn</i>	1	\$ 360.00	\$ 360.00	155
30	EXHAUST PIPE <i>2nd</i>	1	\$ 810.00	\$ 810.00	+
31	EXHAUST PIPE MOUNTING <i>for</i>	4	\$ 62.30	\$ 249.20	+
32	EXHASUT PIPE INSULATOR	1	\$ 233.90	\$ 233.90	+

5683.60

5115.24

TOTAL PRICE \$ 12,495.50
 LESS 10% \$ 1,249.55
 SUB TOTAL PRICE \$ 11,245.95

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	BOOTLID OUTER GARNISH CLIPS (SET) <i>not me</i>	1	\$ 25.00	\$ 25.00	+
3	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 22.00	\$ 22.00	✓
4	REAR BUMPER LOWER LIP ASSY <i>Delud</i>	1	\$ 1,500.00	\$ 1,500.00	850
5	TAILLAMP CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	-
6	TAILLAMP PANEL SEALANT <i>new</i>	1	\$ 20.00	\$ 20.00	+
7	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	60
8	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	-
8	REAR END PANEL INSULATOR SEAL <i>new</i>	1	\$ 120.00	\$ 120.00	60
8	REAR FLOOR PANEL INSULATOR SEAL <i>new</i>	1	\$ 120.00	\$ 120.00	+
8	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200
8	REVERSE CAMERA <i>new</i>	1	\$ 550.00	\$ 550.00	+

TOTAL \$ 2,787.00

1332

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 2,400.00	1200
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 2,400.00	1400
3	TUFF COAT	1	\$ 150.00	80
4	WIRING CHECK	1	\$ 150.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 120.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 120.00	50

7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	1	\$ 120.00	50
8	TRANSFER TAILGATE MECHANISM	1	\$ 120.00	60
9	REMOVE AND REFIX TAILGATE WINDSCREEN	1	\$ 120.00	✓

3050

TOTAL \$ 5,700.00

ESTIMATE REPORT

TOTAL PARTS COST	\$	14,032.95
TOTAL LABOUR COST	\$	5,700.00
TOTAL REPAIR COST	\$	19,732.95

APPROVED DETAILS:

SURVEYOR:
CONTACT NO.:
PART BY PART/LUMP SUM
NO. OF DAYS

Admin Lg

2/5 21/02/23.

09 Days.

total: 9497.24

4/5: 7.6K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: