

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SPCM1000000828	Date of Loss:	14/04/2023
Vehicle Reg. No.:	XE3164E	Driveable?	
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	DYNA-LOG SINGAPORE PTE. LTD.	Contact No:	+6596662345
Driver:	LOW JOON JIANG, ADRIAN		

Make/Model:	mitsubishi fuso, 12.0 D FP51SDR3VDEA (M)	Vehicle Reg. Date:	05/07/2017
Vehicle Colour:	ORANGE	Chassis No:	FP51SDA20198
Engine No:	OM457332835		
Odometer:	5 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	15

Description of Accident/Loss	REFER TO POLICE
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS	Amount
Parts	33,390.50
Miscellaneous Items	0.00
Labour	3,030.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	36,420.50
+ GST 8.00% (S\$)	2,913.64
Nett Amount (S\$)	39,334.14

This claim is handled by: **JANICE CHANG SIEW YIN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 21 Apr 2023)

Parts: N/A MITSUBISHI FUSO 12.0 D FP51SDR3VDEA (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XE3164E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER <i>ra</i>	0.00	0.00	*2,100.00 F
2	1		*FRT BUMPER BRACKET RH ?	0.00	0.00	*305.00 F
3	1		*FRT BUMPER TOW COVER RH <i>missing</i>	0.00	0.00	*280.00 F
4	1		*FRT BUMPER TOP STEP <i>int</i>	0.00	0.00	*250.00 F
5	1		*FRT BUMPER SIDE RH <i>deform</i>	0.00	0.00	*140.00 F
6	1		*FRT BUMPER AIR GUIDE ?	0.00	0.00	*110.00 F
7	1		*FRT BUMPER SENSOR RH <i>x</i>	0.00	0.00	*190.00 F
8	1		*FRT HEADLAMP RH <i>ra</i>	0.00	0.00	*1,700.00 F
9	1		*FRT HEADLAMP BRACKET RH <i>ra</i>	0.00	0.00	*400.00 F
10	1		*FRT HEADLAMP RIM RH <i>ra</i>	0.00	0.00	*185.00 F
11	1		*FRT FOG LAMP RH <i>ra</i>	0.00	0.00	*270.00 F
12	1		*FRT FOG LAMP RIM RH <i>ra</i>	0.00	0.00	*165.00 F
13	1		*FRT APRON PANEL <i>int</i>	0.00	0.00	*900.00 F
14	1		*FRT APRON HOLDER <i>dent</i>	0.00	0.00	*1,200.00 F
15	1		*FRT APRON GARNISH RH <i>ra</i>	0.00	0.00	*400.00 F
16	1		*FRT PANEL <i>bul</i>	0.00	0.00	*2,800.00 F
17	1		*FRT PANEL HINGE RH <i>x</i>	0.00	0.00	*205.00 F
18	1		*FRT PANEL GRILLE TOP <i>ra</i>	0.00	0.00	*225.00 F
19	1		*FRT PANEL GRILLE BOTTOM <i>ra</i>	0.00	0.00	*230.00 F
20	1		*FRT PANEL FUSO STICKER <i>rec</i>	0.00	0.00	*120.00 F
21	1		*FRT PANEL LOCK (CTR) ?	0.00	0.00	*170.00 F
22	1		*FRT PANEL LOCK STRICKER (CTR) <i>scr</i>	0.00	0.00	*55.00 F
23	1		*FRT PANEL LOCK RH ?	0.00	0.00	*145.00 F
24	1		*FRT PANEL LOCK STRICKER RH <i>scr</i>	0.00	0.00	*40.00 F
25	1		*FRT CORNER PANEL RH <i>ra</i>	0.00	0.00	*650.00 F
26	1		*FRT CORNER PANEL BRACKET TOP ?	0.00	0.00	*150.00 F
27	1		*FRT CORNER PANEL BRACKET BOTTOM ?	0.00	0.00	*150.00 F
28	1		*FRT SIGNAL LAMP RH <i>ra</i>	0.00	0.00	*220.00 F
29	1		*FRT STEP GARNISH RH <i>ra</i>	0.00	0.00	*320.00 F
30	1		*FRT CABIN SUPPORT BEAM <i>dent</i>	0.00	0.00	*2,820.00 F
31	1		*FRT CABIN SUPPORT BRACKET RH <i>dent</i>	0.00	0.00	*2,100.00 F
32	1		*FRT CABIN SUPPORT TOP BRACKET RH ?	0.00	0.00	*550.00 F
33	1		*FRT CABIN ABSORBER ?	0.00	0.00	*270.00 F
34	1		*FRT CABIN AIR BELLOW ?	0.00	0.00	*800.00 F
35	1		*FRT PANEL INNER REINFORCEMENT <i>dent R</i>	0.00	0.00	*2,200.00 F
36	1		*FRT WASHER TANK <i>scr</i>	0.00	0.00	*365.00 F
37	1		*AIRCON CONDENSER <i>dent</i>	0.00	0.00	*400.00 F
38	1		*RADIATOR ?	0.00	0.00	*5,200.00 F
39	1		*RADIATOR FAN COWLING ?	0.00	0.00	*400.00 F
40	1		*RADIATOR FAN BLADE ?	0.00	0.00	*495.00 F
41	1		*AIRCON SUCTION HOSE <i>dent</i>	0.00	0.00	*260.00 F
42	1		*FRT BRACE PANEL <i>dent</i>	0.00	0.00	*420.00 F

F=Franchise part.

Sub Total (\$\$)

30,355.00

+ Margin on L,N Items 10.00% (\$\$)

3,035.50

Report was unsubmitted during this print-out.
Generated using Merlimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						33,390.50

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK, WELD, REMOVE & FIX ABOVE PARTS	New	800 1,400.00
2	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	New	1000 1,300.00
3	TO REFILL AIRCON GAS <i>ml</i>	New	30 100.00
4	TO CHECK WIRING	New	30 50.00
5	TO DIAGNOSE & RESET FAULT CODE	New	X 180.00
Gross Labour Cost (\$\$)			3,030.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

EXC: \$1500

5 days OD

L/S

24/4/23
1pm

1 rfm
90097659 *g*