

Estimate

LKK AUTO CONSULTANTS PTE LTD Singapore, Singapore, Singapore, Singapore, Singapore - 575722. Contact: +65 62563561 Email: sur@lkkauto.com	Proforma Invoice No:	Date: Apr 21 2023
	TP Reg. No: SBH138X	Insured Reg. No: SLK7337H
	Ticket No: LKK-J000115	Accident Date: Apr 19 2023
	Policy No: 0	Claim No: 0
Company Name: INDIA INTERNATIONAL INSURANCE Address: 64 Cecil Street,#04-02 IOB Building City: Singapore Region: Central Singapore Postal Code: 049711 Co.Reg.No: 198703792K	Customer: Tan Boon Tee Vehicle: BMW 2 SERIES GRAN TOURER 216i Sport 2019 Kilometer: 0 Color: WHITE Fuel: PETROL PH: +65 96669680 Email:	

#	Part Name	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Parts Total
1	REAR WINDSCREEN RUBBER	Part	1.00	104.50	73.15	31.35	73.15	73.15
2	REAR TAILGATE	Part	1.00	1,496.00	1,047.20	448.80	1,047.20	1,047.20
3	REAR TAILGATE CENTRE LOGO	Part	1.00	93.50	65.45	28.05	65.45	65.45
4	REAR TAILGATE 216I EMBLEM	Part	1.00	82.50	57.75	24.75	57.75	57.75
5	REAR TAILGATE WEATHER STRIP	Part	1.00	181.50	127.05	54.45	127.05	127.05
6	REAR END PANEL	Part	1.00	825.00	577.50	247.50	577.50	577.50
7	REAR BUMPER	Part	1.00	1,089.00	762.30	326.70	762.30	762.30
8	REAR BUMPER REVERSE SENSOR	Part	2.00	280.00	196.00	168.00	392.00	392.00
9	REAR BUMPER LOWER CENTRE MOULDING	Part	1.00	93.50	65.45	28.05	65.45	65.45
10	REAR BUMPER REINFORCEMENT	Part	1.00	588.50	411.95	176.55	411.95	411.95
11	REAR BUMPER CLIPS	Part	1.00	30.00	21.00	9.00	21.00	21.00
12	REAR EXHAUST PIPE	Part	1.00	1,015.00	710.50	304.50	710.50	710.50
13	REAR EXHAUST PIPE TOP COVER	Part	1.00	99.00	69.30	29.70	69.30	69.30
14	REAR EXHAUST PIPE SIDE BRACKET	Part	1.00	82.50	57.75	24.75	57.75	57.75
15	REAR BUMPER INNER SIDE GARNISH	Part	2.00	198.00	138.60	118.80	277.20	277.20
16	REAR BUMPER INNER CENTRE GARNISH	Part	1.00	66.00	46.20	19.80	46.20	46.20
17	REAR WINDSCREEN SEALANT	Part	1.00	50.00	35.00	15.00	35.00	35.00
							Taxable Value	4,796.75
							Discount Total	2,055.75
							Grand Total	4,796.75

#	Service	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
18	REMOVE, REINSTALL REAR WINDSCREEN	Labour	-	120.00	120.00	0.00	120.00	120.00
19	REMOVE, REINSTALL REVERSE SENSOR	Labour	-	50.00	50.00	0.00	50.00	50.00
20	REMOVE + REINSTALL CAMERA	Labour	-	50.00	50.00	0.00	50.00	50.00
21	REMOVE, REINSTALL EXHAUST PIPE	Labour	-	80.00	80.00	0.00	80.00	80.00
22	REMOVE REINSTALL BOOTLID INNER GARNISH	Labour	-	60.00	60.00	0.00	60.00	60.00
23	REMOVE, REPLACE + REPAIR CONSISTENT TO THE ACCIDENT	Labour	-	800.00	503.25	296.75	503.25	503.25
24	RESPRAY PAINTING	Labour	-	800.00	800.00	0.00	800.00	800.00
25	TUFF KOTE	Labour	-	40.00	40.00	0.00	40.00	40.00
							Taxable Value	1,703.25
							Discount Total	296.75
							Grand Total	1,703.25

	Parts Total	4,796.75
	Labour Total	1,703.25
	GST Total	0.00
	Grand Total	6,500.00
	Balance	6,500.00

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

Customer / Authorized Signatory

Service Advisor Signature

Cashier / Authorized Signature