

WB A6V 120205

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

7, 2 1 1 1

Veron

Vehicle No : SBH 138 X

Chassis No: WBA6V120205N97926

Make/Model : BMW 216i

Accident date : 19.04.2023

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Rear windscreen rubber <i>Xle</i>	1	\$ 104.50
2	Rear tailgate <i>Dented.</i>	1	\$ 1,496.00
3	Rear tailgate hinge @ \$99.00 <i>Xle</i>	2	\$ 198.00
4	Rear tailgate shock absorber @ \$451.00 <i>Xle</i>	2	\$ 902.00
5	Rear tailgate inner board <i>2</i>	1	\$ 346.50
6	Rear tailgate lower lock <i>HP</i>	1	\$ 236.50
7	Rear tailgate upper catch <i>new</i>	1	\$ 82.50
8	Rear tailgate centre logo <i>3 new</i>	1	\$ 93.50
9	Rear tailgate 216i emblem	1	\$ 82.50
10	Rear tailgate reflector @ \$462.00 <i>Xle</i>	2	\$ 924.00
11	Rear camera <i>Xle</i>	1	\$ 550.00
12	Rear tailgate weather strip <i>lit</i>	1	\$ 181.50
13	Rear end panel <i>Dented.</i>	1	\$ 825.00
14	Rear end panel top garnish <i>Xle</i>	1	\$ 126.50
15	Rear bumper <i>Dented.</i>	1	\$ 1,265.00
16	Rear bumper side holder @ \$198.00 <i>cracked. Xle</i>	2	\$ 396.00
17	Rear bumper reflector @ \$49.50 <i>Xle</i>	2	\$ 99.00
18	Rear bumper reverse sensor @ \$462.00 <i>2 pieces dng</i>	4	\$ 1,848.00
19	Rear bumper lower centre moulding <i>lit.</i>	1	\$ 93.50
20	Rear bumper reinformant <i>Dented</i>	1	\$ 588.50
21	Rear bumper bracket @ \$60.50 <i>Xle</i>	2	\$ 121.00
22	Rear bumper clips <i>new</i>	1	\$ 66.00
23	Rear ethaust pipe <i>Dented.</i>	1	\$ <u>1,226.50</u>
24	Rear ethaust pipe chrome <i>Xle</i>	1	\$ 154.00
25	Rear ethaust pipe top cover <i>crumpled.</i>	1	\$ 99.00
26	Rear ethaust moulding @ \$33.00 <i>new</i>	2	\$ 66.00
27	Rear ethaust pipe side bracket @ \$82.50 <i>lit Dng</i>	2	\$ 165.00
28	Rear bumper inner side garnish @ \$198.00 <i>cracked</i>	2	\$ 396.00
29	Rear bumper inner centre garnish <i>cracked.</i>	1	\$ 66.00
			\$ 12,446.50
			\$ 622.33
			\$ 11,824.18

6802.50

6122.25

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Vehicle No : SBH 138 X
Chassis No: WBA6V120205N97926

Make/Model : BMW 216i
Accident date : 19.04.2023

No	DESCRIPTION	Qty	Amount (S\$)
Labour Cost			
1	To supply rear windscreen sealant <i>KL</i>	1	\$ 50.00
2	To supply rear end panel sealant	1	\$ 200.00
3	Remove, reinstall rear windscreen	1	\$ 150.00
4	Remove, reinstall reverse sensor	1	\$ 150.00
5	Remove + reinstall camera	1	\$ 100.00
6	Remove, reinstall exhaust pipe	1	\$ 300.00
7	Remove reinstall bootlid inner garnish	1	\$ 200.00
8	Remove, replace + repair consistent to the accident	1	\$ 1,400.00
9	Respray painting	1	\$ 1,200.00
10	Tuff kote	1	\$ 150.00

Total \$ 3,900.00

Grand Total \$ 15,724.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 8172.25

H/S: 6.5k.

06 Days

6.5k