

ASS. REC. BY:

REF:

15B/23004151/K9p3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/4 84720.80 Coll (Red \$1868.58, 28%)
 LNo Lump Sum)

Date/Time, File Pass to?

1) 05/5 10:00

Date/Time, File Return to?

2)

☐ : Prell. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

F. P. 105

Others

TOTAL

Add Fee:

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

Smart Claims - TP
 4720.80

EDWIN GARAGE AIRCON & REPAIR

BLK 5032 Ang Mo Kio. Industrial Park 2 . #01-295. Singapore 569535

Tel: 97856612

Vehicle No: SMK9255K
Model : HONDA/JAZZ RS

4720.80

PARTS	QTY	AMOUNT	
REAR BUMPER	1	\$ Bu 516.60	✓
REAR BUMPER SIDE RETAINER LH/RH	2	\$ Di 36.34	✓
REAR BUMPER GARNISH	1	\$ Crt 41.16	✓
REAR BUMPER SIDE COVER LH/RH	2	\$ In 44.52	X
REAR END PANEL	1	\$ B 330.33	✓
REAR END PANEL INNER GARNISH	1	\$ In 63.84	✓
REAR FLOOR PANEL TOP BOARD	1	\$ In 204.44	X
REAR FLOOR PANEL SPONGE COMPARTMENT BOX	1	\$ Di/In 126.53	✓
REAR TAILLAMP LH/RH	2	\$ G 536.76	✓
TAILGATE	1	\$ B 818.16	✓
TAILGATE INNER TRIMBOARD	1	\$ My Di 64.37	✓
TAILGATE LOCK	1	\$ In 94.61	✓
TAILGATE OUTER GARNISH ASSY	1	\$ In 118.02	X
REAR 'LOGO' EMBLEM	1	\$ In 22.35	✓
REAR 'JAZZ' EMBLEM	1	\$ In 28.54	✓
REAR 'RS' EMBLEM	1	\$ In 26.85	✓
REAR TAILGATE WEATHERSTRIP	1	\$ Di 96.92	✓
REAR WINDSCREEN MOULDING	1	\$ In 47.90	✓
		\$ 3,218.24	
Less 20%		\$ 643.65	
Sub Total		\$ 2,574.59	
Balance		\$ 2,574.59	

S/NETT ITEMS

REAR NUMBER PLATE	1	\$ In 50.00	45JN
REAR BUMPER CLIP	1 SET	\$ In 60.00	✓
REAR END PANEL INNER GARNISH CLIP	1 SET	\$ In 50.00	✓
TAILGATE INNER TRIMBOARD CLIP	1 SET	\$ In 60.00	✓
REAR REVERSE SENSOR	1 SET	\$ In 320.00	200JN
REAR WINDSCREEN SEALANT	2	\$ In 120.00	40JN
JOINT SEALANT	2	\$ In 120.00	30JN
		\$ 780.00	
Balance		\$ 3,354.59	

LABOUR

CHECK REAR WIRING AND LIGHTING SYSTEM	\$	100.00	20L
REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	\$	200.00	60L
REMOVE AND REFIT TAILGATE COMPONENTS	\$	100.00	60L
REMOVE AND REPLACE REAR WINDSCREEN	\$	200.00	120L
REMOVE AND RENEW REAR REVERSE SENSOR	\$	100.00	50L
REMOVE AND REFIT REAR REVERSE CAMERA	\$	100.00	40L
PANEL BEATING ON AFFECTED AREAS	\$	1,000.00	600L
SPRAY PAINTING ON AFFECTED AREAS	\$	1,000.00	660L
APPLY ANTI RUST ON AFFECTED AREAS	\$	150.00	60L
	\$	2,950.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

acknowledged by Repairer
Signature:

EDWIN GARAGE AIRCON & REPAIR

BLK 5032 Ang Mo Kio. Industrial Park 2 . #01-295. Singapore 569535

Tel: 97856612

Vehicle No: SMK9255K

Model : HONDA/JAZZ RS

SUPPLEMENTARY

PARTS	QTY	AMOUNT
REAR BUMPER LOWER DIFFUSER	1	<i>Del</i> 221.3 ✓
BUZZER ASSY	1	<i>CRM</i> 64.7 ✓
ANTENNA SENSOR	1	<i>CM</i> 63.5 ✓
REAR WINDSCREEN MOULDING	1	<i>rk</i> 6.49 ✓
		355.99
	Less 20%	71.198
	Sub Total	284.792
	Balance	284.792