

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

## ESTIMATE OF REPAIR

GK3 3415149.

Veh# SND6407J

Model: HONDA FIT

Accident Date : 21/4/2023

20/6/2019 - 19/6/2029

Location : AYE NEAR JURONG TOWN EXIT

3P: SLW50825(CHINA TAIPIING)

Xiao Tong

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear tailgate <i>Dented</i>	1,080.70	✓ 862	
2	1 pc	Rear tailgate windscreen moulding <i>new</i>	95.00	✓	
3	1 pc	Rear tailgate windscreen inner seal <i>new</i>		100.00	40
4	1 pc	Rear tailgate windscreen sealant <i>new</i>		80.00	40
5	1 pc	Rear tailgate outer garnish <i>cracked</i>	153.40	✓	
6	1 pc	Rear tailgate outer garnish 'H' logo <i>new</i>		80.00	45
7	1 set	Rear tailgate outer garnish clip <i>new</i>		40.00	20
8	2 pcs	Rear tailgate reflector R/L <i>new</i>	233.00	+	
9	1 pc	Rear tailgate inner trim garnish <i>cracked</i>	161.50	✓	
10	1 set	Rear tailgate inner trim garnish clip		80.00	30
11	1 pc	Rear tailgate pull garnish <i>Head Behind</i>	23.50	✓	
12	2 pcs	Rear tailgate guide rubber stopped R/L <i>new</i>	31.00	+	
13	1 pc	Rear tailgate mechanism lock <i>new</i>	97.70	✓	
14	1 pc	Rear tailgate weatherstrip seal <i>cut</i>	101.50	✓	
15	1 pc	Rear tailgate emblem 'FIT' <i>new</i>		100.00	50
16	1 pc	Rear tailgate wiper motor <i>new</i>	225.60	+	
17	1 pc	Rear no. plate (Aluminium type) <i>new Misery</i>		150.00	80
18	1 pc	Rear no. plate holder <i>Behind</i>		50.00	30
19	2 pcs	Rear tail lamp R/L <i>cut</i>	650.60	✓	
20	2 sets	Rear tail lamp clip R/L <i>new</i>		60.00	20
21	2 pcs	Rear tail lamp panel R/L <i>Dented</i>	239.50	✓	
22	1 pc	Rear bumper <i>Behind</i>	890.40	✓ 492	
23	2 pcs	Rear bumper side retainer L/R <i>new</i>	26.40	✓	
24	1 set	Rear bumper clip <i>new</i>		50.00	30
25	1 set	Rear bumper reverse sensor <i>new</i>		280.00	200
26	2 pcs	Rear bumper end seal cover R/L <i>new</i>	73.60	+	
27	1 pc	Rear bumper center garnish moulding <i>cut</i>	160.15	✓	
28	2 pcs	Rear bumper side garnish cover R/L <i>cut</i>	134.10	✓	
29	1 pc	Rear bumper lower spoiler <i>Behind</i>		600.00	450.
30	1 set	Rear bumper side air vent <i>Behind Misery new</i>		180.00	160.
31	1 pc	Rear exhaust silencer <i>Best</i>	475.40	✓	
32	2 pcs	Rear exhaust rubber mounting <i>new</i>	35.00	✓	

new

33	1 pc	Rear exhaust gasket kit <i>new</i>	32.80	✓	
34	1 pc	Rear exhaust aluminium heat shield <i>dent</i>	30.50	✓	
35	1 pc	Rear end panel <i>Dented</i>	<del>539.10</del>	399	
36	1 pc	Rear end panel inner top garnish <i>dent</i>	160.80	✓	
37	1 set	Rear end panel inner top garnish clip <i>new</i>		<del>30.00</del>	20
38	1 pc	Rear end panel sealant <i>new</i>		<del>100.00</del>	60
39	2 pcs	Rear fender inner trim garnish R/L <i>Dented</i>	659.20	✓	
40	2 sets	Rear fender inner trim garnish clip R/L <i>new</i>		<del>100.00</del>	60
41	1 pc	Rear spare tyre panel <i>Buckled</i>	766.70	✓	
42	1 pc	Rear spare tyre inner top cover <i>Dented</i>	289.80	✓	
43	1 pc	Rear spare tyre sponge tray <i>cracked</i>	146.35	✓	
44	1 pc	Rear spare tyre panel insulator mat <i>new</i>		<del>280.00</del>	x
45	1 pc	Rear spare tyre panel sealant <i>new</i>		<del>100.00</del>	60
46	1 pc	Rear fender air vent RH <i>missing</i>	42.35	✓	
47	1 pc	Rear fender RH <i>Repair</i>	588.30	x	
48	1 pc	Rear fender glass seal RH <i>new</i>	56.90	x	
49	1 pc	Rear fender glass sealant <i>new</i>		<del>60.00</del>	x
50	1 pc	Rear buzzer sensor <i>damaged</i>	89.00	✓	
51	1 pc	Rear antenna sensor	92.00	✓	
52	1 pc	Rear floor extension top panel RH <i>Repair</i>	163.75	x	
			Sub Total:	8,545.60	2520.00 0.00
				20%	0% 0%
			After Less %:	6,836.48	2520.00 0.00
<b>Labour</b>			S.N: 1325		
1		To remove & refix accident damaged parts & realign accident affected area.		<del>2,300.00</del>	1200
2		To spray paint on accident affected area.		<del>1,800.00</del>	1400
3		To remove & refix rear tailgate windscreen.		<del>150.00</del>	120
4		To remove & refix rear tailgate mechanism & check for function.		<del>80.00</del>	60
5		To remove & refix upholstery, side covering, trim garnish, rear seat & other attachment parts.		<del>150.00</del>	60
6		To remove & refix rear fender glass.		<del>80.00</del>	x
7		To remove & refix exhaust silencer.	3270	<del>150.00</del>	80
8		To rust proof accident affected area.		<del>120.00</del>	100
9		To conduct chassis alignment.		<del>300.00</del>	x
10		To check wiring & rewire parking sensor.		<del>80.00</del>	50
			Sub Total:	5,210.00	
			Total:	14,566.48	
			After Less 20%:	11,653.18	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental charges must be resurveyed and is subject to final approval from Insurance Company



bizSAFE 8778 1999  
24 hr accident call

Mobil 1

