

ASS. REC. BY:

REF: CT2 / 23.00 4155 1K4

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s SMRT

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S14B 912M Yr Regn: 051 16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius C.C. 1798Colour: M. Brown A/C: Insured / Std / NI / NASp. Reading: 489186 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN36U205768118Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD / RIM or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

Rear

R/Bal. 8 mmR/Bal. 9 mmL/Bal. 8 mmL/Bal. 9 mmD.O.A. 20/4/23D.O.I. 21/4/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

01/ST

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1615 212m @ 29501 Cntr

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/04/2023

User ID : munsan

Section A - Accident Details

Registration Number	SHB912M
Case Reference Number	TAX/04/23/2045
Registration Date	13/5/16
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	WONG WENG WAH
Type of Accident	Side Swipe
Accident Date and Time	20/4/23 4:35 PM
Accident Reported Date and Time	21/4/23 10:08 AM
Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24118234
Special Instruction to ARC, if any	TP/ RIGHT FRONT PORTION
Prepared Date and Time	21/4/23 11:09 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$0.00
Total Spray Cost	\$1,416.00	\$0.00
Total Spare Part Cost	\$7,137.29	\$0.00
Total Other Cost	\$620.00	\$0.00
TOTAL COST	\$10,018.29	\$0.00
ump Sum Total	\$10,000.00	\$0.00
Number of Repair Days	6.0	3 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	21/04/2023 11:25 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/04/2023

User ID : munsan

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR RH FRONT PORTION	\$845.00 <i>4001</i>	
total Labour	\$845.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY FRONT BUMPER	\$378.00 <i>2001</i>	
O RESPRAY FRONT BUMPER LOWER GRILLE	\$220.00 <i>nn X</i>	
O RESPRAY FRONT SUPPORT PANEL	\$220.00 <i>nn X</i>	
O RESPRAY FRONT FENDER RH	\$378.00 <i>2001</i>	
O RESPRAY RIM	\$220.00 <i>X</i>	
total Spray Painting & Panel Beating	\$1,416.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00 <i>nn X</i>	
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00 <i>201</i>	
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00 <i>301</i>	
O DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00 <i>nn X</i>	
O REMOVE AND REFIT TYRE	\$120.00 <i>1 X</i>	
O REPLACE SUNDRY PARTS	\$100.00 <i>nn X</i>	
total Other Costs	\$620.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$602.60	25.00	\$451.95	Replace	<i>nn ✓</i>
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	<i>nn ✓</i>
		52115-47040	BUMPER SUPPORT F/RH	1.00	\$86.20	25.00	\$64.65	Replace	<i>nn ✓</i>
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$97.60	25.00	\$73.20	Replace	<i>nn X</i>
		52021-47023	BUMPER REINFORCEMENT FRT	1.00	\$567.90	25.00	\$425.92	Replace	<i>nn X</i>
		57013-47030	ARM SUB-ASSY,FR BUMPER RH	1.00	\$284.00	25.00	\$213.00	Replace	<i>nn X</i>
		57014-47030	ARM SUB-ASSY,FR BUMPER LH	1.00	\$284.00	25.00	\$213.00	Replace	<i>nn X</i>
		53293-47040	DEFLECTOR, RADIATOR RH	1.00	\$94.30	25.00	\$70.73	Replace	<i>nn X</i>
		53294-47030	DEFLECTOR, RADIATOR LH	1.00	\$86.90	25.00	\$65.18	Replace	<i>nn X</i>
		52127-47903	COVER, FR BUMPER HOLE RH	1.00	\$21.40	25.00	\$16.05	Replace	<i>nn X</i>
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$389.90	25.00	\$292.42	Replace	<i>nn X</i>
		81210-12230	FOG LAMP RH	1.00	\$335.60	10.00	\$302.04	Replace	<i>nn ✓</i>
		81519-47040	BRACKET, FR TURN UPPER RH	1.00	\$32.30	25.00	\$24.22	Replace	<i>nn X</i>
		81519-47060	BRACKET, FR TURN CENTER RH	1.00	\$76.60	25.00	\$57.45	Replace	<i>nn X</i>
		81519-47050	BRACKET, FR TURN LOWER RH	1.00	\$34.40	25.00	\$25.80	Replace	<i>nn X</i>
		81511-47050	LENS & BODY, FR TURN RH	1.00	\$581.40	10.00	\$523.26	Replace	<i>nn X</i>
		75310-47010	EMBLEM FRONT	1.00	\$98.70	25.00	\$74.03	Replace	<i>nn ✓</i>
		53111-47040	GRILLE, RADIATOR	1.00	\$389.30	25.00	\$291.98	Replace	<i>nn X</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 21/04/2023

User ID : munsan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53113 - 47040	GRILLE, RADIATOR LOWER NO.2	1.00	\$118.30	25.00	\$88.73	Replace	✓ X
		76851-47020	BUMPER LIP FRT	1.00	\$182.70	25.00	\$137.02	Replace	✓ X
		52618-47050	BUMPER FRT ABSORBER LOWER	1.00	\$159.30	25.00	\$119.48	Replace	✓ X
		51410-12105	UNDER COVER CENTER	1.00	\$511.20	25.00	\$383.40	Replace	✓ X
		51443-12080	UNDER COVER SIDE/RH	1.00	\$52.50	25.00	\$39.38	Replace	✓ X
		81130-47500	HEAD LAMP RH	1.00	\$1,075.40	10.00	\$967.86	Replace	✓ ✓
		53201-47902	SUPPORT SUB-ASSY	1.00	\$1,839.70	25.00	\$1,379.78	Replace	✓ X
		16533-28051	SUPPORT RADIATOR, RH	1.00	\$72.00	25.00	\$54.00	Replace	✓ X
		53801-47050	FENDER FRT/RH	1.00	\$916.30	25.00	\$687.22	Replace	✓ ✓
		75374-47051	NAME PLATE (HYBRID)	1.00	\$59.20	25.00	\$44.40	Replace	✓ X
		53875-47030	FENDER LINER FRT/RH	1.00	\$195.40	25.00	\$146.55	Replace	✓ X
		53851-47040	FENDER LINER PAD, FR WHEEL, RH	1.00	\$56.30	25.00	\$42.22	Replace	✓ X
		42611-47140	WHEEL DISC. FRONT	1.00	\$1,978.60	25.00	\$1,483.95	Replace	✓ X
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	✓ X
		43550-47011	WHEEL HUB FRT	1.00	\$722.10	25.00	\$541.58	Replace	✓ X
total					\$12,133.64		\$9,463.19		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									