

Section A - Accident Details

Registration Number	SHB912M
Case Reference Number	TAX/04/23/2045
Registration Date	13/May/2016
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	WONG WENG WAH
Type of Accident	Side Swipe
Accident Date and Time	20/Apr/2023 4:35 PM
Accident Reported Date and Time	21/Apr/2023 10:08 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118234
Special Instruction to ARC, if any	TP/ RIGHT FRONT PORTION
Prepared Date and Time	21/Apr/2023 11:09 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$1,416.00	\$400.00
Total Spare Part Cost	\$7,570.55	\$2,102.53
Total Other Cost	\$620.00	\$50.00
TOTAL COST	\$10,451.55	\$2,952.53
Lump Sum Total	\$10,450.00	\$2,950.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / China Taiping
ARC / Surveyor Sign Off Date	21/04/2023 5:27 PM	21/04/2023 4:24 PM
Signature		
Remarks	LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) / HP : 9691 0663 / Email : kennethkong@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2305-0071	Invoice Number	
Quotation Date	08.05.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	\$845.00	\$400.00
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$220.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$220.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$220.00	\$0.00
Total Spray Painting & Panel Beating	\$1,416.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$620.00	\$50.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$602.60	25.00	\$451.95	Replace	Replace
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
		52115-47040	BUMPER SUPPORT F/RH	1.00	\$86.20	25.00	\$64.65	Replace	Replace
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$97.60	0.00	\$0.00	Replace	Check
		52021-47023	BUMPER REINFORCEMENT FRT	1.00	\$567.90	100.00	\$0.00	Replace	Repair
		57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$284.00	0.00	\$0.00	Replace	Check
		57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$284.00	0.00	\$0.00	Replace	Not Given
		53293-47040	DEFLECTOR, RADIATOR RH	0.00	\$94.30	0.00	\$0.00	Replace	Not Given
		53294-47030	DEFLECTOR, RADIATOR LH	0.00	\$86.90	0.00	\$0.00	Replace	Not Given
		52127-47903	COVER, FR BUMPER HOLE RH	0.00	\$21.40	0.00	\$0.00	Replace	Not Given

✓ bt
 ✓ nec
 ✓ dis
 X svc
 R
 X r
 X svc
 X svc
 X svc
 X svc

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 14/05/2023

User ID : PohSuan

		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$389.90	0.00	\$0.00	Replace	Not Given	X	svc
		81210-12230	FOG LAMP RH	1.00	\$335.60	10.00	\$302.04	Replace	Replace	√	cut
		81519-47040	BRAKET, FR TURN UPPER RH	0.00	\$32.30	0.00	\$0.00	Replace	Not Given	X	} r
		81519-47060	BRAKET, FR TURN CENTER RH	0.00	\$76.60	0.00	\$0.00	Replace	Not Given	X	
		81519-47050	BRAKET, FR TURN LOWER RH	0.00	\$34.40	0.00	\$0.00	Replace	Not Given	X	
		81511-47050	LENS & BODY, FR TURN RH	0.00	\$581.40	0.00	\$0.00	Replace	Not Given	X	SVC
		75310-47010	EMBLEM FRONT	1.00	\$98.70	25.00	\$74.03	Replace	Replace	√	nec
		53111-47040	GRILLE, RADIATOR	0.00	\$389.30	0.00	\$0.00	Replace	Not Given	X	} svc
		53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$118.30	0.00	\$0.00	Replace	Not Given	X	
		76851-47020	BUMPER LIP FRT	0.00	\$182.70	0.00	\$0.00	Replace	Not Given	X	} SVC
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$159.30	0.00	\$0.00	Replace	Not Given	X	
		51410-12105	UNDER COVER CENTER	0.00	\$511.20	0.00	\$0.00	Replace	Not Given	X	} SVC
		51443-12080	UNDER COVER SIDE/RH	0.00	\$52.50	0.00	\$0.00	Replace	Not Given	X	
		81130-47500	HEAD LAMP RH	1.00	\$1,075.40	10.00	\$967.86	Replace	Replace	√	cut
		53201-47902	SUPPORT SUB-ASSY	0.00	\$1,839.70	0.00	\$0.00	Replace	Not Given	X	r
		16533-28051	SUPPORT RADIATOR, RH	0.00	\$72.00	0.00	\$0.00	Replace	Not Given	X	r
		53801-47050	FENDER FRT/RH	1.00	\$916.30	25.00	\$687.23	Replace	Replace	√	bt
		75374-47051	NAME PLATE (HYBRID)	1.00	\$59.20	25.00	\$44.40	Replace	Replace	√	nec
		53875-47030	FENDER LINER FRT/RH	0.00	\$195.40	0.00	\$0.00	Replace	Not Given	X	} SVC
		53851-47040	FENDER LINER PAD, FR WHEEL. RH	0.00	\$56.30	0.00	\$0.00	Replace	Not Given	X	
		42611-47140	WHEEL DISC. FRONT	0.00	\$1,978.60	0.00	\$0.00	Replace	Not Given	X	
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	
		43550-47011	WHEEL HUB FRT	0.00	\$722.10	0.00	\$0.00	Replace	Not Given	X	
Total					\$12,133.64		\$2,628.16				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	2,628.16	
	-20%	
	2102.53	L/S \$2,950/-
+	400.00	
+	450.00	
	2,952.53	