

Not Authorized
1/1 Day @
Working After Rain
4 days

ESTIMATION REPORT

Vehicle No : SMN2447D
 Make & Model : OPEL, INSIGNIA GRANDSPORT B16DTH, W0VZM6EF6K1055888
 Estimation No. : E23040010
 Date : 20/04/2023

No.	Code	Description	Qty	U/P	Disc %	Amt
Section: Parts						
1		39214206 FRONT BONNET	1.00	2,046.00	0.00	2,046.00 ✓
2		39107929 FRONT RADIATOR GRILLE	1.00	358.80	0.00	358.80 X
3		13491196 FRONT RADIATOR GRILLE MOULDING (CHROME)	1.00	328.80	0.00	328.80 X
4		13491191 FRONT RADIATOR GRILLE MOULDING RH (CHROME)	1.00	157.20	0.00	157.20 X
5		39197502 FRONT BUMPER UPPER INNER GARNISH	1.00	169.20	0.00	169.20 X
6		39114984 FRONT RADIATOR TOP GARNISH	1.00	48.00	0.00	48.00 X
7		13491204 FRONT LOGO EMBLEM	1.00	90.00	0.00	90.00 X
8		39159651 FRONT BUMPER	1.00	1,389.60	0.00	1,389.60 ✓
9		39098178 FRONT BUMPER SPONGE	1.00	128.40	0.00	128.40 ?
10		39117745 FRONT BUMPER REINFORCEMENT	1.00	550.80	0.00	550.80 X
11		39210100 FRONT HEADLAMP RH	1.00	1,161.00	0.00	1,161.00 ✓
12		13491383 HEADLAMP BRACKET RH	1.00	56.40	0.00	56.40 ?
13		39077621 FRONT UPPER SUPPORT PANEL	1.00	204.00	0.00	204.00 X
14		95515167 FRONT PARKING SENSOR	2.00	246.00	0.00	492.00 X
15		39108782 FRONT PEDESTRIAN CRASH SENSOR	1.00	410.40	0.00	410.40 X
16		39125440 FRONT FENDER RH	1.00	716.40	0.00	716.40 ✓
17		13312747 ALLOY RIM	1.00	550.00	0.00	550.00 X

Subtotal S\$ 8,857.00

Section: Special nett

18		BUMPER CLIP	7.00	7.00	0.00	49.00 ✓
----	--	-------------	------	------	------	---------

Continue on next page...

ESTIMATION REPORT

 Vehicle No : SMN2447D
 Make & Model : OPEL, INSIGNIA GRANDSPORT B16DTH,
 W0VZM6EF6K1055888

 Estimation No. : E23040010
 Date : 20/04/2023

No.	Code	Description	Qty	U/P	Disc %	Amt
19		FENDER INNERSHIELD CLIP	10.00	7.00	<i>na</i> 0.00	70.00 X
20		RADIATOR TOP GARNISH CLIP	10.00	7.00	<i>na</i> 0.00	70.00 X
Subtotal						S\$ 189.00

Section: Labour

21		TO DISMANTLE & PANAL BEATING & REPLACE FRONT BUMPER, FRONT BONNET, FRONT FENDER RH. FRONT SUPPORT PANEL, AND ETC	1.00	1,500.00	0.00	1,500.00 <i>500</i>
22		TO DISMANTLE & RENEW FRONT PARKING SENSOR	1.00	120.00	0.00	120.00 <i>60</i>
23		TO CHECK ELECTRIC WIRING FOR PROPER FUNTION INCLUDING ADJUST OF HEADLAMP	1.00	120.00	0.00	120.00 <i>20</i>
24		TO CONDUCT 4 WHEEL ALIGNMENT & BALANCING	1.00	120.00	0.00 <i>na</i>	120.00 X
25		TO APPLY RUST PROOFING	1.00	120.00	0.00	120.00 <i>60</i>
26		TO RESPRAY FRONT BUMPER, FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER RH, AND ETC	1.00	1,200.00	0.00	1,200.00 <i>600</i>

Subtotal S\$ 3,180.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Remarks:
 INDIA INTERNATIOLNAL INSURANCE
 DOA : 17/4/2023
 TP CLAIM

Parts Subtotal	S\$ 8,857.00
Special nett Subtotal	S\$ 189.00
Labour Subtotal	S\$ 3,180.00
Total Discount	S\$ 0.00
Total	S\$ 12,226.00