

# ESTIMATE

20/4/2023

**LONPAC INSURANCE BHD**  
300 BEACH ROAD  
17-04/07 THE CONCOURSE  
SINGAPORE 199555

Vehicle No: SMZ2507B  
Vehicle Model: SKODA OCTAVIA  
Est No: CD2862  
Claims ref:  
Accident Date: 13/04/23  
In Charge: JUNIOR  
Remarks:

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel : (65) 6476 3333  
Fax : (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel : (65) 6272 3892  
Fax : (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

| No                 | Description                        | Qty   | U. Price    | Amounts S\$           |
|--------------------|------------------------------------|-------|-------------|-----------------------|
| <b>LIST ITEMS:</b> |                                    |       |             |                       |
| 1                  | FRONT BUMPER                       | 1 PC  | \$ 1,875.00 | \$ 1,875.00 <i>Ry</i> |
| 2                  | FRONT BUMPER RETAINER RH / LH      | 2 PC  | \$ 87.50    | \$ 175.00 <i>X</i>    |
| 3                  | FRONT BUMPER CLIPS                 | 10 PC | \$ 4.50     | \$ 45.00 <i>aka</i>   |
| 4                  | RADIATOR GRILLE BASE W GRILLE      | 1 PC  | \$ 920.00   | \$ 920.00 <i>cur</i>  |
| 5                  | FRONT BONNET                       | 1 PC  | \$ 2,875.00 | \$ 2,875.00 <i>ht</i> |
| 6                  | FRONT EMBLEM "SKODA" LOGO          | 1 PC  | \$ 167.25   | \$ 167.25 <i>na</i>   |
| 7                  | RADIATOR TOP COVER CLIPS           | 10 PC | \$ 4.50     | \$ 45.00 <i>na</i>    |
| 8                  | FRONT BONNET LOCK ASSY             | 1 PC  | \$ 262.50   | \$ 262.50 <i>?</i>    |
| 9                  | RADIATOR GRILLE OUTER CHROME       | 1 PC  | \$ 985.20   | \$ 985.20 <i>cut</i>  |
| 10                 | H/LAMP LH & RH C/W GRILLE SIDELAMP | 2 PC  | \$ 2,875.50 | \$ 5,751.00 <i>*?</i> |
| 11                 | FRONT BUMPER SPONGE                | 1 PC  | \$ 192.50   | \$ 192.50 <i>?</i>    |
| 12                 | FRONT BUMPER REINFORCEMENT         | 1 PC  | \$ 937.50   | \$ 937.50 <i>x</i>    |
| 13                 | FRONT BUMPER SPONGE - CHECK        | 1 PC  |             | \$ -                  |
| LIST TOTAL S\$     |                                    |       |             | \$ 14,230.95          |
| 15% COST PLUS S\$  |                                    |       |             | \$ 2,134.64           |
|                    |                                    |       |             | <u>\$ 16,365.59</u>   |

|                       |                                                                                |  |  |                         |
|-----------------------|--------------------------------------------------------------------------------|--|--|-------------------------|
| <b>LABOUR CHARGE:</b> |                                                                                |  |  |                         |
| 1                     | TO CUT, WELD, JACK, STRAIGHTEN, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS |  |  | <i>400</i><br>\$ 600.00 |
| 2                     | TO PUTTY SPRAY PAINT ON BONNET, FRONT BUMPER & AFFECTED AREAS                  |  |  | <i>400</i><br>\$ 600.00 |
| 3                     | TO RUST PROOF ON AFFECTED AREAS                                                |  |  | <i>30</i><br>\$ 100.00  |
| 4                     | TO TRANSFER FRONT BUMPER PARKING SENSOR                                        |  |  | <i>30</i><br>\$ 80.00   |
| 5                     | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING                              |  |  | <i>30</i><br>\$ 80.00   |



Automotive Pte Ltd

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel : (65) 6476 3333  
Fax : (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel : (65) 6272 3892  
Fax : (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

## ESTIMATE

20/4/2023

**LONPAC INSURANCE BHD**  
300 BEACH ROAD  
17-04/07 THE CONCOURSE  
SINGAPORE 199555

Vehicle No: SMZ2507B  
Vehicle Model: SKODA OCTAVIA  
Est No: CD2862  
Claims ref:  
Accident Date: 13/04/23  
In Charge: JUNIOR  
Remarks:

| No                    | Description                                                 | Qty | U. Price | Amounts S\$                      |
|-----------------------|-------------------------------------------------------------|-----|----------|----------------------------------|
| 6                     | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS              |     |          | \$ 280.00 <sup>180? parts.</sup> |
| 7                     | TO REMOVE & REFIT BONNET MECHANISM & OTHER ATTACHMENT PARTS |     |          | \$ 80.00 ✓                       |
| TOTAL LABOUR COST S\$ |                                                             |     |          | <u>\$ 1,820.00</u>               |

AMOUNT S\$ \$ 18,185.59  
GST @ 8% \$ 1,454.85  
AMOUNT DUE S\$ \$ 19,640.44

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfah 97495749 / 62563561  
'wp' 15/5/23 @ 840pm  
Tanfah @ lkkauto.com  
L/S Resurvey after repair  
3-4 days.