

ASS. REC. BY:

REF:

A151

Kenneth

ASSIGNMENT

1790T

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

21 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV

REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SAG 1709T

Yr Regn:

10, 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW

325i Coupe

2497

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAWB32050PV54013

Gen. Cohd: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / SRIm / STD A/RIm or

Tyre Size:

F:

235/35ZR19

R:

265/30ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Towader

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

12/4/23

D.O.I.

24/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The vehicle caught fire. The cause of fire

The UIC / Chassis frame / Body Structure affected due to collision.

probably due to short-circuit at the dashboard
compartment.

Date / Time

Action / Instruction

Boot lid unable to open

Date/Time, File Pass to?



: Prel. Report



: Final Report

1)

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transport:

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

) \$ - RS. \$

), File

), Others

Report Format:

ump-Sum / I.B.I: (\$

TOTAL

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2002599849-01	Date of Loss:	12/04/2023
Vehicle Reg. No.:	SNG1790T	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM YI SHENG	Contact No:	+6586089596
Driver:	LIM YI SHENG		
Make/Model:	BMW 325i, 2.5 COUPE XL (A)	Vehicle Reg. Date:	28/10/2009
Vehicle Colour:	White		
Engine No:	11097238N52B25AF	Chassis No:	WBAWB32050PV54013
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	30 21 days		
Present Location:	DING AUTO PTE LTD (HQ)		

*Not withash
L1Pm &
EX TRA*

COST OF CLAIMS

	Amount
Parts	101,579.50
Miscellaneous Items	550.00
Labour	5,880.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	108,009.50
+ GST 8.00% (S\$)	8,640.76
Nett Amount (S\$)	116,650.26

This claim is handled by: HENRY LEE YOON SANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Apr 2023)
 Parts: M1-COUPE BMW 325I 2.5 COUPE XL (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ding Auto Pte Ltd/SNG1790T/21/04/2023 17:33
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

'8' Burn

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT WINDSCREEN - GLASS	B	0.00	0.00	*1,180.00 F
2	1		*FRONT WINDSCREEN GLASS MOULDING	L	0.00	0.00	*120.00 F
3	1		*DASHBOARD CPL	5	0.00	0.00	*5,200.00 F
4	1		*AIRBAG - DRIVER	5	0.00	0.00	*1,950.00 F
5	1		*AIRBAG - PASSENGER	5	0.00	0.00	*1,850.00 F
6	1		*AIRBAG - ECU	5	0.00	0.00	*1,600.00 F
7	1		*SEAT BELT ASSY RH		0.00	0.00	*540.00 F
8	1		*SEAT BELT ASSY LH		0.00	0.00	*540.00 F
9	1		*STEERING WHEEL CPL		0.00	0.00	*1,800.00 F
10	1		*STEERING WHEEL COVER		0.00	0.00	*390.00 F
11	1		*STEERING COLUMN WITH SWITCHES CPL		0.00	0.00	*1,050.00 F
12	1		*LAMP SWITCH CPL		0.00	0.00	*395.00 F
13	1		*DASHBOARD METER CPL	B	0.00	0.00	*2,550.00 F
14	1		*DASHBOARD AIR VENT FULL SYSTEM CPL	B	0.00	0.00	*1,850.00 F
15	1		*DASHBOARD LOWER GARNISH RH		0.00	0.00	*250.00 F
16	1		*DASHBOARD LOWER GARNISH LH		0.00	0.00	*200.00 F
17	1		*DASHBOARD DRAWER PANEL	B	0.00	0.00	*950.00 F
18	1		*AIR BLOWER CPL	B	0.00	0.00	*980.00 F
19	1		*HEATER BLOWER CPL	B	0.00	0.00	*1,080.00 F
20	1		*AIR COND CONTROLLER SWITCH PANEL CPL	B	0.00	0.00	*2,480.00 F
21	1		*AIR OUTLET VENT RH	sm	0.00	0.00	*300.00 F
22	1		*AIR OUTLET VENT LH	B	0.00	0.00	*300.00 F
23	1		*AIR OUTLET CTR VENT		0.00	0.00	*350.00 F
24	1		*RADIO SYSTEM CPL	B	0.00	0.00	*2,850.00 F
25	1		*GEAR KNOB SYSTEM CPL	B	0.00	0.00	*320.00 F
26	1		*GEAR KNOB COVER	B	0.00	0.00	*280.00 F
27	1		*GEAR CONSOLE PANEL CPL	B	0.00	0.00	*750.00 F
28	1		*REAR CTR CONSOLE PANEL WITH ARM REST CPL	B	0.00	0.00	*1,250.00 F
29	1		*CTR CONSOLE POWER WINDOW SWITCH X2		0.00	0.00	*360.00 F
30	1		*HAND BRAKE KIT CPL		0.00	0.00	*700.00 F
31	1		*DOOR INNER TRIM RH		0.00	0.00	*2,600.00 F
32	1		*DOOR INNER TRIM LH	B	0.00	0.00	*2,600.00 F
33	1		*DOOR WINDOW SWITCH PANEL RH	sm	0.00	0.00	*945.00 F
34	1		*DOOR WINDOW SWITCH PANEL LH		0.00	0.00	*945.00 F
35	1		*HEADLINING CPL	B	0.00	0.00	*2,250.00 F
36	1		*HEADLINING AIRBAG RH		0.00	0.00	*950.00 F
37	1		*HEADLINING AIRBAG LH	B	0.00	0.00	*950.00 F
38	1		*REAR VIEW MIRROR WITH DIM LAMP CPL	B	0.00	0.00	*1,000.00 F
39	1		*SUN VISOR RH	B	0.00	0.00	*300.00 F
40	1		*SUN VISOR LH	B	0.00	0.00	*300.00 F
41	1		*SUN VISOR LH	B	0.00	0.00	*300.00 F
42	1		*HEADLINING - CTR DIM LAMP CPL	B	0.00	0.00	*300.00 F
43	1		*HEADLINING - HANDLE X 4	B	0.00	0.00	*320.00 F
44	1		*FRONT SIDE TRIM RH	B	0.00	0.00	*600.00 F
45	1		*FRONT SIDE TRIM LH		0.00	0.00	*200.00 F
46	1		*CTR UPPER TRIM RH	B	0.00	0.00	*200.00 F
47	1		*CTR UPPER TRIM LH	B	0.00	0.00	*220.00 F

48	1	*CTR LOWER TRIM RH	0.00	0.00	*220.00 F	X
49	1	*CTR LOWER TRIM LH	0.00	0.00	*220.00 F	✓
50	1	*REAR UPPER TRIM RH	0.00	0.00	*250.00 F	✓
51	1	*REAR UPPER TRIM LH	0.00	0.00	*250.00 F	✓
52	1	*FRONT SEAT CPL RH	0.00	0.00	*5,680.00 F	✓
53	1	*FRONT SEAT CPL LH	0.00	0.00	*5,680.00 F	✓
54	1	*REAR SEAT CPL	0.00	0.00	*7,800.00 F	✓
55	1	*FLOOR CARPET CPL	0.00	0.00	*880.00 F	✓
56	1	*REAR SIDE ARM TRIM RH	0.00	0.00	*400.00 F	✓
57	1	*REAR SIDE ARM TRIM LH	0.00	0.00	*400.00 F	✓
58	1	*REAR UPPER SPEAKER BOARD PANEL	0.00	0.00	*900.00 F	✓
59	1	*REAR SPEAKER X2	0.00	0.00	*1,400.00 F	✓
60	1	*DOOR SPEAKER X2	0.00	0.00	*1,600.00 F	✓
61	1	*DASHBOARD TWEETER SPEAKER X2	0.00	0.00	*3,200.00 F	✓
62	1	*INTERIOR HARNESS WIRE CPL	0.00	0.00	*5,250.00 F	✓
63	1	*DASHBOARD HARNESS WIRE CPL	0.00	0.00	*2,250.00 F	✓
64	1	*HEADLINING HARNESS WIRE CPL	0.00	0.00	*2,200.00 F	✓
65	1	*FUSE HOUSING CPL	0.00	0.00	*3,950.00 F	✓
66	1	*ENGINE ECU	0.00	0.00		✓

F=Franchise part.

Sub Total (\$\$) 92,345.00
+ Margin on L,N Items 10.00% (\$\$) 9,234.50

Total Parts (\$\$) 101,579.50

Ding Auto Pte Ltd/SNG1790T/21/04/2023 17:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

No	Qty	Particulars	Amount
1	1	ENGINE ECU - DIAGNOSIS/RE-PROGRAMMING	550.00
			7

Sub Total (S\$) 550.00

Estimates on Labour

No Particulars

Labour Items

No	Particulars	Lab. Type	Amount
1	REMOVE, CLEANING & RESTORATION - INTERIOR DAMAGED COMPONENTS	New	2,000.00
2	REMOVE & REFIT - DASHBOARD COMPONENTS	New	450.00
3	REMOVE & REFIT - HEADLINING COMPONENTS	New	450.00
4	REMOVE & REFIT - SEAT BELT COMPONENTS	New	350.00
5	REMOVE & REFIT - FRONT & REAR SEAT CUSHION COMPONENTS	New	350.00
6	REMOVE & REFIT - DOORS INNER TRIM & COMPONENTS	New	350.00
7	REMOVE & REFIT - INTERIOR FULL HARNESS WIRING	New	350.00
8	REMOVE & REFIT - INTERIOR SIDE & PILLAR TRIM/PANEL COMPONENTS	New	350.00
9	REMOVE & REFIT - FLOOR CARPET, CONSOLE & COMPONENTS	New	350.00
10	REMOVE & REFIT - FRONT WINDSCREEN GLASS & MOULDING	New	180.00
11	CHECKING & TEST WIRING - INTERIOR ELECTRICAL & ELECTRONIC GADGET SYSTEM COMPONENTS	New	350.00
12	CHECKING, CLEANING & TESTING - AIR COND COMPONENTS	New	350.00

Gross Labour Cost (S\$) 5,880.00

Ding Auto Pte Ltd/SNG1790T/21/04/2023 17:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 13/04/2023 15:20 (SGT)
Reported by Both Policyholder and Actual Driver
Date of Accident 12/04/2023 22:45 (SGT)
Exact Location of Accident Singapore
Additional Location Information 91 DESKER RD (PARKING LOT 19)
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SNG1790T

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LIM YI SHENG
NRIC No S9714251C
Email Address daniellysx1@gmail.com
Mobile Phone No (Phone) +65-86089596
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer BMW
Model 325I COUPE XL
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 2497

INSURANCE COMPANY

Name of Insurance Company Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number SP2002599849-01

DRIVER


Name of Driver LIM YI SHENG
NRIC No S9714251C
Date Of Birth 06/05/1997
Occupation Indoor

Describe Circumstance of the Accident

**** NOTE: PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14 DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.**

(☒) Claim Own Policy () Claim Third party () Reporting Only
() Claim OD/ TP at other workshop ()

Sketch Plan

Shops Lot		Shops Lot	A - SNG17907 X - Fire Location = 91 Desker Road (Parking lot no. 19)
-----------	---	-----------	---


Statement refer to Police Report A/20230413/7022

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time

 13/4/23

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

(43)