

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)

176 Sin Ming Drive #04-06, Sin Ming Autocare

Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2002599849-01	Date of Loss:	12/04/2023
Vehicle Reg. No.:	SNG1790T	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM YI SHENG	Contact No:	+6586089596
Driver:	LIM YI SHENG		
Make/Model:	BMW 325I, 2.5 COUPE XL (A)	Vehicle Reg. Date:	28/10/2009
Vehicle Colour:	White		
Engine No:	11097238N52B25AF	Chassis No:	WBAWB32050PV54013
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	30 <i>21 days</i>		
Present Location:	DING AUTO PTE LTD (HQ)		

*Not withain
L1Pm &
Ex TRA*

COST OF CLAIMS

	Amount
Parts	101,579.50
Miscellaneous Items	550.00
Labour	5,880.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	108,009.50
+ GST 8.00% (\$\$)	8,640.76
Nett Amount (\$\$)	116,650.26

This claim is handled by: HENRY LEE YOON SANG

Generated using Merlmen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Apr 2023)
 Parts: M1-COUPE BMW 325i 2.5 COUPE XL (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ding Auto Pte Ltd/SNG1790T/21/04/2023 17:33
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

'B' Bury

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount		
1	1		*FRONT WINDSCREEN - GLASS	B	0.00	0.00	*1,180.00 F	✓
2	1		*FRONT WINDSCREEN GLASS MOULDING	L	0.00	0.00	*120.00 F	✓
3	1		*DASHBOARD CPL	5	0.00	0.00	*5,200.00 F	✓
4	1		*AIRBAG - DRIVER	5	0.00	0.00	*1,950.00 F	✓
5	1		*AIRBAG - PASSENGER	5	0.00	0.00	*1,850.00 F	✓
6	1		*AIRBAG - ECU	5	0.00	0.00	*1,600.00 F	✓
7	1		*SEAT BELT ASSY RH		0.00	0.00	*540.00 F	7
8	1		*SEAT BELT ASSY LH		0.00	0.00	*540.00 F	7
9	1		*STEERING WHEEL CPL		0.00	0.00	*1,800.00 F	7
10	1		*STEERING WHEEL COVER		0.00	0.00	*390.00 F	7
11	1		*STEERING COLUMN WITH SWITCHES CPL		0.00	0.00	*1,050.00 F	7
12	1		*LAMP SWITCH CPL		0.00	0.00	*395.00 F	7
13	1		*DASHBOARD METER CPL	B	0.00	0.00	*2,550.00 F	✓
14	1		*DASHBOARD AIR VENT FULL SYSTEM CPL	B	0.00	0.00	*1,850.00 F	✓
15	1		*DASHBOARD LOWER GARNISH RH		0.00	0.00	*250.00 F	7
16	1		*DASHBOARD LOWER GARNISH LH		0.00	0.00	*200.00 F	7
17	1		*DASHBOARD DRAWER PANEL	B	0.00	0.00	*950.00 F	✓
18	1		*AIR BLOWER CPL	B	0.00	0.00	*980.00 F	✓
19	1		*HEATER BLOWER CPL	A	0.00	0.00	*1,080.00 F	✓
20	1		*AIR COND CONTROLLER SWITCH PANEL CPL	B	0.00	0.00	*2,480.00 F	✓
21	1		*AIR OUTLET VENT RH	5m	0.00	0.00	*300.00 F	X
22	1		*AIR OUTLET VENT LH	B	0.00	0.00	*300.00 F	✓
23	1		*AIR OUTLET CTR VENT		0.00	0.00	*350.00 F	7
24	1		*RADIO SYSTEM CPL	B	0.00	0.00	*2,850.00 F	506m
25	1		*GEAR KNOB SYSTEM CPL	B	0.00	0.00	*320.00 F	✓
26	1		*GEAR KNOB COVER	B	0.00	0.00	*280.00 F	✓
27	1		*GEAR CONSOLE PANEL CPL	B	0.00	0.00	*750.00 F	✓
28	1		*REAR CTR CONSOLE PANEL WITH ARM REST CPL	B	0.00	0.00	*1,250.00 F	✓
29	1		*CTR CONSOLE POWER WINDOW SWITCH X2		0.00	0.00	*360.00 F	7
30	1		*HAND BRAKE KIT CPL		0.00	0.00	*700.00 F	7
31	1		*DOOR INNER TRIM RH		0.00	0.00	*2,600.00 F	7
32	1		*DOOR INNER TRIM LH		0.00	0.00	*2,600.00 F	7
33	1		*DOOR WINDOW SWITCH PANEL RH	B	0.00	0.00	*945.00 F	X
34	1		*DOOR WINDOW SWITCH PANEL LH	5m	0.00	0.00	*945.00 F	7
35	1		*HEADLINING CPL		0.00	0.00	*2,250.00 F	2
36	1		*HEADLINING AIRBAG RH	B	0.00	0.00	*950.00 F	7
37	1		*HEADLINING AIRBAG LH		0.00	0.00	*950.00 F	7
38	1		*REAR VIEW MIRROR WITH DIM LAMP CPL	B	0.00	0.00	*1,000.00 F	✓
39	1		*SUN VISOR RH	B	0.00	0.00	*300.00 F	✓
40	1		*SUN VISOR LH	B	0.00	0.00	*300.00 F	✓
41	1		*SUN VISOR LH	B	0.00	0.00	*300.00 F	✓
42	1		*HEADLINING - CTR DIM LAMP CPL	B	0.00	0.00	*300.00 F	✓
43	1		*HEADLINING - HANDLE X 4	B	0.00	0.00	*320.00 F	✓
44	1		*FRONT SIDE TRIM RH	B	0.00	0.00	*600.00 F	✓
45	1		*FRONT SIDE TRIM LH		0.00	0.00	*200.00 F	7
46	1		*CTR UPPER TRIM RH	B	0.00	0.00	*200.00 F	7
47	1		*CTR UPPER TRIM LH		0.00	0.00	*220.00 F	7
				B	0.00	0.00	*220.00 F	7

48	1	*CTR LOWER TRIM RH	0.00	0.00	*220.00 F	X
49	1	*CTR LOWER TRIM LH	0.00	0.00	*220.00 F	✓
50	1	*REAR UPPER TRIM RH	0.00	0.00	*250.00 F	7
51	1	*REAR UPPER TRIM LH	0.00	0.00	*250.00 F	7
52	1	*FRONT SEAT CPL RH	0.00	0.00	*5,680.00 F	7
53	1	*FRONT SEAT CPL LH	0.00	0.00	*5,680.00 F	7
54	1	*REAR SEAT CPL	0.00	0.00	*7,800.00 F	7
55	1	*FLOOR CARPET CPL	0.00	0.00	*880.00 F	7
56	1	*REAR SIDE ARM TRIM RH	0.00	0.00	*400.00 F	7
57	1	*REAR SIDE ARM TRIM LH	0.00	0.00	*400.00 F	7
58	1	*REAR UPPER SPEAKER BOARD PANEL	0.00	0.00	*900.00 F	7
59	1	*REAR SPEAKER X2	0.00	0.00	*1,400.00 F	7
60	1	*DOOR SPEAKER X2	0.00	0.00	*1,600.00 F	7
61	1	*DASHBOARD TWEETER SPEAKER X2	0.00	0.00	*500.00 F	7
62	1	*INTERIOR HARNESS WIRE CPL	0.00	0.00	*3,200.00 F	✓
63	1	*DASHBOARD HARNESS WIRE CPL	0.00	0.00	*5,250.00 F	✓
64	1	*HEADLINING HARNESS WIRE CPL	0.00	0.00	*2,250.00 F	✓
65	1	*FUSE HOUSING CPL	0.00	0.00	*2,200.00 F	7
66	1	*ENGINE ECU	0.00	0.00	*3,950.00 F	✓

F=Franchise part.

Sub Total (S\$)	92,345.00
+ Margin on L,N Items 10.00% (S\$)	9,234.50
Total Parts (S\$)	101,579.50

Ding Auto Pte Ltd/SNG1790T/21/04/2023 17:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

Amount

1 1 ENGINE ECU - DIAGNOSIS/RE-PROGRAMMING

550.00

Sub Total (S\$)

550.00

Estimates on Labour

No Particulars

Labour Items

Lab.Type

Amount

1 REMOVE, CLEANING & RESTORATION - INTERIOR DAMAGED COMPONENTS

New

2,000.00

2 REMOVE & REFIT - DASHBOARD COMPONENTS

New

450.00

3 REMOVE & REFIT - HEADLINING COMPONENTS

New

450.00

4 REMOVE & REFIT - SEAT BELT COMPONENTS

New

350.00

5 REMOVE & REFIT - FRONT & REAR SEAT CUSHION COMPONENTS

New

350.00

6 REMOVE & REFIT - DOORS INNER TRIM & COMPONENTS

New

350.00

7 REMOVE & REFIT - INTERIOR FULL HARNESS WIRING

New

350.00

8 REMOVE & REFIT - INTERIOR SIDE & PILLAR TRIM/PANEL COMPONENTS

New

350.00

9 REMOVE & REFIT - FLOOR CARPET, CONSOLE & COMPONENTS

New

350.00

10 REMOVE & REFIT - FRONT WINDSCREEN GLASS & MOULDING

New

180.00

11 CHECKING & TEST WIRING - INTERIOR ELECTRICAL & ELECTRONIC GADGET SYSTEM COMPONENTS

New

350.00

12 CHECKING, CLEANING & TESTING - AIR COND COMPONENTS

New

350.00

Gross Labour Cost (S\$)

5,880.00

Ding Auto Pte Ltd/SNG1790T/21/04/2023 17:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >