

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
SALLY ONG XIU JIN BLK 417 HOUGANG AVENUE 8 #03-972 SINGAPORE 530417 Contact No	Cust No/Name	KCV19331/SALLY ONG XIU JIN
	Reg No/Reg Date	SNC3631C / 15/10/202
	Date In/Mileage	/ 0
	Chassis No	GF7W0701522
	Engine No	4J11A35933
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT (CLASSIC
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV19331	CRDVCH	20/04/2023/ 19:02		442 / CocoLu	33112			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								7680.00
RENEW REAR BUMPER, TAILGATE, REAR END PANEL, REAR LAMP HOUSING RH&LH								
REAR FENDER RH,REPAIR REAR FENDER LH,REAR COMPARTMENT, REAR CHASSIS								5500.00
E PNT98000								
SPRAY PAINT FOR REAR BUMPER, TAILGATE, REAR END PANEL,REAR COMPARTMENT								
REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH, REAR CHASSIS RH & LH								360.00
E PNT88000								
REMOVE & INSTALL REAR WINDSCREEN								80.00
M SUNDRY								
SEALANT FOR REAR WINDSCREEN								400.00
E PNT88000								
REMOVE & INSTALL TAILGATE TRIMS & REAR COMPARTMENT TRIMS								100.00
E PNT88000								
REMOVE & INSTALL PARKING SENSOR								50.00
M SUNDRY								
REAR NUMBER PLATE WITH FRAME								50.00
M SUNDRY								
C&C LOGO								150.00
M SUNDRY								
APPLY SEALANT FOR ACCIDENT PORTION								280.00
M SUNDRY								
SUPPLY PARKING SENSOR								500.00
E PNT88000								
TO STRAIGHTEN REAR CHASSIS								220.00
E PNT88000								
REMOVE & INSTALL QUATER GLASS								60.00
M SUNDRY								
APPLY SEALANT FOR QUATER GLASS								300.00
E PNT88000								
REMOVE & INSTALL REAR FENDER TRIMS AND SEATS								20.00
M SUNDRY								
Sundry								50.00
E PNT88000								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
SALLY ONG XIU JIN BLK 417 HOUGANG AVENUE 8 #03-972 SINGAPORE 530417 Contact No	Cust No/Name	KCV19331/SALLY ONG XIU JIN
	Reg No/Reg Date	SNC3631C / 15/10/202
	Date In/Mileage	/ 0
	Chassis No	GF7W0701522
	Engine No	4J11A35933
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT (CLASSIC
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KCV19331	CRDVCH	20/04/2023/ 19:02		442 / CocoLu	33112		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
CONDUCT WATER LEAKING TEST							
M	FACE,RR BUMPER			1.00	857.00	00.00	857.00
M	EXTENSION,RR BUMPER			1.00	509.00	00.00	509.00
M	BRKT,R/BMPR FACE SIDE,RH			1.00	20.00	00.00	20.00
M	BRKT,R/BMPR FACE SIDE,LH			1.00	20.00	00.00	20.00
M	REINFORCEMENT,RR BUMPER,LH			1.00	97.00	00.00	97.00
M	REINFORCEMENT,RR BUMPER,RH			1.00	97.00	00.00	97.00
M	MOULDING,RR BUMPER,RH			1.00	91.00	00.00	91.00
M	MOULDING,RR BUMPER,LH			1.00	91.00	00.00	91.00
M	MOULDING,RR WHEEL ARCH,RH			1.00	173.00	00.00	173.00
M	MOULDING,RR WHEEL ARCH,LH			1.00	173.00	00.00	173.00
M	PANEL ASSY,TAILGATE			1.00	1025.00	00.00	1025.00
M	GARNISH,TAILGATE			1.00	512.00	00.00	512.00
M	W/STRIP,TAILGATE OPENING			1.00	220.00	00.00	220.00
M	GLASS,TAILGATE WINDOW			1.00	695.00	00.00	695.00
M	STOPPER,WINDSHIELD GLASS			1.00	4.00	00.00	4.00
M	DAM,TAILGATE,LWR			1.00	25.00	00.00	25.00
P	FASTENER,WINDSHIELD			4.00	8.00	00.00	32.00
M	DAM,TAILGATE,UPR			1.00	13.00	00.00	13.00
M	LATCH,TAILGATE			1.00	229.00	00.00	229.00
M	STRIKER,TAILGATE LATCH			1.00	21.00	00.00	21.00
M	TRIM,TAILGATE			1.00	339.00	00.00	339.00
M	HANDLE,TAILGATE PULL			1.00	18.00	00.00	18.00
M	PANEL,RR END			1.00	336.00	00.00	336.00
M	PANEL,RR END,INR RH			1.00	150.00	00.00	150.00
M	PANEL,RR END,INR LH			1.00	150.00	00.00	150.00
M	PANEL,QTR,OTR RH			1.00	1011.00	00.00	1011.00
M	EXTN,QTR PANEL,RR LWR RH			1.00	81.00	00.00	81.00
M	EXTN,QTR PANEL,RR LWR LH			1.00	81.00	00.00	81.00
M	EXTENSION,QTR PANEL,OTR RH			1.00	146.00	00.00	146.00
M	EXTENSION,QTR PANEL,OTR LH			1.00	146.00	00.00	146.00
M	GLASS,QTR WINDOW,RH			1.00	475.00	00.00	475.00
M	SHIELD,RR WHEEL,FR RH			1.00	132.00	00.00	132.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
SALLY ONG XIU JIN BLK 417 HOUGANG AVENUE 8 #03-972 SINGAPORE 530417 Contact No	Cust No/Name	KCV19331/SALLY ONG XIU JIN
	Reg No/Reg Date	SNC3631C / 15/10/202
	Date In/Mileage	/ 0
	Chassis No	GF7W0701522
	Engine No	4J11A35933
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT (CLASSIC
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KCV19331	CRDVCH	20/04/2023/ 19:02		442 / CocoLu	33112		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	SHIELD,RR WHEEL,FR LH			1.00	132.00	00.00	132.00
M	SHIELD,RR WHEEL,RR RH			1.00	27.00	00.00	27.00
M	SHIELD,RR WHEEL,RR LH			1.00	27.00	00.00	27.00
M	MARK,OUTLANDER			1.00	118.00	00.00	118.00
M	TRIM,RR END			1.00	116.00	00.00	116.00
M	BOX,CARGO FLOOR			1.00	211.00	00.00	211.00
M	TRIM ASSY,QTR,LWR RH			1.00	414.00	00.00	414.00
M	TRIM ASSY,QTR,LWR LH			1.00	414.00	00.00	414.00
M	LAMP ASSY,COMB,RR LH			1.00	628.00	00.00	628.00
M	LAMP ASSY,COMB,RR RH			1.00	628.00	00.00	628.00
M	LAMP ASSY,TAIL,LH			1.00	625.00	00.00	625.00
M	LAMP ASSY,TAIL,RH			1.00	625.00	00.00	625.00
M	LAMP ASSY,LICENSE PLATE			1.00	35.00	00.00	35.00
M	REFLECTOR,TAIL LAMP,RH			1.00	103.00	00.00	103.00
M	REFLECTOR,TAIL LAMP,LH			1.00	103.00	00.00	103.00
M	BUZZER,KEYLESS OPERATIO,RR			1.00	94.00	00.00	94.00
M	ANT,KEYLESS OPERATION,RR			1.00	99.00	00.00	99.00
M	HARNESS,RR BUMPER			1.00	87.00	00.00	87.00

Confirm & accepted by

Nett	28,255.00
8% GST on	2260.40
Total Payable	30,515.40

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.