



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
Bodyshop Retail Cash Sales Pandan TCBC Toyota Bodyshop Retail Cash Sales Pandan TCBC Toyota			c0110038 / PBPREG		M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No. 0				
			Document Date 24/04/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZVW50R	AHXEBW Q1	09/01/2017	SLK1784P	0	21427	75/DS/SLK1784P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FUX03539643		2ZRR974660	00	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SKT1889K ACC DATE : 23/04/23 DRIVE IN: 24/04/23 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00	
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST				198.00	
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
4	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN AND PANEL BEAT ACC AFF AREA				2376.00	
5	B	BP-RES2 RESPRAY ACC AFF AREA				1968.00	
6	1	U52119-47962 COVER, FR BUMPER	1.00	622.20	10.00	559.98	
7	2	U52161-16010 PIECE, RR BUMPER	10.00	5.40	10.00	48.60	
8	3	U52116-47050 SUPPORT, FR BUMPER	1.00	95.70	10.00	86.13	
9	4	U53112-47240 GRILLE, RADIATOR,	1.00	204.20	10.00	183.78	
10	5	U81185-47691 UNIT, HEADLAMP	1.00	3167.20	10.00	2850.48	
11	6	U81220-47020 LAMP ASSY, FOG, LH	1.00	1143.60	10.00	1029.24	
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							9,598.21
			Please acknowledge receipt of vehicle				GST 8.00%
					Parts 4,758.21		767.86
					Labour 4,840.00		
					Sublet 0.00		
					Lubrication/Fluid 0.00		Less 0.00
					Others 0.00		Amount Due 10,366.07

Customer Copy