

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: **AIG Asia Pacific Insurance Pte. Ltd.**  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120From: **LKK Auto Consultants Pte Ltd**  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chew, Yvonne

Date: 24 Apr 2023

**Preliminary Advice**

Vehicle No	: SDX6690U	Accident Date	: 14/04/2023
Make	: AUDI Q5 SPORT	Policy No.	: 1800143031
Assignment Date	: 24/04/2023	Excess	: S\$0.00
Date of Inspection	: 19/4/2023	Est. Duration of Repair	: 3
Inspection At	: PREMIUM AUTOMOBILES PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	63,343.00
Revised Amount	:S\$	10,060.00
Check Items (Estimated)	:S\$	3,506.00
Total	:S\$	13,566.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	148,000.00
COE / PARF Rebate	:S\$	56,900.00
Salvage Value	:S\$	
Margin for Repair	:S\$	91,100.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .