



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0384/2023/EQ
DATE : 18-Apr-23
WIP : 16961

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/4/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS NURHASLINDA BINTE RAMLI
ADDRESS : BLK 18 MARINE TERRACE
#03-112
SINGAPORE 440018
TELEPHONE : HP +65 91000469
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800143031-03
VEHICLE NO : **SDX 6690 U**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 30/11/2018
ENGINE NO : DAX 046620
CHASSIS NO : WAUZZZFY7J2238865
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Apr-23
PLACE OF ACCIDENT : CHOA CHU KANG WAY

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDX 6690 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	X
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,600.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00	500
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS.	\$	4,800.00	550
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 13,472.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDX 6690 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>dehd</i>	1	\$ 3,314.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 357.00	+
3	FRONT BUMPER SECURING STRIP - LH / RH ?	2	\$ 90.00	?
4	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$ 266.00	+
5	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 170.00	+
6	FRONT BUMPER SPOILER <i>new</i>	1	\$ 900.00	+
7	FRONT BUMPER UNDERRUN BAR ?	1	\$ 614.00	?
8	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 260.00	+
9	RADIATOR GRILLE <i>new</i>	1	\$ 4,155.00	✓
10	"QUATTRO" INSCRIPTION <i>new</i>	1	\$ 118.00	✓
11	RADITOR GRILLE STRIKER PLATE ?	1	\$ 288.00	?
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>LH cut</i>	2	\$ 1,382.00	<i>691</i>
13	FRONT BUMPER END CAP - LH / RH <i>new</i>	2	\$ 218.00	+
14	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 210.00	?
15	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$ 1,104.00	?
16	FRONT BUMPER BRACKET - LH / RH <i>new</i> ?	2	\$ 608.00	?
17	FRONT BUMPER GUIDE SECTION - LH / RH ?	2	\$ 92.00	?
18	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 152.00	+
19	CAUTION SIGN STICKER <i>new</i>	1	\$ 17.00	+
20	AIR CONDITIONER STICKER <i>new</i>	1	\$ 24.00	+
SUB TOTAL SPARE PARTS			\$ 14,339.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDX 6690 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR - OUTER <i>3 new</i>	2	\$ 543.00	+
22	FRONT PARKING AID SENSOR - INNER <i>3 new</i>	2	\$ 543.00	+
23	FRONT PARKING AID SEAL RING <i>3</i>	4	\$ 11.00	x
24	FRONT BUMPER WIRING SET <i>3 new</i>	1	\$ 457.00	x
25	HORN LOW TONE - LH <i>3 new</i>	1	\$ 220.00	x
26	HORN HIGH TONE - RH <i>3 new</i>	1	\$ 220.00	x
27	FRONT FENDER - LH <i>3 new</i>	1	\$ 1,607.00	x
28	FRONT FENDER BRACE - LH <i>3 new</i>	1	\$ 266.00	+
29	FRONT FENDER BRACKET - LH <i>3 new</i>	1	\$ 21.00	+
30	FRONT FENDER CLOSURE PANEL - LH <i>3 new</i>	1	\$ 37.00	+
31	FRONT FENDER PANEL COVER - LH / RH <i>3 new</i>	2	\$ 94.00	+
32	BONNET <i>3 new</i>	1	\$ 4,359.00	+
33	BONNET IMPACT PROTECTION - LH / RH / CENTER <i>3 new</i>	3	\$ 101.00	+
34	BONNET RELEASE ELEMENT <i>3 new</i>	1	\$ 69.00	+
35	BONNET RELEASE LEVER <i>3 new</i>	1	\$ 17.00	+
36	HEADLIGHT MOUNTING - LH / RH <i>3 new</i>	2	\$ 280.00	+
37	HEADLIGHT - LH / RH <i>3 new</i>	2	\$ 18,452.00	+
38	LIFT CYLINDER - LH / RH <i>3 new</i>	2	\$ 324.00	x
39	LIFT CYLINDER HOSE <i>3 new</i>	1	\$ 150.00	+
40	LOCK CARRIER <i>3 new</i>	1	\$ 1,646.00	+
SUB TOTAL SPARE PARTS			\$ 29,417.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDX 6690 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	OUTSIDE TEMPERATURE SENSOR BRACKET <i>Ne n</i>	1	\$	20.00	<i>+</i>
42	A/C CONDENSER <i>Ne n</i>	1	\$	709.00	<i>+</i>
43	A/C CONDENSER REFRIGERANT LINE <i>Ne n</i>	1	\$	347.00	<i>+</i>
44	A/C CONDENSER REFRIGERANT LINE <i>Ne n</i>	1	\$	359.00	<i>+</i>
45	CHARGE AIR COOLER <i>Ne n</i>	1	\$	964.00	<i>+</i>
46	READY-MIX COOLANT <i>Ne n</i>	6	\$	326.00	<i>+</i>
47	RADIATOR AIR GUIDE - UPPER <i>Ne n</i>	1	\$	61.00	<i>+</i>
48	RADIATOR AIR GUIDE - CENTER <i>Ne n</i>	1	\$	61.00	<i>+</i>
49	RADIATOR AIR GUIDE - LOWER <i>Ne n</i>	1	\$	61.00	<i>+</i>
50	RADIATOR AIR GUIDE - LH / RH <i>Ne n</i>	2	\$	140.00	<i>+</i>
51	RADIATOR LOUVRE <i>Ne n</i>	1	\$	623.00	<i>+</i>
52	RADIATOR COVER CAP <i>Ne n</i>	1	\$	7.00	<i>+</i>
53	FRONT WHEEL SPOILER - LH <i>Ne n</i>	1	\$	191.00	<i>+</i>
54	FRONT WHEEL SPOILER - RH <i>Ne n</i>	1	\$	182.00	<i>+</i>
55	FRONT WHEEL COVER - LH / RH <i>Ne n</i>	2	\$	1,504.00	<i>+</i>
56	FRONT NUMBER PLATE <i>Bent</i>	S/N	\$	60.00	<i>✓</i>
57	SUNDRIES <i>?</i>		\$	500.00	<i>?</i>
TOTAL SPARE PARTS		:	\$	49,871.00	
TOTAL LABOUR CHARGES		:	\$	13,472.00	
GRAND TOTAL		:	\$	63,343.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lij*
SURVEYED DATE : *19/04/23.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOON
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT