

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 25 Apr 2023

Preliminary Advice

Vehicle No	: SJZ4911P	Accident Date	: 15/04/2023
Make	: KIA SORENTO	Policy No.	: SP2004547943-01
Assignment Date	: 24/04/2023	Excess	: S\$600.00
Date of Inspection	: 24/04/2023	Est. Duration of Repair	: 4
Inspection At	: CYCLE & CARRIAGE KIA PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,129.00
Revised Amount	:S\$	9,783.00
Check Items (Estimated)	:S\$	620.00
Total	:S\$	10,403.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	212,000.00
COE / PARF Rebate	:S\$	108,265.00
Salvage Value	:S\$	
Margin for Repair	:S\$	103,735.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :the vehicle repair on part by part basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.