



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Wanneck Hans-Peter	Cust No/Name LCV18915/Wanneck Hans-Peter
218 Loyang Avenue	Reg No/Reg Date SJZ4911P / 06/02/202
#01-02	Date In/Mileage / 2267
Singapore 509066	Chassis No KNARH81GMP5139881
Contact No Mobile: 6596571772	Engine No G4FTNH040713
	Make/Model KIA/SORENTO 1.6 A SR G918
	Colour/Trim B4U / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	20/04/2023/ 17:28	BLE	261 / Edwin Caina	12257			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	GARNISH - FR DR RH	missing			1.00	117.00	00.00	117.00
M	GARNISH ASSY-FNDR SIDE, RH ?	NEC			1.00	76.00	00.00	76.00
M	GARNISH ASSY-FR DR SIDE RH	missing			1.00	177.00	00.00	177.00
M	GARNISH ASSY-RR DR SIDE, RH	nn			1.00	210.00	00.00	210.00
M	MOULDING ASSY-SIDE SILL, RH	? X nn			1.00	129.00	00.00	129.00
M	MIRROR ASSY-OUTSIDE RR VIEW, RH	sur			1.00	1559.00	00.00	1559.00
M	PANEL ASSY-FRONT DOOR, RH	bul			1.00	1411.00	00.00	1411.00
M	HINGE ASSY-FRONT DOOR, RH ?	X nn			2.00	32.00	00.00	64.00
M	MOULDING ASSY-FRT DR FRAME, RH	nn			1.00	46.00	00.00	46.00
M	GARNISH ASSY-DR FRAME RH	nn			1.00	48.00	00.00	48.00
M	W/STRIP ASSY-FR DR BELT O/S RH ?	X nn			1.00	90.00	00.00	90.00
M	W/STRIP ASSY-FR DR SIDE RH ?	X nn			1.00	75.00	00.00	75.00
M	HANDLE ASSY-DOOR OUTSIDE, RH	nn			1.00	136.00	00.00	136.00
M	COVER-FR DR O/S HDL RH	X nn			1.00	15.00	00.00	15.00
M	PAD-FR DR O/S HDL COVER, RH ?	X nn			1.00	5.00	00.00	5.00
M	BASE ASSY-FR DR O/S HANDLE RH ?	X nn			1.00	76.00	00.00	76.00
M	CHECKER ASSY-FRONT DOOR, RH ?	MIS			1.00	50.00	00.00	50.00
M	COVER-DR CHECKER ?	X nn			1.00	7.00	00.00	7.00

SURVEYOR NAME: \_\_\_\_\_

SURVEYOR SIGNATURE: \_\_\_\_\_

DATE: \_\_\_\_\_

REMARKS: \_\_\_\_\_

\_\_\_\_\_

SURVEYOR NAME: \_\_\_\_\_

SURVEYOR SIGNATURE: \_\_\_\_\_

DATE: \_\_\_\_\_

REMARKS: \_\_\_\_\_

Confirm &amp; accepted by

Nett 13,129.00  
 8% GST on 13129.00 1050.32  
**Total Payable 14,179.32**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Wanneck Hans-Peter  218 Loyang Avenue #01-02 Singapore 509066  Contact No Mobile: 6596571772	Cust No/Name	LCV18915/Wanneck Hans-Peter
	Reg No/Reg Date	SJZ4911P / 06/02/202
	Date In/Mileage	/ 2267
	Chassis No	KNARH81GMP5139881
	Engine No	G4FTNH040713
	Make/Model	KIA/SORENTO 1.6 A SR G918
	Colour/Trim	B4U / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	20/04/2023/ 17:28	BLE	261 / Edwin Caina	12257		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M SUNDRY							
W/STRIP-DR BODY SIDE RH ? nn							
82120P2000							
M SUNDRY							
W/STRIP-FR DR BELT I/S RH ? nn							
82240P2000							
M SUNDRY							
PAD-FR DR O/S HDL HINGE,RH? nn							
82663S9000							2560 ✓
E PNT88000							3840.00
RENEW RHF FENDER & RHF DOOR							
REPAIR RHF DOOR PILLAR & RHR DOOR							
E PNT98000							1925 ✓
RESPRAY RHF FENDER , RHF DOOR , RHF DOOR PILLAR ,							2750.00
RHR DOOR & RH WINGMIRROR✓							
E PNT88000							Nett 280.00
REMOVE & REFIT RHF DOOR COMPONENT							
E PNT88000							Nett 280.00
REMOVE & REFIT RHF TRIM & CARPET TO FACILATATE REPAIR							
A 54900099							Nett 100.00
CHECK WIRING ELECTRICAL SYSTEM							
A 10028901							Nett 280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M SUNDRY							100 ✓
APPLY ANTI CORROSION ON AFFECTED AREAS							250.00
M SUNDRY							80 ✓
SUPPLY BODY PNL SEALANT							120.00
M SUNDRY							30 ✓
Sundries							100.00
M PANEL ASSY-FENDER,RH Dent				1.00	702.00	00.00	702.00
M INSULATOR-FENDER UPPER,RH? X nn				1.00	17.00	00.00	17.00
M INSULATOR-FENDER RH ? X nn				1.00	31.00	00.00	31.00
M GARNISH-FENDER SIDE UPR,RH Scr				1.00	88.00	00.00	88.00

Confirm & accepted by

4 days OP EXPRESS: \$600H  
 PIP 1rfan 24/4/23 4pm  
 1rfan@LKK Auto-com  
 90097659

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.