

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:jlperfectautowork@gmail.com



DATE : 24.04.2023

TO : ALLIANZ MOTOR CLAIMS DEPTS
VEHICLE NO : SKV5767S
MODEL : TOYOTA COROLLA ALTIS
DATE OF ACCIDENT : 23.04.2023
TIME OF ACCIDENT : 12:40 HOURS

MR053REH104541322

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Delcd</i>	1	\$ 495.00	\$ 495.00
2	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 147.00	\$ 147.00
3	FRONT BUMPER FOG LAMP LH <i>new</i>	1	\$ 320.00	\$ 320.00
4	FRONT BUMPER FOG LAMP GARNISH LH <i>new</i>	1	\$ 75.00	\$ 75.00
5	FRONT BUMPER SIDE RETAINER <i>Lt Dnd</i>	2	\$ 60.00	\$ 120.00
6	FRONT BUMPER REINFORCEMENT SPONGE <i>new</i>	1	\$ 123.00	\$ 123.00
7	FRONT CENTER GRILLE <i>new</i>	1	\$ 349.00	\$ 349.00
8	FRONT CENTER GRILLE LOGO <i>new</i>	1	\$ 85.00	\$ 85.00
9	RESONATOR BOX <i>and C</i>	1	\$ 510.00	\$ 510.00
10	RESONATOR AIR DUCT <i>new</i>	1	\$ 195.00	\$ 195.00
11	HEADLAMP <i>Cut LH</i>	2	\$ 980.00 <i>2348.50</i>	\$ 1,960.00 <i>2348.50</i>
12	HEADLAMP LOWER BRACKET LH <i>new</i>	1	\$ 95.00	\$ 95.00
13	FRONT FENDER LH <i>Disturbed</i>	1	\$ 782.00	\$ 782.00
14	FRONT FENDER INNER GARNISH LH <i>new</i>	1	\$ 120.00	\$ 120.00
15	FRONT FENDER EMBLEM (VVTI) <i>new</i>	1	\$ 55.00	\$ 55.00
16	FRONT FENDER INNER COWLING LH <i>new</i>	1	\$ 210.00	\$ 210.00
17	FRONT FENDER UPPER CORNER GARNISH LH <i>new</i>	1	\$ 85.00	\$ 85.00
18	FRONT FENDER SUPPORT BRACKET <i>Bent</i>	1	\$ 90.00	\$ 90.00
19	FRONT CROSS MEMBER <i>new</i>	1	\$ 1,670.00	\$ 1,670.00
20	FRONT KNUCKLE ARM LH <i>Bnd</i>	1	\$ 585.00	\$ 585.00
21	FRONT LOWER ARM LH <i>Bent</i>	1	\$ 640.00	\$ 640.00
22	FRONT KNUCKLE ARM BEARING LH <i>Bnd</i>	1	\$ 280.00	\$ 280.00

1
+
+
+
60
+
+
+
144
+
2348.50
+
+
+
+
+
+
+
+
543

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKV5767S**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 23.04.2023
 TIME OF ACCIDENT : 12:40 HOURS

23	FRONT STABILIZER BAR LINKAGE LH <i>new</i>	1	\$ 195.00	\$ 195.00	<i>+</i>
24	FRONT DRIVESHAFT LH <i>new</i>	1	\$ 1,635.00	\$ 1,635.00	<i>+</i>
25	FRONT SHOCK ABSORBER LH <i>new</i>	1	\$ 405.00	\$ 405.00	<i>+</i>
26	FRONT STEERING RACK AND PINION <i>Best</i>	1	\$ 1,890.00	\$ 1,890.00	<i>✓ (62)</i>
27	FRONT ABS SENSOR LH <i>new</i>	1	\$ 460.00	\$ 460.00	<i>+</i>
28	FRONT WHEEL RIM LH <i>lit</i>	1	\$ 1,655.00	\$ 1,655.00	<i>880/sn</i>
29	FRONT DOOR VIEW MIRROR LH <i>new</i>	1	\$ 1,682.00	\$ 1,682.00	<i>+</i>
30	FRONT DOOR LH <i>Dented</i>	1	\$ 1,358.00	\$ 1,358.00	<i>✓ (275)</i>
31	FRONT DOOR BLACK STICKER LH <i>new</i>	1	\$ 87.00	\$ 87.00	<i>+</i>
32	FRONT DOOR OUTER MOULDING LH <i>new</i>	1	\$ 160.00	\$ 160.00	<i>+</i>
33	FRONT DOOR HINGE LH <i>2 for</i>	2	\$ 95.00	\$ 190.00	<i>+</i>
34	FRONT DOOR CHECKER LH <i>for</i>	1	\$ 155.00	\$ 155.00	<i>+</i>
35	FRONT DOOR WEATHER STRIP LH <i>for</i>	1	\$ 175.00	\$ 175.00	<i>+</i>
36	FRONT DOOR FRAME WEATHER STRIP LH <i>MT</i>	1	\$ 174.00	\$ 174.00	<i>+</i>
37	FRONT DOOR GLASS CHANNEL LH <i>new</i>	1	\$ 140.00	\$ 140.00	<i>+</i>
38	FRONT DOOR INNER LOCK LH <i>2 for</i>	1	\$ 480.00	\$ 480.00	<i>+</i>
39	FRONT DOOR LOCK CATCH LH <i>for</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
40	FRONT DOOR INNER TRIM BOARD LH <i>Cracked</i>	1	\$ 790.00	\$ 790.00	<i>✓ 645</i>
41	FRONT DOOR REGULATOR LH <i>new</i>	1	\$ 240.00	\$ 240.00	<i>+</i>
42	FRONT DOOR POWER WINDOW MOTOR LH <i>MT</i>	1	\$ 770.00	\$ 770.00	<i>+</i>
43	FRONT DOOR SPEAKER LH <i>new</i>	1	\$ 298.10	\$ 298.10	<i>+</i>
44	FRONT DOOR PILLAR LH <i>Repair</i>	1	\$ 1,108.00	\$ 1,108.00	<i>+</i>
45	FRONT WINDSCREEN MOULDING <i>new</i>	1	\$ 165.80	\$ 165.80	<i>+</i>

9220.50

6915.57

SN: 680

TOTAL PRICE \$ 23,233.90
 LESS 25% \$ 5,808.48
SUB TOTAL PRICE \$ 17,425.43

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER UNDER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
3	FRONT BUMPER FOG LAMP GARNISH CLIP LH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	FRONT WIPER GARNISH CLIP <i>new</i>	1	\$ 50.00	\$ 50.00
5	FRONT CENTER GRILLE CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKV5767S**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 23.04.2023
 TIME OF ACCIDENT : 12:40 HOURS

6	FRONT FENDER COWLING CLIPS (SET) <i>New</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
7	FRONT FENDER UPPER CORNER GARNISH CLIP LH (SET) <i>New</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
8	FRONT DOOR SEALANT LH <i>New</i>	1	\$ 120.00	\$ 120.00 <i>+</i>
9	FRONT DOOR INNER TRIM CLIP <i>New</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
10	FRONT WINDSCREEN SEALANT <i>3M</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
11	FRONT WINDSCREEN INNER SHIELD <i>3M</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
12	BRAKE OIL <i>3M</i>	1	\$ 30.00	\$ 30.00 <i>+</i>
13	FRONT WHEEL TYRE LH <i>3M</i>	1	\$ 580.00	\$ 580.00 <i>+</i>

30

TOTAL \$ 1,330.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>600</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 80.00	<i>30</i>
5	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	<i>60</i>
6	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	<i>X</i>
7	REMOVE AND REFIX DASHBOARD	\$ 350.00	<i>X</i>
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	<i>200</i>
9	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80</i>

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKV5767S**
MODEL : **TOYOTA COROLLA ALTIS**
DATE OF ACCIDENT : 23.04.2023
TIME OF ACCIDENT : 12:40 HOURS

10	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 300.00	120
11	RESET ABS LIGHT	\$ 350.00	X
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	4

TOTAL \$ 5,880.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 18,755.43
TOTAL LABOUR COST : \$ 5,880.00
TOTAL REPAIR COST : \$ 24,635.43

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 9435.37
w/s: 7550

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: