



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



CITROËN

Company Reg No. 200609327M
 GST Reg No. MR-5500111-X

ESTIMATE

Invoice Name & Address					Owner Name & Vehicle Info			
Mr Yoppy					/Mr Yoppy			
1 Tanah Merah Kechil Road					Reg No/Reg Date SMX6453G / 14/07/2016			
#03-02					Date In/Mileage / 0			
Singapore 466663					Chassis No VF73ABHZTGJ658025			
Contact No Mobile: 96285663					Engine No 10JBHD3051371			
					Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 CONFORT			
					Colour/Trim WPP BLANC BANQUISE / 8MF ONDULICE CLOTH			
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00073	Cash	21/04/2023/ 19:49	TLE	261 / Edwin Caina	20236			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW TAILGATE , TAILGATE LWR PNL , RR BUMPER & RR END PNL								1520 4560.00
E PNT98000 RESPRAY TAILGATE , TAILGATE LWR PNL , RR BUMPER & RR END PNL								1100 2750.00
E PNT88000 REMOVE & REFIT TAILGATE COMPONENT								Xm ? 380.00
E PNT88000 REMOVE & REFIT RR FLR BOARD , TRIM & CARPET								180 ? 380.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								100.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								380.00
E PNT88000 REMOVE & REFIT RR WS GLASS								Xm ? 380.00
M SUNDRY SUPPLY BODY PNL SEALANT								Xm ? 80.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING								80.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR								120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								Xm ? 180.00
M SUNDRY SUPPLY BODY PNL SEALANT								Xm ? 100.00
M SUNDRY SUPPLY C&C BADGE								? 80.00
M SUNDRY Sundries								20 ? 80.00
M REAR BUMPER					1.00	1634.00	0.00	1634.00
M BUMPER BRACKET					1.00	355.00	0.00	355.00
M BUMPER SKIRT					1.00	539.00	0.00	539.00
M BRACKET SET					1.00	233.00	0.00	233.00
M BRACKET SET LAT					1.00	233.00	0.00	233.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



CITROËN

ESTIMATE

Company Reg No. 200609327M
GST Reg No. MR-6500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Yoppy 1 Tanah Merah Kechil Road #03-02 Singapore 466663 Contact No Mobile: 96285663	Cust No/Name /Mr Yoppy Reg No/Reg Date SMX6453G / 14/07/2016 Date In/Mileage / 0 Chassis No VF73ABHZTGJ658025 Engine No 10JBHD3051371 Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 CONFORT Colour/Trim WPP BLANC BANQUISE / 8MF ONDULICE CLOTH

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	21/04/2023/ 19:49	TLE	261 / Edwin Caina	20236

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BUMPER BRACKET ? Xan	1.00	491.00	0.00	491.00
M STIFFENER LH ? Xan	1.00	220.00	0.00	220.00
M STIFFENER RH ? Xan	1.00	220.00	0.00	220.00
M LOW RR PAN FIX ? Xan	1.00	223.00	0.00	223.00
M SENSOR SUPPORT ? Xan	1.00	269.00	0.00	269.00
M REAR PANEL ASS ? Xan	1.00	884.00	0.00	884.00
M TAILGATE ? Xan	1.00	2988.00	0.00	2988.00
M TLGT EXT PANEL ? Xan	1.00	569.00	0.00	569.00
M WEATHERSTRIP ? Xan	1.00	212.00	0.00	212.00
M SPOILER LH ? Xan	1.00	231.00	0.00	231.00
M SPOILER RH ? Xan	1.00	231.00	0.00	231.00
M BADGE-C4 ? Xan	1.00	91.00	0.00	91.00
M BADGE-PICASSO ? Xan	1.00	91.00	0.00	91.00
M BADGE-LOGO ? Xan	1.00	114.00	0.00	114.00
M BADGE-BLUEHDI ? Xan	1.00	91.00	0.00	91.00
M TAIL-LIGHT LH COMPLEMENTAIRE ? Xan	1.00	199.00	0.00	199.00
M TAIL-LIGHT RH COMPLEMENTAIRE ? Xan	1.00	224.00	0.00	224.00
M SENSOR-CTR ? Xan	2.00	228.00	0.00	456.00
M SENSOR-OTR ? Xan	2.00	389.00	0.00	778.00

SURVEYOR NAME: *Pony - 4p 2001068*SURVEYOR SIGNATURE: *[Signature]*DATE: *09/05/23 @ 1530*REMARKS: *4 days + 2.6 days**Res before paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Confirm & accepted by

Parts	11,576.00
Labour	9,050.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/ Others	600.00
Total (w/o GST)	21,226.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

INSURANCE CO.: CHINA TAIPING

Supplementary Parts For Registration No.: SMX 6453 G

Parts
1 Bumper Bracket *de*

Cost (\$)
691.00 ✓

Total Parts 691.00

Labour
1 Repair rear end panel *m*
2 Respray rear end panel *m*

Cost (\$)
380.00 ✓
550.00 ✓

Total Labour 930.00

Taxable amount 1,621.00

8% GST 129.68

Grand total \$ 1,750.68

Thank You.

Yours faithfully

[Signature]
LOI AI TING
Senior Officer - Admin
CITROEN SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240