

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 17/04/2023
TP Veh Reg No: YQ8862R

Estimate No: EST2300156
Date: 18 Apr 2023

Veh Reg No: EW57G
Make/Model: TOYOTA COROLLA 1.6
Chasis No: MR053ZEC107104935
Reg. Date: 06/12/2005
Your Ref No: YQ8862R

Estimate Repair Cost to Vehicle No :EW57G

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price			
1	1 PC FRT DOOR LH	1,402.10	
2	1 PC FRT LH DOOR TOP MOULDING	178.60	
3	1 PC FRT LH DOOR KEY LOCK	96.70	
4	1 PC FRT LH DOOR KEY LOCK COVER	41.60	
5	1 PC FRT DOOR OUTER HANDLE LH	221.00	
6	1 PC FRT DOOR LH TAPE STICKER	55.80	
7	1 PC FRT DOOR PROTECTOR LH	73.30	
8	1 PC FRT DOOR PROTECTOR MOULDING LH	39.40	
9	1 PC FRT DOOR SIDE MIRROR LH	466.70	
10	1 PC FRT DOOR SIDE MIRROR COVER LH	58.30	
11	1 PC REAR DOOR LH	1,105.90	
12	1 PC REAR DOOR PROTECTOR LH	66.10	
13	1 PC REAR DOOR PROTECTOR MOULDING LH	32.70	
14	1 PC REAR DOOR TAPE STICKER LH	50.10	
15	1 PC REAR DOOR TOP MOULDING LH	166.90	
		4,055.20	
	Less 25%	1,013.80	3,041.45
Labour			
16	1 TO CHECK WIRING	50.00	
17	1 TO REMOVE AND REFIX FRT & REAR DOOR GLASS	200.00	
18	1 TO REMOVE AND REFIT FRT & REAR DOOR TRIM	200.00	
19	1 TO SPRAY PAINTING	1,000.00	
20	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	
		2,450.00	2,450.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 17/04/2023
TP Veh Reg No: YQ8862R

Estimate No: EST2300156
Date: 18 Apr 2023

Veh Reg No: **EW57G**
Make/Model: TOYOTA COROLLA 1.6
Chasis No: MR053ZEC107104935
Reg. Date: 06/12/2005
Your Ref No: YQ8862R

Estimate Repair Cost to Vehicle No :EW57G

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 5,491.45
		Add GST @ 8%	439.32
		Total Amount Payable	<u>S\$ 5,930.77</u>

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED THIRTY AND CENTS
SEVENTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE