

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/AIS23004213/Upr3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKB5163P

at Workshop m/s 7 Klee

of XE 4186K

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 6331k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 25 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKB5163P Yr Regn: 07/06/11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra c.c 1591

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 139335 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHDH41CMCU173331

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55-R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 22/04/23 D.O.I. 25/4/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S New & The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 22/11/13.

100 until 31-05-2026 L7A 13680

L/S 20% should be \$4300

inform MR Lee L/S \$4000 G.A?

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$))

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Email: Tklee0247@gmail.com

no of Fullwork
der
4/5 @ 4000
5 days
25 (4/2)

Vehicle Number: SKB5163P

Vehicle Model: HYUNDAI ELANTRA

PARTICULAR		AMOUNT	
QTY	LIST PRICE		SS
1	1 REAR BUMPER	Dis/To in 471.2	\$ 516.90
2	2 REAR BUMPER SIDE RETAINER - RH/LH @58.50	one / der	\$ 117.00
3	1 REAR BUMPER REINFORCEMENT	11	\$ 431.50 X
4	1 REAR FENDER - LH	body in	\$ 1,786.90
5	1 REAR FENDER AIR VENT	one	\$ 89.90
6	1 REAR FENDER INNER SHIELD	To in	\$ 126.20
7	1 REAR FENDER INNER PANEL	1	\$ 811.50 X
8	1 REAR TAILLAMP LH	one	\$ 586.90
9	1 REAR WINDSCREEN MOULDING	der	\$ 126.20
10	1 REAR HUB BEARING - LH	Daye	\$ 461.50
11	1 REAR SHOCK ABSORBER - LH	11	\$ 280.90 X
			\$ 5,335.40
		LESS 20%	\$ 1,067.08
			\$ 4,268.32

SPECIAL NETT ITEMS

1	(SET) REAR BUMPER CLIP	der	\$ 45.00
1	(SET) REAR BUMPER CLIP	Repull	\$ 280.00 X
1	(SET) REAR WINDSCREEN SEALANT	der	\$ 80.00 40
1	REAR SPORT WHEEL - LH	cut	\$ 550.00 450
1	REAR TYRE - LH	der	\$ 280.00 X
			\$ 1,235.00

LABOUR CHARGES

TO CHECK REAR ELECTRICAL WIRING	\$ 50.00	20
TO REMOVE AND REFIX REAR INNER TRIMS	\$ 120.00	80
TO REMOVE AND REFIX REAR WINDSCREEN	\$ 180.00	120
TO PERFORM COMPUTERISE 4 WHEEL ALIGHTMENT	\$ 120.00	60
TO REMOVE AND REPLACE REAR UNDERCARRIAGE	\$ 250.00	120
TO TUFF KOTE	\$ 80.00	30
TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	\$ 900.00	600
TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	\$ 1,050.00	800
		\$ 2,750.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 8,253.32

7- 3765.8
202
3012.64
535
1830
5377.64
4033

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: