

ASSIGNMENT

COE-2023/Dec

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBC 8308Xat Workshop m/s CHENH AUTOof S. SMOLEST #01-60Insured: LIP

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: 10K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBC 8308X Yr Regn: 2013 / Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA DYNA 150 M c.c. 2982Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 525686 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JFAT3SYX0 K 202674

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NIP / S/Rim / STD A/Rim orTyre Size: F: 195/75R15R: 155R12C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 13/04/23

Survey held at

Rear

R/Bal. 5/5 mmL/Bal. 5/5 mmD.O.I. 25/04/23

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Limit - 7k

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



CHENG AUTO BODYWORKS

Co. Reg. No. 53315238X | GST Reg. No. M90372111L

5 Soon Lee Street, #01-60 Pioneer Point, Singapore 627607

☎ 6631 0707 ✉ cab@chengauto.com 📍 Cheng Auto Bodyworks Singapore

Date: 25 April 2023

REPAIR DETAILS		
REFERENCE		
Vehicle Reg. No.	GBC8308X	45 TP
Make & Model	TOYOTA / TOYOTA DYNA 150 MANUAL	
Chassis No.	JTFAT35YX0K202674	
Engine No.	1KD2344804	
Manufacture Year	2013	
TP Vehicle Reg. No.	YQ7077Y	
DOA & Location	13-04-2023	ALONG KIAN TECK ROAD

ESTIMATES OF PARTS

No.	Description	Qty	Price
1	WINDSCREEN X	1	\$ 1,674.02
2	WINDSCREEN MOULDING X	1	\$ 395.26
3	CENTRE PANEL X	1	\$ 1,277.90
4	GRILLE ASSY X	1	\$ 636.86
5	HEADLAMP LH <i>su</i>	1	\$ 1,260.67
6	SIDE CORNER PANEL LH <i>4</i>	1	\$ 349.46
7	SIDE CORNER MOULDING BLACK LH X	1	\$ 82.50
8	PARKING MIRROR LH GARNISH COVER <i>ms</i>	1	\$ 92.40
9	DOOR LH <i>repair</i>	1	\$ 1,811.60
10	DOOR LH HINGE UPPER X	1	\$ 142.10
11	DOOR LH HINGE LOWER X	1	\$ 142.10
12	ROUND PARKING MIRROR <i>ms</i>	1	\$ 98.60
13	PARKING MIRROR STAND LH <i>4</i>	1	\$ 104.50
14	EMBLEM DYNA X	1	\$ 68.80
15	BUMPER BRACKET LH X	1	\$ 253.80
16	STEP GARNISH LH X	1	\$ 375.30

17. Windscreen Lower panel <i>10.65</i> X	Sub-Total (\$\$)	\$ 8,765.87
18. Front Bumper <i>4</i>	SAAA List Item Discount 25% (\$\$)	\$ 2,191.47
	Total Parts (\$\$)	\$ 6,574.40

LABOUR

No.	Description	Price
1	LABOUR	\$ 1,800.00 <i>su</i>
2	SPRAYPAINTING	\$ 1,400.00 <i>600</i>
3	REMOVE AND REINSTALL ROOF AC ASSY TO CHECK	\$ 400.00 X
4	REMOVE AND REINSTALL INNER TRIM, GARNISH, ROOF LINING AND/OR UPHOLSTERY TO FACILITATE REPAIRS	\$ 300.00 X

5	REMOVE AND REPLACE FRONT WINDSCREEN	\$	150.00
6	ALIGNMENT	\$	150.00
Total Labour (\$\$)		\$	4,000.00

MISCELLANEOUS ITEMS

No.	Description	Price
1	AC GAS	\$ 200.00
2	COMPANY STICKER LOGO DOOR	\$ 400.00
3	COMPANY STICKER	\$ 30.00
Total Miscellaneous Items (\$\$)		\$ 630.00

Total Parts (\$\$)	\$	6,574.40
Total Labour (\$\$)	\$	4,000.00
Total Miscellaneous (\$\$)	\$	630.00
Total (\$\$)	\$	11,204.40
GST 8% (\$\$)	\$	896.35
Grand Total (\$\$)	\$	12,100.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resul
Hy 90010068
4 days
4/5
25/04/23 P1410
Resurvey after repair

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	135D
Vehicle No.:	GBC8308X
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Apr 2023
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	1KD2344804
Chassis No.:	JTFAT35YX0K202674
Maximum Power Output:	-
Open Market Value:	\$27,856.00
Original Registration Date:	12 Dec 2013
First Registration Date:	12 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$1,393.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	11 Dec 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$42,067.00
COE Rebate Amount:	\$2,625.00
Total Rebate Amount:	\$2,625.00

The information contained herein is correct as at 26 Apr 2023

OK