



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23004225/Rvy3m4 Date: 23/05/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YQ 7077Y	Veh. Inspected	GBC 8308X
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS23/1251	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	25/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150 M	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	JTFAT35YX0K202674	Colour	WHITE
	Odometer	525686 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/75R15	YOKOHAMA	7 mm
	L/H Front Tyre	195/75R15	YOKOHAMA	7 mm
	R/H Rear Tyre	155R12C	YOKOHAMA	5/5 mm
	L/H Rear Tyre	155R12C	YOKOHAMA	5/5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/04/2023	Inspection Date	25/04/2023
	Survey held at	5 SOON LEE STREET, #01-60 PIONEER POINT		
	Repairer	CHENG AUTO BODYWORKS		
5a. Remarks				
	A)REGISTRATION DATE: 12 DEC 2013 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	