

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Estimate : ES708842

Date : 25/04/2023

Vehicle Num. : GBL 3951Z

Make/Model : TOYOTA HIACE

Chassis/Eng# :

Accident Date : 25/04/2023

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	N/S HEADLAMP <i>SCN</i>		990.00
2.	1 PC	FRONT BUMPER <i>DIS</i>		653.00
3.	1 PC	N/S FRONT BUMPER SIDE RETAINER <i>CM</i>	<i>145</i>	191.00
4.	1 PC	N/S FRONT BUMPER AIR GRILLE <i>1</i>		274.00
List Total S\$:				2,048.00
25.00% Discount S\$:				512.00
				1,536.00
SPECIAL NETT ITEMS :				
1.	1 PC	HEADLAMP CLIP <i>1</i>		40.00
2.	1 PC	FRONT BUMPER CLIP <i>1</i>		40.00
3.	1 PC	FRONT BUMPER RIVET <i>NS</i>		60.00
4.	1 PC	N/S FRONT DOOR COMPANY STICKER <i>1</i>		60.00
Special Nett Total S\$:				200.00
LABOUR :				
TO FOCUS HEADLAMP & WIRING				50.00
TO RUSTPROOF ON DAMAGED PARTS				150.00
TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEMENT				400.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Authed
25/4/23
2/5 \$1600/
3 days.
Tel p the Admin.

1788
202
1341
70

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
 51 CLUB STREET #03-00 LIBERTY HOUSE
 SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Estimate : ES708842

Date : 25/04/2023

Vehicle Num. : GBL 3951Z

Make/Model : TOYOTA HIACE

Chassis/Eng# :

Accident Date : 25/04/2023

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

OF PARTS AND ALIGN THE SAME
 TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA

600.00 400

Labour Total S\$:

1,200.00

E. & O.E.

Total S\$: 2,936.00

=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH