

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6548 8158

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK

DATE: 24.04.2023

SKW7322Z

INSURANCE: INCOME (LKS)MODEL: Hyundai IoniqSURVEYOR: LKK-VEHICLE NO.: SHA1364TMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Rear Bumper	1		\$ 459.40	XRA
	Rear Bumper Side Brackets LH	1		\$ 55.80	?XSVL
	Rear Bumper Centre Moulding	1		\$ 451.25	DEF
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00	XND/NEC
	Rear Bumper Reflector Lamp LH	1		\$ 41.45	?XSVL
	Rear Bumper Tow Cover	1		\$ 98.80	XSVL
	SUB TOTAL		932.65	\$ 1,128.70	
	LESS 20%			\$ 225.74	
	DISCOUNTED TOTAL		746.12	\$ 902.96	
	Reverse Sensors	1		\$ 180.00	XSVL
	S/NETT SUB			\$ 180.00	
	LESS 10%			\$ 18.00	
	S/NETT TOTAL			\$ 162.00	
	Rear Bumper Mat	1		\$ 50.00	NETT - NEC
	SPARE PARTS TOTAL			\$ 1,114.96	
	Labour Charge				
	Panel Beating			\$ 400.00	350
	Spray Painting Charge			\$ 300.00	250
	Remove/Refix Reverse Sensor			\$ 120.00	30
	TOTAL LABOUR			\$ 820.00	
	ESTIMATE TOTAL			\$ 1,934.96	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LKK
24/4/2023 1615
LJ
2 days
CHECK ITEM (PHOTO)
AFTER REPAIR (PHOTO)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: