

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

SKW7322Z

DATE: 24.04.2023INSURANCE: INCOME (LKS)MODEL: Hyundai IoniqSURVEYOR: LKK-VEHICLE NO.: SHA1364TMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Side Brackets LH	1		\$ 55.80
	Rear Bumper Centre Moulding	1		\$ 451.25
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00
	Rear Bumper Reflector Lamp LH	1		\$ 41.45
	Rear Bumper Tow Cover	1		\$ 98.80
	SUB TOTAL			\$ 1,128.70
	LESS 20%			\$ 225.74
	DISCOUNTED TOTAL			\$ 902.96
	Reverse Sensors	1		\$ 180.00
	S/NETT SUB			\$ 180.00
	LESS 10%			\$ 18.00
	S/NETT TOTAL			\$ 162.00
	Rear Bumper Mat	1		\$ 50.00
	SPARE PARTS TOTAL			\$ 1,114.96
	<u>Labour Charge</u>			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 820.00
	ESTIMATE TOTAL			\$ 1,934.96

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LK11
24/4/2023 1615
L11
2 days
CHECK ITEM PHOTO
AFTER REPAIR PHOTO