

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 24.04.2023

INSURANCE: SMQ3896T INCOME

MODEL: Hyundai Ioniq

SURVEYOR: LKK-

VEHICLE NO.: SHC3171J

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Rear Bumper	1		\$ 459.40	/ DEF
	Rear Bumper Reinforcement	1		\$ 394.80	?
	Rear Bumper Reinforcement Bracket LH / RH	2	\$ 138.10	\$ 276.20	?
	Rear Bumper Side Brackets LH / RH	2	\$ 55.80	\$ 111.60	?
	Rear Bumper Centre Moulding	1		\$ 451.25	/ CRA
	Rear Bumper Lower Centre Moulding	1		\$ 155.00	- SCR
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00	/ NEU
	Rear Bumper Reflector Lamp LH / RH	2	\$ 41.45	\$ 82.90	?
	Rear Bumper Tow Cover	1		\$ 98.80	/ SCR
	Rear Bumper FogLamp	1		\$ 201.50	/ CRA
	Rear Smart Key Antenna	1		\$ 40.50	?
	BootLid Emblem - Hybrid	1		\$ 24.30	- NEU
	BootLid Emblem - Ioniq	1		\$ 31.30	- NEU
	BootLid Assy	1		\$ 2,549.70	/ DD
	BootLid Lamp LH	1		\$ 822.00	/ CRA
	TailLamp LH	1		\$ 935.40	/ SUL
	SUB TOTAL			\$ 6,656.65	
	LESS 20%			\$ 1,331.33	
	DISCOUNTED TOTAL			\$ 5,325.32	
	BootLid ComfortDelGro	1		\$ 30.00	
	BootLid 65521111	1		\$ 30.00	/ NEU
	BootLid ZIG	1		\$ 40.00	
	Reverse Sensors	1		\$ 180.00	/ ORF
	Rear No.Plade With Trim Cover-YELLOW	1		\$ 55.00	/ DD
	Rear Windscreen Sealants	2	\$ 46.00	\$ 92.00	- NEU
	S/NETT SUB			\$ 427.00	
	LESS 10%			\$ 42.70	
	S/NETT TOTAL			\$ 384.30	
	Rear Fender Adv.Sticker RH / LH	2	\$ 100.00	\$ 200.00	NETT / NEU
	BootLid Adv.Sticker	1		\$ 100.00	NETT / NEU
	SPARE PARTS TOTAL			\$ 6,009.62	
	Labour Charge				
	Panel Beating			\$ 800.00	700
	Spray Painting Charge			\$ 600.00	500
	Check Lightings/Wirings			\$ 60.00	30
	Remove/Refix Reverse Sensor			\$ 120.00	30
	Remove/Refix Rear Windscreen Glasses			\$ 240.00	200
	TOTAL LABOUR			\$ 1,820.00	
	ESTIMATE TOTAL			\$ 7,829.62	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKK
24/4/2023 1605
LIS
3 DAYS
CHECK ITEM PHOTOS / AFTER REPAIR PHOTOS