

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 03.04.2023

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : PC7874T
MODEL : TOYOTA HIACE COMMUT
DATE OF ACCIDENT : 03.04.2023
TIME OF ACCIDENT : 16:30 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR SIDE PANEL RH <i>Dented</i>	1	\$ 1,984.00	\$ 1,984.00
2	REAR SIDE PANEL GLASS RH <i>shattered</i>	1	\$ 1,280.00	\$ 1,280.00
3	REAR SIDE INNER PANEL RH <i>Regr</i>	1	\$ 1,620.00	\$ 1,620.00
4	REAR SIDE INNER LOWER PANEL RH <i>Regr</i>	1	\$ 654.20	\$ 654.20
5	REAR SIDE PANEL INNER TRIM RH <i>new</i>	1	\$ 324.20	\$ 324.20
6	REAR SHOCK ABSORBER RH <i>new</i>	1	\$ 439.00	\$ 439.00
7	REAR WHEEL HUP RH <i>new</i>	1	\$ 390.00	\$ 390.00
8	REAR WHEEL HUP BEARING RH <i>new</i>	1	\$ 187.00	\$ 187.00
9	REAR BUMPER SIDE RETAINER <i>new RH</i>	2	\$ 55.00	\$ 110.00
10	REAR AXLE <i>new</i>	1	\$ 1,654.00	\$ 1,654.00
11	TAIL LAMP RH <i>new</i>	1	\$ 390.00	\$ 390.00
12	TAILLAMP LOWER GARNISH EH <i>new</i>	1	\$ 167.00	\$ 167.00
13	TAILLAMP LOWER GARNISH RETAINER EH <i>new</i>	1	\$ 65.00	\$ 65.00

Centre Glass

cut

650

6527

4895.25

TOTAL PRICE \$ 9,264.40

LESS 25% \$ 2,316.10

SUB TOTAL PRICE \$ 6,948.30

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER (SPECAIL TYPE) <i>Deland</i>	1	\$ 2,500.00	\$ 2,500.00

30

1000

TO

VEHICLE NO

MODEL

DATE OF ACCIDENT

TIME OF ACCIDENT

: CHINA TAIPING MOTOR CLAIMS DEPTS

: PC7874T

: TOYOTA HIACE COMMUT

: 03.04.2023

: 16:30 HOURS

3	REAR SIDE PANEL SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00	<i>80</i>
4	REAR SIDE INNER PANEL SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
5	REAR SIDE INNER LOWER PANEL RH SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
6	REAR SIDE PANEL INNER TRIM CLIP RH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
7	REAR SIDE PANEL GLASS SEALANT RH <i>new</i>	1	\$ 80.00	\$ 80.00	<i>40</i>
8	REAR SIDE PANEL GLASS INNER SEAL RH <i>new</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
9	REAR SIDE PANEL GLASS SOLAR FLIM RH <i>new</i>	2	\$ 61.00	\$ 122.00	<i>✓</i>
10	REAR SIDE PANEL GLASS CURTAIN (SPECAIL TYPE) (	1	\$ 480.00	\$ 480.00	<i>+</i>
11	REAR SIDE PANELWHEEL ARCH (SPECAIL TYPE) (SET) <i>cut</i>	1	\$ 850.00	\$ 850.00	<i>280</i>
12	TAIL LAMP RING (SPECAIL TYPE) (SET) <i>cut</i>	1	\$ 550.00	\$ 550.00	<i>150</i>
13	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>10</i>
14	TAILLAMP LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	<i>+</i>
15	SPORT RIM WHEEL <i>cut</i>	1	\$ 1,200.00	\$ 1,200.00	<i>350</i>
16	REAR TYRE <i>Punctured</i>	1	\$ 480.00	\$ 480.00	<i>250</i>
17	SIDE SKIRT (SPECAIL TYPE) (SET) <i>new</i>	1	\$ 1,200.00	\$ 1,200.00	<i>+</i>
18	BRAKE OIL <i>new</i>	1	\$ 80.00	\$ 80.00	<i>40</i>

2382

TOTAL

\$ 8,222.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 2,600.00	<i>700</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00	<i>600</i>
3	WIRNING, BULB CHECKING	\$ 250.00	<i>30</i>
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 650.00	<i>120</i>
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>X</i>
6	REMOVE AND REFIX SIDE PANEL GLASS LH	\$ 200.00	<i>100</i>

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
 VEHICLE NO : **PC7874T**
 MODEL : **TOYOTA HIACE COMMUT**
 DATE OF ACCIDENT : 03.04.2023
 TIME OF ACCIDENT : 16:30 HOURS

7	VACCUM AND CLEAN SIDE PANEL GLASS SPLINTER	\$ 250.00	80
8	REMOVE AND REFIX LINING & SEATS	\$ 480.00	120
9	REMOVE REFIX REAR UNDERCARRIAGE	\$ 480.00	350
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 7,210.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 15,170.30
 TOTAL LABOUR COST : \$ 7,210.00
 TOTAL REPAIR COST : \$ 22,380.30

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP:8297 9787

Adrian Lj
 1/s 05/04/23.
 08 days.

total: 9377.25
 1/s: 7.51C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: