



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				CS3/LIP22012377/Tqy3-1	
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS3/LIP22012377/Tqy3 Date: 12/12/2022 21/04/2023 Code: LIP		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.	GBK 5633J		Veh. Inspected	GBJ 9867E	
Policy No.			Coverage (\$)	0.00	
Claim No.	AVS22/3431		Excess (\$)	0.00	
Assign From	TED SEAH ANDY SEAH		Assign Date	09/12/2022 21/04/2023	
2. Vehicle Particulars & Condition					
Make & Model			c.c	0	
Engine No.	HIDDEN		Year of Reg.		
Chassis No.			Colour		
Odometer	-		Steering		
Brakes			Modification		
General					
3. Conditions of Tyres					
		Size	Make	Balance	
R/H Front Tyre				mm	
L/H Front Tyre				mm	
R/H Rear Tyre				mm	
L/H Rear Tyre				mm	
4. Description of Damages					
5. General Information					
Accident Date	07/12/2022		Inspection Date	12/12/2022	
Survey held at	SV AUTOWORKS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					