

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 10.04.2023

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLR4481G**
MODEL : **TOYOTA WISH**
DATE OF ACCIDENT : 07.04.2023
TIME OF ACCIDENT : 19:00 HOURS

260206022815

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR VIEW MIRROR RH <i>cracked</i>	1	\$ 1,187.67	\$ 1,187.67
2	FRONT DOOR LH <i>Dented</i>	1	\$ 1,390.00	\$ 1,390.00
3	FRONT DOOR BLACK STICKER <i>New</i>	1	\$ 95.00	\$ 95.00
4	FRONT DOOR OUTER HANDLE LH <i>New</i>	1	\$ 236.00	\$ 236.00
5	FRONT DOOR OUTER MOULDING LH <i>New</i>	1	\$ 129.00	\$ 129.00
6	FRONT DOOR WEATHER STRIP LH <i>2</i>	1	\$ 186.00	\$ 186.00
7	FRONT DOOR INNER LOCK LH <i>1</i>	1	\$ 480.00	\$ 480.00
8	FRONT DOOR INNER SPONGE LH <i>1</i>	1	\$ 60.00	\$ 60.00
9	FRONT DOOR INNER TRIM BOARD LH <i>1</i>	1	\$ 840.00	\$ 840.00
10	FRONT DOOR POWER WINDOW MOTOR LH <i>1</i>	1	\$ 770.00	\$ 770.00

995
1288
60

2343
1757.25

TOTAL PRICE \$ 5,373.67
LESS 25% \$ 1,343.42
SUB TOTAL PRICE \$ 4,030.25

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT FLOOR INNER TRIM (SET) <i>New</i>	1	\$ 50.00	\$ 50.00
2	FRONT DOOR SEALANT LH <i>3</i>	1	\$ 150.00	\$ 150.00
3	FRONT DOOR OUTER MOULDING CLIP <i>1</i>	1	\$ 50.00	\$ 50.00
4	FRONT DOOR VISOR <i>New</i>	1	\$ 250.00	\$ 250.00

80

TOTAL \$ 500.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

80

TO : AIG MOTOR CLAIMS DEPTS
VEHICLE NO : SLR4481G
MODEL : TOYOTA WISH
DATE OF ACCIDENT : 07.04.2023
TIME OF ACCIDENT : 19:00 HOURS

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000.00	300.
2	SPRAY PAINTING TO AFFECTED AREA	\$ 800.00	300
3	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	40.
4	REMOVE & REINSTALL FRONT WINDOW GLASS	\$ 60.00	40.
5	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X

TOTAL

\$2,020.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,530.25
TOTAL LABOUR COST : \$ 2,020.00
TOTAL REPAIR COST : \$ 6,550.25

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King,
H/s 10/04/23.
03 Days.

total: 2517.25
H/s: 2K

2K