

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 82624 Yr Regn: 2021 / APRType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai / i10 c.c. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 221625 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCB51CVLU193068Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WFS LAKE

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 14/04/23Survey held at COMFORT

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

SAS-KIV

LKK - RASUL

GBE8992J

DATE: 19.04.2023

INSURANCE: INCOME CP/P

MODEL: Hyundai Ioniq

MVA: LIM T S

VEHICLE NO.: SHC8262Y

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper <i>de</i>	1		\$ 481.10
	Front Bumper Clips <i>ne</i>	10	\$ 2.20	\$ 22.00
	Front Bumper Upper Moulding <i>su</i>	1		\$ 368.50
	Front Bumper Sponge <i>?</i>	1		\$ 186.90
	Front Bumper Reinforcement <i>?</i>	1		\$ 1,136.70
	Front Bumper Lower Grille <i>sa</i>	1		\$ 368.50
	Front Bumper Lower Moulding <i>sa</i>	1		\$ 187.20
	Radiator Grille <i>cr</i>	1		\$ 1,409.10
	Headlamp LH <i>X in consistent</i>	1		\$ 2,110.30
	DayLight LH <i>X</i>	1		\$ 642.50
	DayLight Grille LH <i>X</i>	1		\$ 93.45
	SUB TOTAL			\$ 7,006.25
	LESS 20%			\$ 1,401.25
	TOTAL SPARE PARTS			\$ 5,605.00
	Front No. Plate With Trim Cover	1		\$ 55.00 55
	LESS 10%			\$ 5.50
	S/NETT TOTAL			\$ 49.50
	Labour Charge			
	Panel Beating			\$ 350 400.00
	Spray Painting			\$ 250 300.00
	Tuff Kote			\$ X 40.00
	Check Lightings/Wirings			\$ 30 40.00
	TOTAL LABOUR			\$ 780.00
	ESTIMATE TOTAL			\$ 6,434.50

Rasul

Hy 90010062

3 days

P/P

19/04/23

@ 1130

Reg before
paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Acknowledged by Repairer

Signature:

Date:

Workshops

205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609280

Date/Time: 19.04.2023 10:58

Page : 1

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5893622

JC NO305551720

CUSTOMER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO: SHC8262Y	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL: IONIQ(G3)	DATE/TIME IN 19.04.2023 09:50
	YR OF MANU: 29.04.2021	TARGET DATE
	CHASSIS CODE: KMHC851CVLU193068	COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 19.04.2023
NATURE: 3P 19.04.2023

LXX - Rasu


PP
Income

GB E
8992J

3/NO
100010

LABOR CODE
PB

DESCRIPTION
LUMPSUM REPAIR-SHC8262Y-TP



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

Vehicle No.: **SHC8262Y**

LIMITS

Vehicle No.: **SHC8262Y**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 821R

Vehicle Details

Vehicle No.: SHC8262Y

Vehicle to be Exported: No

Intended Deregistration Date: 24 Apr 2023

Vehicle Make: HYUNDAI

Vehicle Model: AE IONIQ HEV FL 1.6 DCT

Primary Colour: Blue

Manufacturing Year: 2019

Engine No.: G4LEKU422227

Chassis No.: KMHC851CVLU193068

Maximum Power Output: 103.6 kW (138 bhp)

Open Market Value: \$24,958.00

Original Registration Date: 29 Apr 2021

First Registration Date: 29 Apr 2021

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 Apr 2029

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 28 Apr 2029

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$33,827.00

COE Rebate Amount: \$25,417.00

Total Rebate Amount: \$29,167.00