

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

SAS-KIV

LKK - RASUL

GBE8992J

DATE: 19.04.2023

INSURANCE: INCOME CP/P)

MODEL: Hyundai Ioniq

MVA: LIM T S

VEHICLE NO.: SHC8262Y

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper <i>de</i>	1		\$ 481.10 ✓
	Front Bumper Clips <i>ne</i>	10	\$ 2.20	\$ 22.00 ✓
	Front Bumper Upper Moulding <i>su</i>	1		\$ 368.50 ✓
	Front Bumper Sponge <i>? X 11</i>	1		\$ 186.90
	Front Bumper Reinforcement <i>? X 11</i>	1	2836.40	\$ 1,136.70
	Front Bumper Lower Grille <i>su</i>	1	20%	\$ 368.50 ✓
	Front Bumper Lower Moulding <i>sa</i>	1	2269.12	\$ 187.20 ✓
	Radiator Grille <i>cu</i>	1		\$ 1,409.10 ✓
	Headlamp LH <i>X in consistent X 11</i>	1		\$ 2,110.30
	DayLight LH <i>X 11</i>	1		\$ 642.50
	DayLight Grille LH <i>X 11</i>	1		\$ 93.45
	SUB TOTAL			\$ 7,006.25
	LESS 20%			\$ 1,401.25
	TOTAL SPARE PARTS			\$ 5,605.00
	Front No. Plate With Trim Cover	1		\$ 55.00 55
	LESS 10%	55		\$ 5.50
	S/NETT TOTAL	10%		\$ 49.50
	Labour Charge			
	Panel Beating	630		\$ 400.00
	Spray Painting			\$ 250.00
	Tuff Kote			\$ 40.00
	Check Lightings/Wirings			\$ 30.00
	TOTAL LABOUR			\$ 780.00
	ESTIMATE TOTAL			\$ 6,434.50

Rasul

Hy 900/0062

3 days

P/P

19/04/23

@1130

Ben before
paint

55

2269.12

49.50

630.00

2945.62

3 days

LKK Auto Consultants hence notify the Repairee of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

• Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: