

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 23.04.2023

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLW4729S**
MODEL : **HONDA HRV**
DATE OF ACCIDENT : 21.04.2023
TIME OF ACCIDENT : 14:00 HOURS

JHMR418306x203655

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Delnd</i>	1	\$ 865.50	\$ 865.50
2	REAR BUMPER REFLECTOR <i>cracked</i>	2	\$ 151.10	\$ 302.20
3	REAR BUMPER SIDE <i>LH Delnd</i>	2	\$ 230.00	\$ 460.00
4	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 57.00	\$ 114.00
5	TAIL LAMP <i>cracked</i>	2	\$ 475.00	\$ 950.00
6	TAILGATE <i>Distorted</i>	1	\$ 1,420.00	\$ 1,420.00
7	TAILGATE NUMBER PLATE LAMP <i>new</i>	2	\$ 85.00	\$ 170.00
8	TAILGATE LOGO <i>new</i>	1	\$ 65.00	\$ 65.00
9	TAILGATE EMBLEM 'HRV' <i>3 New</i>	1	\$ 68.00	\$ 68.00
10	TAILGATE EMBLEM 'I-VTEC' <i>new</i>	1	\$ 65.00	\$ 65.00
11	TAILGATE OUTER GARNISH <i>cracked</i>	1	\$ 220.00	\$ 220.00
12	TAILGATE SIDE LAMP <i>cracked</i>	2	\$ 240.00	\$ 480.00
13	TAILGATE INNER HOLDER <i>new</i>	1	\$ 52.00	\$ 52.00
14	TAILGATE STOPPER <i>new</i>	2	\$ 19.00	\$ 38.00
15	TAILGATE TOP LOCK <i>new</i>	1	\$ 180.00	\$ 180.00
16	TAILGATE LOWER LOCK <i>new</i>	1	\$ 24.70	\$ 24.70
17	TAILGATE INNER TRIM <i>cracked</i>	1	\$ 398.60	\$ 398.60
18	TAILGATE WEATHER STRIP <i>cut</i>	1	\$ 168.40	\$ 168.40
19	TAILGATE WINDSCREEN MOULDING (SET) <i>new</i>	1	\$ 164.00	\$ 164.00
20	TAILGATE LOCK CONNECTOR <i>new</i>	1	\$ 379.00	\$ 379.00

492
230
853
255

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLW4729S**
 MODEL : **HONDA HRV**
 DATE OF ACCIDENT : 21.04.2023
 TIME OF ACCIDENT : 14:00 HOURS

21	BUZZER <i>new included</i>	1	\$	109.00	\$	109.00	<i>✓ 588</i>
22	REAR FENDER INNER TRIM <i>new included</i>	2	\$	399.10	\$	798.20	<i>✓ 399.10</i>
23	REAR FENDER COWLING <i>new</i>	2	\$	150.20	\$	300.40	<i>✓</i>
24	REAR FENDER ARCED GARNISH <i>new</i>	2	\$	184.70	\$	369.40	<i>✓</i>
25	REAR END PANEL <i>Dented</i>	1	\$	530.00	\$	530.00	<i>✓</i>
26	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$	146.30	\$	146.30	<i>✓</i>
27	REAR FLOOR PANEL <i>Repair</i>	1	\$	1,130.00	\$	1,130.00	<i>✓</i>
28	REAR FLOOR PANEL BOTTOM GARNISH <i>Dented</i>	1	\$	269.00	\$	269.00	<i>✓</i>
29	REAR FLOOR TOWING PANEL <i>new</i>	1	\$	545.00	\$	545.00	<i>✓</i>
30	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$	300.40	\$	300.40	<i>✓</i>
31	REAR STORAGE BOX <i>included</i>	1	\$	495.00	\$	495.00	<i>✓</i>
32	REAR EXHAUST <i>2</i>	1	\$	980.00	\$	980.00	<i>✓</i>
33	REAR EXHAUST INSULATOR <i>new</i>	1	\$	55.00	\$	55.00	<i>✓</i>
34	REAR EXHAUST MOUNTING <i>new</i>	4	\$	18.00	\$	72.00	<i>✓</i>
35	REAR EXHAUST GASKET (SET)	1	\$	80.00	\$	80.00	<i>✓</i>
36	REVERSE CAMERA <i>new</i>	1	\$	1,358.60	\$	1,358.60	<i>✓</i>
37	REVERSE SENSOR (SET) <i>2nd</i>	1	\$	650.00	\$	650.00	<i>✓ 400/sv</i>

7080.30
 5664.24
 S.N : 400

TOTAL PRICE \$ 14,772.70
 LESS 20% \$ 2,954.54
SUB TOTAL PRICE \$ 11,818.16

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
4	TAILGATE OUTER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
5	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
6	TAILGATE WINDSCREEN SEALANT <i>3 new</i>	1	\$ 80.00	\$ 80.00
7	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
8	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
9	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
10	REAR FENDER ARCED GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLW4729S**
 MODEL : **HONDA HRV**
 DATE OF ACCIDENT : **21.04.2023**
 TIME OF ACCIDENT : **14:00 HOURS**

11	REAR END PANEL TOP GARNISH CLIP (SET) <i>NW</i>	1	\$ 60.00	\$ 60.00	<i>20</i>
12	REAR END PANEL INSULATION SEAL <i>NW</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
13	REAR FLOOR PANEL SEALANT <i>NW</i>	1	\$ 350.00	\$ 350.00	<i>X</i>
14	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET) <i>NW</i>	1	\$ 80.00	\$ 80.00	<i>30</i>

320

TOTAL \$ 1,380.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	<i>800</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>80</i>
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>80</i>
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	<i>50</i>
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>X</i>
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>
10	TRANSFER TAILGATE MECHANISM	\$ 80.00	<i>80</i>
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	<i>X</i>

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLW4729S**
MODEL : **HONDA HRV**
DATE OF ACCIDENT : 21.04.2023
TIME OF ACCIDENT : 14:00 HOURS

2110

12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL \$ 5,300.00

TOTAL PARTS COST : \$ 13,198.16
TOTAL LABOUR COST : \$ 5,300.00
TOTAL REPAIR COST : \$ 18,498.16

Adrian L
I/s 25/04/23.
06 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 849424

4/s: 68K

6.8K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: