



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS/GAI23004245/Uvy3e2 Date: 03/05/2023 Code: GAI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YM 5064T	Veh. Inspected	SLA 3210T
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000004334	Excess (\$)	0.00
Assign From	ELIZABETH CHEW	Assign Date	25/04/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104546479	Colour	WHITE
Odometer	158667 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	GOODYEAR	6 mm
L/H Front Tyre	225/45 R17	GOODYEAR	6 mm
R/H Rear Tyre	225/45 R17	GOODYEAR	6 mm
L/H Rear Tyre	225/45 R17	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/04/2023	Inspection Date	25/04/2023
Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	