

金興(豐)海運私人有限公司

K. KIM HEE AUTO PTE LTD

160 Selegie Road, #02-18/19/20

Singapore City

Phone: 6452 375722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

No. : 32894

Vehicle Insured : YP 1626 H  
Accident Date : 20-Apr-2023

Date : 24-Apr-2023

Our Ref : 023223 (LONPAC) / SANDRA

PAGE : 1

LANDSCAPE ENGINEERING PTE LTD  
Singapore

ESTIMATED COST OF REPAIR FOR MITSUBISHI CANTER (2998CC) (2017) YP5835U

1 pc	front cabin assy (used)		14,000.00 c
1 pc	air con condenser	]	3,000.00 c
1 pc	air con pipes	]	
1 pc	air con dryers	]	
1 pc	air con fan assy	]	
1 pc	air con fan assy bracket	]	
1 pc	air con cooling coil	]	
1 pc	air con blower	]	
1 pc	air con heater unit	]	
1 pc	engine mounting (1 set)	]	200.00 c
1 pc	gearbox mounting (1 set)	]	
1 pc	radiator assy	]	1,800.00 c
1 pc	radiator fan assy	]	
1 pc	radiator fan cowling	]	
1 pc	radiator fan blade	]	
1 pc	radiator fan clutch	]	
1 pc	air cleaner box assy	]	750.00 c
1 pc	air intake duct	]	
1 pc	turbo cooler		1,200.00 c
2 pcs	taillamp assy (LH/RH)	@ S\$100.00	200.00 c
1 pc	dashboard meter		850.00 c
1 pc	front cabin mountings (2 pcs)		2,800.00 c
1 pc	front cabin mountings bracket	]	
	(2 pcs)	]	
1 pc	rear cabin mountings (2pcs)	]	
1 pc	front cabin tilt shaft	]	
1 pc	front cabin tilt inner shaft	]	
			<hr/>
			24,800.00
Add 15% :			3,720.00
			<hr/>
			28,520.00

Press any key to continue...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming Auto Centre

Singapore 573722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : YP 1626 H

Our Ref : 023223

Page : 2

No. : 32894

6 pcs 'U' bolt (for securing wooden deck)	@ S\$ 25.00	150.00	sn
1 pc rear wooden cargo deck assy		9,500.00	sn
2 pcs rear wooden chassis member	@ S\$400.00	800.00	sn
1 pc rear canopy (sliding type with railing)		6,000.00	sn
1 pc rear lower step panel		400.00	sn
1 pc rear lower reinforcement		650.00	sn
1 pc reverse camera		550.00	sn
1 pc reverse sensor		220.00	sn
1 pc rear mudguard (2 pcs)	]	450.00	sn
1 pc rear mudguard bracket (8 pcs)]			
2 pcs front & rear number plates	@ S\$ 40.00	80.00	sn
1 pc radio headset		400.00	sn
1 pc ERP bracket		26.00	sn
2 pcs '60km/h' & '23 pax' sticker	@ S\$ 15.00	30.00	sn
1 pc company advertisement sticker		950.00	sn
To tow accident vehicle to workshop by normal towing		100.00	
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.		3,500.00	
To remove aircon condenser, pipes and driers. Vaccum and recharge gas		100.00	
To remove door's fittings		160.00	
To remove and renew front wind-screen glass and conduct water leak test.		100.00	
To remove and renew front instrument panel assy, to rewiring and transfer instrument fittings.		280.00	

Con't Page 3 ...

金興(龔)汽車私人有限公司  
K. KIM HIN AUTO PTE LTD  
160 Sin Ming Drive #02-197/198  
Sin Ming Auto Centre  
Singapore 575717  
Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : YP 1626 H  
Our Ref : 023223

Page : 3  
No. : 32894

To remove and refit front seat assy trim board and carpet to facilitate repairing works	120.00
To check and realignment on chassis member.	1,800.00
To putty and respray on affected portions.	2,500.00
To focus Headlamps and Taillamps.	
To check front and rear lighting operation and rewiring	80.00
Remove and replace rear wooden deck in order to facilitate repairing works	2,400.00
Total :	<u>S\$59,866.00</u>

Singapore Dollars FIFTY NINE THOUSAND EIGHT HUNDRED AND SIXTY SIX Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.