

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/HLA23004273/UWY3Q2
Date: 11/05/2023

REFERENCE

Handling Insurer: HL Assurance Pte Ltd Policy No: MP319487
Claimant Vehicle No : FBL6324P **Insured Vehicle No :** SMR1990L
Date of Loss: 10/04/2023 Nature of Claim: TP Claim No: MPC04108

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBL6324P**
Make & Model: YAMAHA YBR125, 123cc (M) Engine No: E3F5E043516
Reg. Date: 12/01/2017 (Man. Year: 2016) Chassis No: LBP101000058527
Colour: Red Odometer: 78040 km
Engine Capacity: 124 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 2.75-18 Rear Tyre Size: 3.00 -18
Front Left Side: Timsun 6 mm Rear Left Side: Timsun 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	482.00	222.50	259.50	53.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	222.00	160.00	62.00	27.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	704.00	382.50	321.50	45.67
Approved Total (Overridden) (S\$)		300.00		
(S\$)	704.00	300.00	404.00	57.39
+ GST 8.00/8.00% (S\$)	56.32	24.00	32.32	57.39
Nett Amount (S\$)	760.32	324.00	436.32	57.39

INSPECTION

Date of Assignment: 25/04/2023
Date Inspected: 26/04/2023 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
BLK 8 Defu South Street 1, #04-28 JTC Defu
Industrial City
Singapore 533758
Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 11 May 2023)	
Parts:	N/A	YAMAHA YBR125 123cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL6324P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*COVER TAIL LH (RED) (CUT)	Not Consistent With The Impact	86.00 F	*- FL	
2	1		*HEADLAMP ASSY (Scratched)	Not Consistent With The Impact	117.00 F	*- FL	
3	1		*LAMP SIGNAL LREAR LH	Serviceable	24.00 F	*- FL	
4	1		*LAMP SIGNAL LREAR RH	Scratched	24.00 F	*24.00 FL	
5	1		*LEVER BRAKE	Scratched	21.00 F	*21.00 FL	
6	1		*MIRROR RH	Cut	39.00 F	*39.00 FL	
7	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Scratched	30.00 FS	*20.00 FS	
8	1		*PROTECTOR EXHAUST	Cut	86.00 F	*86.00 FL	
9	1		*PROTECTOR EXHAUST CAP	Cut	55.00 F	*55.00 FL	
					Sub Total (\$)	482.00	245.00
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00	22.50
					Total Parts (\$)	482.00	222.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT CHARGES	New	50.00	0.00
2	LABOUR	New	172.00	160.00
			Gross Labour Cost (S\$)	222.00
				160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >