



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD
10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983
ATTN: CYNTHIA

Ref: CC4/HSB23004281/Upa3q2
Date: 14/07/2023
Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8568B	Veh. Inspected	GBG 2935D
Policy No.	P2478220	Coverage (\$)	0.00
Claim No.	S3M04LU1	Excess (\$)	0.00
Assign From		Assign Date	26/04/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDY2318027988	Colour	SILVER
Odometer	183514 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	KAPSEN	6 mm
L/H Front Tyre	195 R15	KAPSEN	6 mm
R/H Rear Tyre	165 R13 (D)	KAPSEN	6/6 mm
L/H Rear Tyre	165 R13 (D)	KAPSEN	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/04/2023	Inspection Date	04/05/2023
Survey held at	TLM AUTOMOBILE PTE LTD 1 DEFU LANE 6, DEFU INDUSTRIAL PARK A, SINGAPORE 539365		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**