

(08/11/13) wef

ASS. RES. BY: Marcus

REF:

CC4/LPC 23004282/Upa3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK 2937R

at Workshop m/s PT.

of _____

Insured: SLK 2937R

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: \$59k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 274 527650

Veh No: SLK 2937R Yr Regn: 25/09/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or CA / GLS

Make: Hyundai Elantra c.c. 1591

Colour: white A/C: Insured / Std / NI / NA

Sp.Reading: 152065 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH D841 CMJU 545336

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55-16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 25/04/23 D.O.I. 26/4/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>9/5/23</u>	<u>4/5 @ 7000 in hand Aler.</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS. ____ SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Allowed
26/4/23
1/5 @ 7000/
take photo after 4 days.

VEHICLE No: SLS 4387R

1PC	FRONT DOOR N/S	Body DO	2201.30	\$2,415.00	—
1PC	FRONT DOOR OUTER HANDLE N/S	cut	265.80	\$282.00	—
1PC	FRONT DOOR INNER LOCK N/S	mofusion / Daye	305.40	\$453.00	—
1PC	FRONT DOOR INNER RUBBER N/S	ner		\$166.00	—
1PC	FRONT DOOR INNER TRIM N/S	De / 1001		\$688.10	—
2PCS	FRONT DOOR HINGES N/S @ \$90.00	11		\$180.00	X
1PC	FRONT DOOR CHECKER N/S	11		\$121.00	X
1PC	FRONT DOOR GLASS OUTER MOULDING N/S	ner		\$165.00	—
1PC	FRONT DOOR GLASS N/S	11		\$255.10	X
1PC	FRONT DOOR GLASS REGULATOR & MOTOR N/S	Daye / 1001	465.50	\$755.30	—
1PC	FRONT DOOR SPEAKER N/S	11		\$250.00	X
1PC	CENTRE PILLAR N/S	11		\$988.20	X
1PC	CENTRE PILLAR INNER GARNISH N/S	11		\$185.20	X
1PC	ROCKER PANEL N/S	11		\$1,299.10	X
1PC	REAR DOOR N/S	11 / 1001	2062	\$2,399.10	—
1PC	REAR DOOR OUTER HANDLE N/S	11		\$245.00	X
1PC	REAR DOOR INNER RUBBER N/S	ner	146.80	\$182.00	—
1PC	REAR DOOR INNER TRIM BOARD N/S	11		\$600.50	X
2PCS	REAR DOOR HINGES N/S @ \$90.00	11		\$180.00	X
1PC	REAR DOOR CHECKER N/S	11		\$121.00	X
1PC	REAR DOOR GLASS OUTER MOULDING N/S	ner		\$108.90	—
1PC	REAR DOOR GLASS N/S	11		\$255.00	X
1PC	REAR DOOR GLASS REGULATOR & MOTOR N/S	11		\$455.00	X
1PC	REAR DOOR SPEAKER N/S	11		\$250.00	X
1PC	REAR DOOR INNER STEP GARNISH N/S	11		\$182.00	X
1PC	REAR DOOR INNER HANDLE BRACKET N/S	11		\$205.00	X
1PC	REAR DOOR INNER CHANNEL RUBBER N/S	11		\$285.00	X
1PC	REAR FENDER N/S	11		\$1,915.00	X
1PC	REAR FENDER INNER TRIM N/S	11		\$242.00	X
1PC	REAR FENDER QUARTER GLASS N/S	11		\$305.00	X
1PC	REAR WINDSCREEN MOULDING	11		\$110.00	X
1PC	REAR BUMPER	11		\$482.00	—
1PC	REAR BUMPER MUDFLAP N/S	cut / 1001	481.40	\$98.20	—
1PC	REAR SHOCK ABSORBER N/S	11		\$322.00	X
1PC	REAR AXLE BEAM	11		\$1,665.00	X
1PC	REAR KNUCKLE ARM N/S	11		\$545.00	X
1PC	REAR WHEEL HUB BEARING N/S	Daye		\$225.00	—
1PC	REAR WHEEL HOUSING PANEL N/S	11		\$945.10	X
				\$20,525.80	

S.NETT

202

1PC	REAR SPORT RIM N/S	warped	\$600.00	500
1PC	REAR TYRE N/S	sun	\$200.00	X
1PC	REAR DOOR VISOR N/S	new	\$60.00	50
1SET	REAR DOOR INNER TRIM BOARD CLIPS N/S	new	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	^^	\$50.00	X
1PC	REAR WINDSCREEN SEALANT	^^	\$50.00	X
1PC	REAR FENDER QUARTER GLASS SEALANT N/S	^^	\$50.00	X
1PC	FRONT DOOR VISOR N/S	new	\$60.00	50
1SET	FRONT DOOR INNER TRIM BOARD CLIPS N/S	new	\$50.00	40

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR WINDSCREEN	^^ \$150.00	X
TO DISMANTLE & REPLACED REAR FENDER QUARTER GLASS N/S	^^ \$100.00	X
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$200.00	120
TO CONDUCT WHEEL ALIGNMENT	\$120.00	60
TO DISMANTLE & REFIX FUEL TANK	\$100.00	60
TO RESET & REPROGRAMME SYSTEM	^^ \$180.00	X
TO MOUNT VEHICLE ON CAR O-LINER	^^ \$380.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	600
TO PUTTY & SPRAY PAINTING	\$1,500.00	1180
TOTAL	\$26,475.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-7379.4
 202
 5903.52
 680
 2170
 8753.52
 202
 7002