

ASS. REC. BY:

REF:

F021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ QD / ☐ TP / ☐ WS / ☐ TP RES / ☐ QD RES / ☐ EVA / ☐ INV / ☐ MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

20 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SUB 807L

Yr Regn:

03, 16

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

C.C.

1496

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

150699

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

RU1

1109203

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: ☒ Nil / ☐ S/Rlm / ☐ STD / ☐ A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

2

mm

R/Bal.

3

mm

L/Bal.

2

mm

L/Bal.

3

mm

D.O.A.

21/4/23

D.O.I.

26/4/2023

Survey held at

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

O/S body & N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision. ☒

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLB 807L
 OD/FC

Not Not haise
LI Rep &
Resumy After Pain
20 days

M/S : MS FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877
 TEL: 65073848 FAX: 65073849
 ATTN: Motor Claim Department

Estimate No: ES2300429/YISHUN
 Date: 26 Apr 2023
 Policy No: D-22099561MFQC/4
 Veh Reg No: SLB807L
 Make/Model: HONDA HONDA VEZEL
 1.5X CVT
 Chassis No: RU11109203
 Engine No: L15B4029206
 Reg. Date: 28/03/2016

WS Ref: OD/FC
 Claim Type: Own Damage
 Accident Date: 21/04/2023

Estimate Repair Cost to Vehicle No :SLB807L

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
1 FRONT BUMPER	875.50	1 PC	71 875.50	✓
2 FRONT BUMPER TOW COVER	19.10	1 PC	R 19.10	X
3 FRONT BUMPER LOWER SKIRT	219.90	1 PC	CR 219.90	✓
4 FRONT BUMPER LOWER RUBBER	90.10	1 PC	CR 90.10	✓
5 FRONT BUMPER RH SIDE RETAINER	18.70	1 PC	CR 18.70	✓
6 FRONT BUMPER RH FOG LAMP GARNISH	29.80	1 PC	CR 29.80	✓
7 FRONT BUMPER CLIPS	3.80	6 PCS	R 22.80	✓
8 FRONT BUMPER REINFORCEMENT	270.40	1 PC	270.40	7
9 FRONT RH SPORT RIM	836.20	1 PC	R 836.20	✓
10 FRONT RH SHOCK ABSORBER	387.20	1 PC	R 387.20	✓
11 FRONT RH KNUCKLE ARM	28.10	1 PC	R 28.10	✓
12 FRONT RH WHEEL BEARING	164.70	1 PC	R 164.70	✓
13 FRONT RH LOWER ARM	444.80	1 PC	DI 444.80	✓
14 STEERING RACK & PINION	1,280.00	1 PC	R/T 1,280.00	✓
15 FRONT RH DRIVE SHAFT	1,347.10	1 PC	1,347.10	7
16 ENGINE REAR CROSS MEMBER	907.20	1 PC	907.20	7
17 FRONT RH FENDER	475.70	1 PC	R 475.70	✓
18 FRONT RH FENDER INNER SHIELD	112.70	1 PC	CR 112.70	✓
19 FRONT RH FENDER INNER SHIELD CLIPS	3.80	8 PCS	R 30.40	✓
20 FRONT RH FENDER WHEEL ARP GARNISH	153.00	1 PC	R 153.00	✓
21 FRONT RH FENDER INNER PANEL	256.90	1 PC	R 256.90	✓
22 FRONT RH FENDER INNER BRACKET	157.00	1 PC	R 157.00	✓
23 FRONT RH FENDER INNER PANEL SUPPORT	122.30	1 PC	R 122.30	✓
24 RH SIDE SKIRT	233.60	1 PC	233.60	7
25 FRONT WIPER TANK	85.90	1 PC	R 85.90	✓
26 BONNET	857.50	1 PC	R 857.50	✓
27 BONNET INNER SPONGE	122.30	1 PC	CR 122.30	✓
28 BONNET INNER RUBBERS	24.10	2 PCS	old CR 48.20	4
29 BONNET HINGES	48.50	2 PCS	97.00	4
30 HEADLAMP RH	1,967.50	1 PC	1,967.50	✓
31 HEADLAMP LOWER BRACKET RH	35.00	1 PC	CR 35.00	✓
32 HEADLAMP LH	1,967.50	1 PC	1,967.50	7

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848

ATTN: Motor Claim Department

FAX: 65073849

WS Ref: OD/FC

Claim Type: Own Damage

Accident Date: 21/04/2023

Estimate No: ES2300429/YISHUN

Date: 26 Apr 2023

Policy No: D-22099561MFQC/4

Veh Reg No: SLB807L

Make/Model: HONDA HONDA VEZEL
 1.5X CVT

Chassis No: RU11109203

Engine No: L15B4029206

Reg. Date: 28/03/2016

Estimate Repair Cost to Vehicle No :SLB807L

Description	U/Price	Quantity	List Price	Amount
33 FRONT RH DOOR	898.70	1 PC	<i>R</i> 898.70 <u>SS</u>	<u>SS</u>
34 FRONT RH DOOR GLASS	632.10	1 PC	632.10	<i>7</i>
35 FRONT RH DOOR GLASS OUTER MOULDING	60.10	1 PC	60.10	<i>7</i>
36 FRONT RH DOOR GLASS REGULATOR	418.10	1 PC	<i>R</i> 418.10	<i>7</i>
37 FRONT RH DOOR GLASS CHANNEL	70.70	1 PC	<i>7</i> 70.70	<i>7</i>
38 FRONT RH DOOR SIDE MIRROR	606.60	1 PC	<i>7</i> 606.60	<i>7</i>
39 FRONT RH WINDSCREEN PILLAR	850.60	1 PC	850.60	<i>7</i>
40 FRONT WINDSCREEN GLASS MOULDING	130.80	1 SET	130.80	<i>7</i>
41 FRONT RH DOOR TOP HINGE	48.90	1 PC	<i>R</i> 48.90	<i>7</i>
42 FRONT RH DOOR BOTTOM HINGE	48.90	1 PC	<i>R</i> 48.90	<i>7</i>
43 FRONT RH DOOR CHECKER	48.60	1 PC	48.60	<i>7</i>
44 FRONT RH DOOR INNER RUBBER	96.00	1 PC	<i>7</i> 96.00	<i>7</i>
45 FRONT RH DOOR FRAME STICKER	19.00	1 SET	<i>7</i> 19.00	<i>7</i>
46 REAR RH DOOR	971.30	1 PC	<i>R</i> 971.30	<i>7</i>
47 REAR RH DOOR FRAME STICKER	19.70	1 SET	<i>7</i> 19.70	<i>7</i>
48 REAR RH DOOR INNER RUBBER	95.20	1 PC	<i>7</i> 95.20	<i>7</i>
49 REAR RH DOOR TOP HINGE	48.90	1 PC	48.90	<i>7</i>
50 REAR RH DOOR BOTTOM HINGE	48.90	1 PC	<i>R</i> 48.90	<i>7</i>
51 REAR RH DOOR CHECKER	48.60	1 PC	48.60	<i>7</i>
52 RH TAILLAMP	394.00	1 PC	<i>7</i> 394.00	<i>X</i>
53 REAR RH FENDER	931.80	1 PC	<i>R</i> 931.80	<i>7</i>
54 REAR RH FENDER WHEEL ARCH GARNISH	199.00	1 PC	<i>7</i> 199.00	<i>7</i>
55 REAR BUMPER	571.80	1 PC	<i>7</i> 571.80	<i>7</i>
56 REAR BUMPER LH SIDE PAD	172.60	1 PC	172.60	<i>7</i>
57 REAR BUMPER CLIPS	3.50	6 PCS	<i>7</i> 21.00	<i>7</i>
58 REAR LH WHEEL ARC GARNISH	187.90	1 PC	<i>7</i> 187.90	<i>7</i>
			21,303.90	
			Less 20%	4,260.78
				17,043.12
Special Net				
59 FRONT RH TYRE	180.00	1 PC	<i>7</i> 180.00	<i>30/m</i>
60 FRONT WINDSCREEN GLASS GUM	40.00	1 PC	40.00	<i>7</i>
			220.00	220.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848 FAX: 65073849
 ATTN: Motor Claim Department

WS Ref: OD/FC
 Claim Type: Own Damage
 Accident Date: 21/04/2023

Estimate No: ES2300429/YISHUN
 Date: 26 Apr 2023
 Policy No: D-22099561MFQC/4
 Veh Reg No: SLB807L
 Make/Model: HONDA HONDA VEZEL
 1.5X CVT
 Chassis No: RU11109203
 Engine No: L15B4029206
 Reg. Date: 28/03/2016

Estimate Repair Cost to Vehicle No :SLB807L

Description	U/Price	Quantity	List Price	Amount
Labour			S\$	S\$
61 TOWING				
62 REMOVE AND REFIX FRONT WINDSCREEN GLASS	50.00	1 LA	50.00	✓
63 REMOVE & REFIX DASHBOARD, METER ASSY AND CHECK WIRING	100.00	1 LA	100.00	?
	280.00	1 LA	280.00	?
64 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
65 REMOVE & REFIX FRT BUMPER ASSY,BONNET,FOG LAMPS,GRILLE,HEADLAMPS,FRT FENDERS,RADIATOR & MOTOR,CUT,WELD & RENEW FRT RH FENDER INNER PANEL,REMOVE & REFIX FRT RH & REAR RH DOOR,TRANSFER DOOS ATTACHMENT,CUT,WELD & RENEW FRT RH W/SCREEN PILLAR, TO BE CONTINUED	2,800.00	1 LA	2,800.00	2200
66 REMOVE & REFIX REAR BUMPER,KNOCK REAR END PANEL AND REALIGN THE SAME		1 LA		
67 PUTTY & RESPRAY ON FRT & REAR BUMPERS,REINFORCEMENTS,BONNET,FRT BOTH FENDERS,SUPPORT PANEL,FRT RH FENDER INNER PANEL,FRT RH W/SCREEN PILLAR,FRT & REAR RH DOORS,RH DOOR PILLAR,REAR RH FENDER	2,200.00	1 LA	2,200.00	2000
68 REMOVE & REFIX FRT UNDER CARRIAGE, UNDER CROSS MEMBER,STEERING AND DRIVE SHAFT.	360.00	1 LA	360.00	300
69 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	80.00	1 PC	80.00	60
			5,970.00	5,970.00
			Total	S\$ 23,233.12
			Add GST @ 8%	1,858.65
			Total Amount Payable	S\$ 25,091.77

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

577M

SLB807L

No

21 Apr 2023

HONDA

VEZEL 1.5X CVT

Silver

2015

L15B4029206

RU11109203

96.0 kW (128 bhp)

\$19,297.00

28 Mar 2016

28 Mar 2016

0

\$9,297.00

Yes

27 Mar 2026

\$5,578.00

27 Mar 2026

A - Car up to 1600cc & 97kW (130bhp)

10

\$55,399.00

\$16,247.00

\$21,825.00

The information contained herein is correct as at 21 Apr 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/04/2023 18:14 (SGT)
Reported by	Actual Driver
Date of Accident	21/04/2023 09:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ADMIRALTY ROAD WEST
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLB807L

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	POLLISUM ENGINEERING (PTE) LTD
Company Reg No	1XXXXX577M
Email Address	admin@pollisum.com
Mobile Phone No	(Phone) +65-67557600
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Vezel
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1500

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099561MFQC/4

DRIVER


Name of Driver	TEY GEOK ENG
NRIC No	SXXXX789I
Date Of Birth	03/01/1967
Occupation	Indoor

Describe Circumstance of the Accident

** NOTE : PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

(✓) Claim Own Policy () Claim Third party
() Claim OD/ TP at other workshop () Reporting Only

Sketch Plan



Refer to Police Report No: T/20230421/2062

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)